

Report #: 91517-MD-44
Inspect Date: 05/04/2011
Page: 1 of 10

REPORT Canadian Natural Insp. Co. Job #: 91517 Green **Criticality Designation:** Insp. Comp: Matrix_Inspection District: St Albert - South Field: Brightview 1431 Location: 14-02-046-01W5 Unit / Skid #: Inlet Bld LSD: 14-02-046-01W5 Jurisdiction #: Equip Tag #: A0244714 Serial #: FS5959 CRN #: H5308.2 Nat'l Bd #: Year Built: 1988 Equipment Description: Other: SEPARATOR Manufacturer: LARSEN D' AMICO MFG LTD Service: Sweet Status: In Service -Equip. Type: Vessel: Separator MAWP Shell: 1440 Volume: 0.48 Code Stamp:

✓ Y

✓ N MAWP Tube: Psi @ °F 108.00 Insulated: Y X N Height/Length: in. MDMT: -20 °F RT: RT-1 Size/Diameter.: 20.00 in. O.D. PWHT: ☐ Y 🖾 N Manway: ⊠Y □ N Support Saddle Vessel on Original CNRL Inventory List: ☐ Y ☐ N 1.58 Clad: No C.A.: mm Coated: Yes J.E.: N/A Remote Access:

-OD/ID Tube Side Material Nominal Thk Diameter Shell Side Component Main - Shell SA-516-70 25.000 mm 20.000 in. OD \bowtie 2 North - Head OD \boxtimes SA-516-70 22.000 mm 20.000 in. South - Head SA-516-70 22.000 mm 20.000 in. OD \boxtimes Static Data: Confirmed Changed (See Comments) Comments: Static data updated **PSV Static Data** PSV -1 Tag #: PSV244714 Serial #: 88C1802 CRN: 01832.52 Model #: 1997C11111 Capacity: 10693 Set Pressure: 1440 psi Manufacturer: Consolidated Service Company: Last Service Date: 6/21/2006 Inlet Size & Type: 1.50 in. -Outlet Size & Type: Block Valve: Carseal Intact: Code Stamp: Shell Side / Tube Side: Out for Service During Insp.: Location of PSV: PSV -2 Tag #: CRN: Serial #: Model #: Set Pressure: Capacity: Service Company: Manufacturer: Inlet Size & Type: Last Service Date: Outlet Size & Type: Block Valve: - -Carseal Intact: Code Stamp: Shell Side / Tube Side: Out for Service During Insp.: Location of PSV: PSV Comments To be removed and serviced during the 2011 TA



Report #: 91517-MD-44

Insp. Co. Job #: 91517

Inspect Date: 05/04/2011 Page: 2 of 10

Insp. Company: Ma	trıx_Ir	nspection	LSD: 14-02-046-01W5	urisdiction #:	A02	44714		
External Inspection Results – VE External Inspection Performed								
Item	N/A	Condition	Comment (Check Status Bar or Press F1 for Help)	NCR	Action Item Integrity	Action Item Maintenance		
Nameplate		Accept	secure and legible					
Foundation and Supports		Accept	acceptable condition					
Anchor Bolts		Accept	tight with no signs of deformation					
Grounding		Accept	grounded to building					
Insulation Condition	\boxtimes		coalescer does not have insulation					
PSV		Accept	vented properly					
Shell Heads & Nozzles		Accept	minor surface corrosion noted					
Metal Surfaces (Paint)		Accept	mild paint chipping and flaking					
Aux Equipment		Accept	instrumentation intact					
Cathodic Protection			no anode for inspection					
Alignment		Accept	vessel is level with building					
Flange Connections		Accept	proper studs and nuts					
Pressure Gauge		Accept	0-1500 psi					
Temperature Gauge		Accept	0-100°C					
Sight Glass		Accept	visible level and intact					
Ladder / Platform	\boxtimes		no ladders or platforms on vessel					
Leaks		No	no leaks noted at the time of inspection					
Piping from Vessel		Accept	well supported					
Previous UT Survey				UT Company	y:			
External Visual Observations		1				,		
There is mild paint deterioration through out the vessel exposing the base metal to minor surface corrosion. Minor surface corrosion also noted between the flanges and supports. The lifting lugs on the manway are bent with cracking on the painted welds. The thruwall caulking seal is deteriorated. UT corrosion survey was performed on selected areas of the shell, heads, nozzles and piping at suspect locations using GE DMS2 SN 01NOV4. All readings recorded were found to be at or above nominal thickness - corrosion allowance. Evidence of previously performed surveys was noted but no access to previous UT data was available at the time of inspection. Recommendations:								
Clean the minor surface corrosion and touch up the point. Remove the paint on the south head lifting lugs and perform MT								
			h up the point. Remove the paint on the south h lace the existing thru-wall caulking seal. Maintai					



Report #: 91517-MD-44 Inspect Date: Page:

Insp. Co. Job #:

05/04/2011 3 of 10 91517

14-02-046-01W5 A0244714 Matrix_Inspection LSD: Jurisdiction #: Insp. Company: Internal Inspection Results - VI N/A (Not Applicable) Action Item Action Item Comment NCR N/A Condition Item (Check Status Bar or Press F1 for Help) Integrity Maintenance Shell No Internal Inspection Carried Out \boxtimes Heads No Internal Inspection Carried Out П П Manway \boxtimes No Internal Inspection Carried Out **Gasket Surfaces** \boxtimes No Internal Inspection Carried Out \boxtimes Welds No Internal Inspection Carried Out П Refractory \boxtimes No Internal Inspection Carried Out П **Heating Coils** \boxtimes No Internal Inspection Carried Out Demister Pad \boxtimes No Internal Inspection Carried Out П П П \boxtimes Vane Pack No Internal Inspection Carried Out Baffles \boxtimes No Internal Inspection Carried Out Trays \boxtimes No Internal Inspection Carried Out П П П Filter \boxtimes No Internal Inspection Carried Out Internal Coating \boxtimes No Internal Inspection Carried Out Tubesheet \boxtimes No Internal Inspection Carried Out П П Tube Bundle \boxtimes No Internal Inspection Carried Out Internal Visual Observations No Internal Inspection Carried Out Recommendations: No Internal Inspection Carried Out



Report #: 91517-MD-44
Inspect Date: 05/04/2011
Page: 4 of 10

Canadi	an Na	atural		IXEI OIX		Insp. C	o. Job #:	91517	
Insp. Company: Matrix_Inspection		LSD:	14-02-04	6-01W5	Jurisdiction #: A0244714		244714		
Firetube Static Data N/A (Not Applicable)									
Diameter: Not Applica	ble		Nom	Thickness: N	ot Applicable		Bend: Not	Applicable	
Length: Not Applica	Length: Not Applicable Firetube Description: Not Applicable								
UT Report#: Not Applicable ET Report#: Not Applicable									
Firetube NDE Performed:	MT	☐ Repor	t#: Not Applica	able	RT □	Report#: Not Applicable			
renomieu.	PT	Repor	t#: Not Applica	able	Other \square	Report#: Not	Applicable		
Firetube Inspection Result	s								
				Comm	ant		Action Item	Action Item	
Item	N/A	Condition	(Che	eck Status Bar or F	Press F1 for Help)	NCR	Integrity	Maintenance	
Burner			No Firetube Ir	nspection Carr	ied Out				
Stack	\boxtimes		No Firetube Ir	nspection Carr	ied Out				
Flange (Throat)				nspection Carr					
Tube Sheet				nspection Carr					
Hot Side				nspection Carr					
Miter				nspection Carr					
Return Bend				nspection Carr					
Supports				nspection Carr					
Butt Welds				nspection Carr					
Fillet Welds			No Firetube Ir	nspection Carr	ied Out		Ш		
Firetube Visual Observation	าร								
No Firetube Inspection C	arried (Out							
·									
Recommendations:									
No Firetube Inspection C	arried (Out							



Report #: 91517-MD-44 Page:

Inspect Date: 05/04/2011 5 of 10 Insp. Co. Job #: 91517

Insp. Company:N	/latrix_Inspection	LSD: 14-02-	046-01W5	Jurisdiction #:	A0244714			
Vessel NDE and Final S	Summary:							
	UT ☐ Report#	:	ET 🗆	Report#:				
NDE Performed	l: MT 🗌 Report#		RT 🗌	Report#:				
	PT Report#		Other	Report#:				
Maxi-Trak Observations	Summary (Summarize	inspection results Max	255 Characters):					
	There is mild paint deterioration through out the vessel exposing the base metal to minor surface corrosion. Minor surface corrosion also noted between the flanges and supports. The lifting lugs on the manway are bent with cracking on the painted welds.							
Maxi-Trak Recommenda	tions Summary (Summ	arize Recommendatio	ns Max 255 Charact	ers):				
	e corrosion and touch ເ t scheduled TA. Replac			h head lifting lugs and	perform MT			
Actions Corrected at Tin	ne of Inspection: (If action	ns were corrected at the time	of Inspection – note the	corrected actions here.)				
no actions to correct at	the time of inspection							
Additional Visual Observ	ations							
No additional visual ob	servations made at the	time of inspection						
Any other safety concern	s or observations from	associated equipment	: (for example asso	ciated piping, buildings	. pumps etc)			
Any other safety concerns or observations from associated equipment: (for example associated piping, buildings, pumps etc) the south door stairs were removed during the 2011 TA.								
	oro romovou dumig und							



Report #: Inspect Date: Page:

Insp. Co. Job #:

91517-MD-44 05/04/2011 6 of 10 91517

Insp. Company: Matrix_Inspection LSD: 14-02-046-01W5 Jurisdiction #: A0244714

Thickness and Remaining Life Evaluation

" Must be Completed"

MUST BE COMPLETED AND RESOLVED WITH CNRL IMMEDIATELY UPON DISCOVERY OF LOW WALL THICKNESS AREAS

Step 1: Was any thickness measurement location found to be less than (Nominal WT - Corrosion Allowance)?: No

If YES, proceed to Step 2; if NO, proceed to "Crack Evaluation" and "CNRL Criticality Designation".

Step 2: Which component(s) were found below (Nominal WT - Corrosion Allowance)?

Components found below Nom - CA:

Components					
N/A - N/A					
N/A - N/A					
N/A - N/A					
N/A - N/A					
N/A - N/A					

Perform Steps 3 – 8 for each component with actual thickness less than (Nominal WT – Corrosion Allowance).

Step 3: Describe Location and Extent of Corrosion:

Components

Location and Extent of Corrosion

N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection

Notes:

Not Applicable for this Inspection

Step 4:

- For shells and nozzles, calculate minimum required thickness (T-min) as per ASME Section VIII UG-27.
- For heads, calculate minimum required thickness (T-min) as per ASME Section VIII UG-32.

Components	T-Min
N/A - N/A	N/A



Report #: Inspect Date: Page:

Insp. Co. Job #:

91517-MD-44 05/04/2011 7 of 10 91517

Insp. Company: Matrix_Inspection LSD: 14-02-046-01W5 Jurisdiction #: A0244714

Thickness and Remaining Life Evaluation (Continued)

Step 5: Is any measured thickness less than calculated minimum required thickness (T-min)? N/A

If YES, complete Step 6
If NO, proceed to Step 7..

Step 6: Is nature and extent of pitting acceptable as per API 510? N/A

Step 7: Calculate Remaining Life as per API 510. How? (Find last reading; use nominal thickness if nothing available). Short Term Corrosion Rates and Long Term Corrosion Rates.

Components	Remaining Life (Yrs)
N/A - N/A	N/A

Step 8: Contact CNRL Integrity Coordinator to discuss above results.

- Name of CNRL contact: Not Applicable for this Inspection
- Date and time of conversation: Not Applicable for this Inspection

Summary/results of conversation:

Not Applicable for this Inspection

Crack Evaluation by Magnetic Particle or Alternative Inspection "Must be Completed"

MUST BE COMPLETED AND RESOLVED WITH CNRL IMMEDIATELY UPON DISCOVERY OF CRACK-LIKE INDICATIONS

Were any indications found to suggest the vessel contained cracks? N/A

If NO, proceed to "CNRL Criticality Designation".

If YES, Contact CNRL Integrity Coordinator to discuss results.

- Name of CNRL contact: Not Applicable for this Inspection
- Date and time of conversation: Not Applicable for this Inspection

Summary/results of conversation:

Not Applicable for this Inspection



91517-MD-44 Report #: 05/04/2011 Inspect Date: Page: 8 of 10

Insp. Co. Job #: 91517

Matrix_Inspection 14-02-046-01W5 A0244714 Insp. Company: LSD: Jurisdiction #:

CNRL Criticality Evaluation – "MUST BE COMPLETED"

The CNRL In-Service Pressure Vessel Inspector MUST answer all the following questions

- Is the vessel fit-for-service? : Yes 1.
- 2. Was the measured thickness less than the calculated minimum required thickness (T-min) for any component?: **No**
- Were MT indications found?: **N/A** 3.
- Was the remaining life less than 6 years for sour service vessels or less than 10 years for sweet service vessels?: No 4.
- Were NCR's or Action Items generated as a result of the inspection? : **No** 5.
- Were UT readings below (Nominal WT Corrosion Allowance) found? : **No**

Information on CNRL Owner User Program - Criticality Designation and Required Review

RED – Vessel Inspection Results are deemed RED if one of the following occurred:

- The measured thickness was less than the calculated minimum required thickness (T-min) for any component.
- MT indications were found.
- The remaining life was calculated to be less than 6 years for sour-service vessels or less than 10 years for sweet-service vessels.

RED inspection reports must be signed off by the CNRL Chief Inspector.

YELLOW - Vessel Inspection Results are deemed YELLOW if one or more of the following occurred:

- The vessel was declared NOT fit-for-service by the 3rd Party In-Service PV Inspector.
- NCR's or Action Items were generated as a result of the inspection.
- UT readings below (Nominal WT Corrosion Allowance) were found.

YELLOW inspection reports must be signed off by the CNRL Pressure Equipment Integrity Coordinator.

GREEN - Vessel Inspection Results are deemed GREEN if all of the following are true:

- The vessel was declared fit-for-service by the 3rd Party In-Service PV Inspector.
- UT readings below (Nominal WT Corrosion Allowance) were NOT found.
- MT indications were NOT found.
- NCR's or Action Items were NOT generated as a result of the VE inspection.

GREEN inspection reports must be signed off by the 3rd Party In-Service Pressure Vessel Inspector.

Criticality Designation							Green	
Vehicle #:	380 Kms:		I	nspector (Name):	Matthew	BDickinson	PESL:	
Time In:	00:00 Time Out:	00:00 Hrs	s	nspector (Signature	e):		API:	39483
Time In:	00:00 Time Out:	00:00 Hrs	(C	CNRL Coordinato	r (Name):		-	
Personnel:				CNRL Coordinator	r (Signature):			_
Billing Info:	:			ONRL Chief Inspe	ector (Signature		reement with re	port contents)
						(I am in full ag	reement with re	port contents)



Report #: 91517-MD-44 Inspect Date: 05/04/2011 Page: Insp. Co. Job #:

9 of 10 91517

Equipment Photographs:





01 nameplate





04 lugs are bent

02 overview

03 outside overview



Report #: Inspect Date: Page:

Insp. Co. Job #:

91517-MD-44 05/04/2011 10 of 10 91517





05 paint deterioration with surface scale

06 corrosion between flanges