

Report #: 91590-MD-05
Inspect Date: 06/29/2011
Page: 1 of 10
Insp. Co. Job #: 91590

Criticality Designation:						Green		
Insp. Comp: Matrix_Insp	ection	District:	St Albert	- South		Field	d: Morr	in 1327
Location: 11-16-031-		Jnit / Skid #:	Group Ir	nlet Bld	-	LSE	D: 11-16-0	)31-20W4
Jurisdiction #: A04317	56 E	quip Tag #:			-	Serial #	#: 96-8	3771-1
CRN #: M2318.	21	Nat'l Bd #:			Ye	ear Buil	t:1	997
Manufacturer: WELLS-HALL F	FABRICATION	LTD E	quipment Des	scription: O	ther: INLET SE	PARAT	OR	
Status: In Service -		Equ	iip. Type: Ves	sel: Separa	tor	<u> </u>	Service:	Sweet
MAWP Shell: 720 Psi	@ 100	°F	Volume:			_ (	Code Stamp:	$\boxtimes$ Y $\square$ N
MAWP Tube: Psi	@		ght/Length:	114.17	in.	_	Insulated:	$\square$ Y $\square$ N
MDMT: -20 °F	RT: RT-1			36.00 in.		<u> </u>	PWHT:	⊠Y □N
Support Skirt		•	inal CNRL Inv	•			Manway:	☐ Y ⊠ N
C.A.: in.	Coated: Y	es (	Clad: No	J.E.:	N/A Remo	ote Acc	ess: 🗌	
Component	Ma	terial	Nomina	al Thk	Diameter (	OD/ID	Tube Side	Shell Side
1 Main - Shell			0.875	in. 3	36.000 in.	OD		$\boxtimes$
2 - Head			0.960	) in. (	36.000 in.	OD		$\boxtimes$
3 - Head			0.960	) in. 3	36.000 in.	OD		$\boxtimes$
4 -								
5 -								
Static Data: Confirmed	Changed (See	Comments	s) 🖂					
Comments:								
PSV Static Data								
PSV –1 Tag #: PSV43175	6	Sorial #:	CE-3914-KD	<u> </u>		·DNI· O	G254.5C	
Model #: 2741U	0	_	5609 SCFM		Set Press			
Manufacturer: Farris		_ Oupdoity.	3003 001 10	<u> </u>	Service Comp		•	
Inlet Size & Type: 2.00 i	n - Threaded	<del></del>			Last Service D			
Outlet Size & Type: 2.00 i		=		Bloc	k Valve: N/A -	- -	00/2000	
Carseal Intact: Yes	iii iiii daada	_		5.00	Code Sta	amp: Y	es	
Shell Side / Tube Side: Sl	hell Side	Out for S	Service During	Insp.: N	Location of F			
		=		<u> </u>	=	-		
PSV –2 Tag #:		Serial #:	-		Cat Drass			
Model #: Manufacturer:		_ Capacity:			Set Press Service Comp			
Inlet Size & Type:								
Outlet Size & Type:		=		Bloc	Last Service Dk Valve: -	_		
Carseal Intact:		_		Dioc	Code Sta			
Shell Side / Tube Side:		Out for S	Service During	Insn ·	Location of F	· · ·		
PSV Comments								
Proper venting and set pressur	c							



Report #: 91590-MD-05
Inspect Date: 06/29/2011
Page: 2 of 10
Insp. Co. Job #: 91590

Insp. Company: Matrix_Inspection LSD: 11-16-031-20W4 Jurisdiction #: A0431756								
I	External Inspection Results	– VE	External In	spection Performed				
	Item	N/A	Condition	Comment (Check Status Bar or Press F1 for Help)	NCR	Action Item Integrity	Action Item Maintenance	
	Nameplate		Accept	sure and legible				
	Foundation and Supports		Accept	skid foundation with skirt support				
	Anchor Bolts		Accept	no evidence of damage				
	Grounding		Accept	grounded by skid				
	Insulation Condition	$\boxtimes$		vessel is not insulated				
	PSV		Accept	proper venting and set pressure				
	Shell Heads & Nozzles		Accept	condensation noted during inspection				
	Metal Surfaces (Paint)		Accept	well adhered with a scratch				
	Aux Equipment		Accept	adequately supported				
	Cathodic Protection	$\boxtimes$		no anodes for inspection				
	Alignment		Accept	level with skid				
	Flange Connections		Accept	correct bolting and thread engagement				
	Pressure Gauge		Accept	0 - 1000 pi				
	Temperature Gauge		Accept	-40-160 °F				
	Sight Glass		Accept	clean and intact				
	Ladder / Platform	$\boxtimes$		no ladders or platforms				
	Leaks		No	evidences of previous leaks noted				
	Piping from Vessel		Accept	secure and well supported				
	Previous UT Survey	$\boxtimes$	No	N/A	UT Company	y: N/A		
Е	External Visual Observations							
	The overall condition of the separator is good. It should be noted that the separator was not in use during the inspection; the sight glass was empty and pressure was 0.							
	There is evidence of previs	sions	leaks noted	at the flange connections to the sight glass pip	ing.			
	Condensation was observe	ed on	the inside b	ouilding portion of separator at the time of inspe	ction.			
	There in minor corrosion in	the	tell-tale hole	es of the reinforcement pads on the vessel.				
	A UT corrosion Survey was	s per	formed using	g a DMS 2 with no significant wall lose noted at	the time of ir	spection		
				<ul> <li>7' from grade) extending upwards ~ 19". the denote the prior of the denoted are the denoted ar</li></ul>		mensurable d	ue to how tight	
F	Recommendations:							
	Buff off paint to perform MT examination to determine if any indication has propagated into the shell, or perform shear wave ultrasonic examination to determine if there is any depth to this suspect area.							
	Maintain regulatory inspec	tion t	o ensure saf	fe operation and continued use.				



Report #: **91590-MD-05**Inspect Date: 06/29/2011
Page: 3 of 10

Page: 3 of 10 Insp. Co. Job #: 91590

Insp. Company:Ma	atrix_In	spection	LSD:	11-16-031-20W4	Jurisdiction	#:A0	431756	
Internal Inspection Results	s – VI I	V/A (Not Ap						
			,	Comment		Action Item	Action Item	
Item	N/A	Condition	(Che	eck Status Bar or Press F1 for Help)	NC	R Integrity	Maintenance	
Shell			No Internal In	spection Carried Out				
Heads	$\boxtimes$		No Internal In	spection Carried Out				
Manway			No Internal In	spection Carried Out				
Gasket Surfaces				spection Carried Out				
Welds				spection Carried Out				
Refractory				spection Carried Out				
Heating Coils				spection Carried Out				
Demister Pad				spection Carried Out				
Vane Pack				spection Carried Out				
Baffles				spection Carried Out				
Trays				spection Carried Out				
Filter				spection Carried Out				
Internal Coating				spection Carried Out				
Tubesheet				spection Carried Out				
Tube Bundle	$\boxtimes$		No Internal In	spection Carried Out				
Internal Visual Observation	s							
No Internal Inspection Ca	arried C	Jul						
Recommendations:								
	arriad (	\t						
No Internal Inspection Ca	ameu (	Jul						



Report #: 91590-MD-05
Inspect Date: 06/29/2011
Page: 4 of 10
Insp. Co. Job #: 91590

Insp. Company: Mat	rix_In	spection	LSD:	11-16-0	)31-20W4		Jurisdiction #:	A04	31756	
Firetube Static Data N/A (Not Applicable)										
Diameter: Not Applicable Nom Thickness: Not Applicable Bend: Not Applicable										
Length: Not Applicab				-	Not Applicat			Bena. 140t	Тррпсаыс	
Longin. Not Applicab	UT	□ Penor	t#: Not Applica	-			Report#: Not	Applicable		
Firetube NDE		· ·								
Performed:		-	t#: Not Applica		_ RT		Report#: Not			
	PT	Repor	t#: Not Applica	able	Other	Ш	Report#: Not	Applicable		
Firetube Inspection Results	Firetube Inspection Results									
Item	N/A	Condition			ment		NCR	Action Item	Action Item	
		Condition			or Press F1 for H	lelp)		Integrity	Maintenance	;
Burner			No Firetube Ir							
Stack			No Firetube Ir						<u> <u> </u></u>	
Flange (Throat)			No Firetube Ir							
Tube Sheet			No Firetube Ir					<u> </u>		
Hot Side			No Firetube Ir				<u> </u>	<u> </u>	<u> </u>	
Miter			No Firetube Ir	•				<u> </u>	<u> </u>	
Return Bend			No Firetube Ir	•			<u> </u>	<u> </u>	<u> </u>	
Supports			No Firetube Ir				<u> </u>	<u> </u>	<u> </u>	
Butt Welds			No Firetube Ir					<u> </u>	<u> </u>	
Fillet Welds			No Firetube Ir	ispection Ca	arried Out					
Firetube Visual Observations	3									
No Firetube Inspection Ca	rried	Out								
Recommendations:										
No Firetube Inspection Ca	rried	Out	-					-		
•										



Report #: 91590-MD-05 Inspect Date: Page:

Insp. Co. Job #:

06/29/2011 5 of 10 91590

Insp. Company:	Matrix_In	spect	ion	LSD:	11-16-031	-20W4		Jurisdiction #:	A0431756
Vessel NDE and Final	Summar	y:							
	UT		Report#:			ET	· 🗆	Report#:	
NDE Performe			Report#:			RT		Report#:	
	PT		Report#:			Othe		Report#:	
Maxi-Trak Observations	s Summar	y (Su	mmarize ir	nspection res	sults Max 25	5 Characte	ers):		
There is a scratch on it is.	the shell	(north	side ~ 7' 1	from grade)	extending up	owards ~ 19	9". the	depth was not me	ensurable due to how tight
Maxi-Trak Recommend	lations Su	mmar	y (Summa	rize Recomr	mendations I	Max 255 CI	naract	ers):	
Buff off paint to perfo ultrasonic examinatio	rm MT exa n to deter	amina mine i	tion to det if there is a	ermine if any any depth to	y indication h this suspect	nas propaga area	ated ir	nto the shell, or pe	rform shear wave
Actions Corrected at T	ime of Ins	pectio	on: (If actions	s were corrected	d at the time of I	nspection – no	ote the o	corrected actions here.)	
None									
Additional Visual Obser	vations								
None									
Any other safety conce	rns or obs	ervati	ons from a	associated e	quipment: (f	or example	asso	ciated piping, build	dings, pumps etc)
None						· ·			



Report #: Inspect Date: Page:

Insp. Co. Job #:

91590-MD-05 06/29/2011 6 of 10 91590

Insp. Company: Matrix\_Inspection LSD: 11-16-031-20W4 Jurisdiction #: A0431756

#### Thickness and Remaining Life Evaluation

### " Must be Completed"

### MUST BE COMPLETED AND RESOLVED WITH CNRL IMMEDIATELY UPON DISCOVERY OF LOW WALL THICKNESS AREAS

Step 1: Was any thickness measurement location found to be less than (Nominal WT - Corrosion Allowance)?: No

If YES, proceed to Step 2; if NO, proceed to "Crack Evaluation" and "CNRL Criticality Designation".

Step 2: Which component(s) were found below (Nominal WT - Corrosion Allowance)?

Components found below Nom - CA:

Components					
N/A - N/A					
N/A - N/A					
N/A - N/A					
N/A - N/A					
N/A - N/A					

Perform Steps 3 – 8 for each component with actual thickness less than (Nominal WT – Corrosion Allowance).

Step 3: Describe Location and Extent of Corrosion:

Components

**Location and Extent of Corrosion** 

N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection

#### Notes:

Not Applicable for this Inspection

#### Step 4:

- For shells and nozzles, calculate minimum required thickness (T-min) as per ASME Section VIII UG-27.
- For heads, calculate minimum required thickness (T-min) as per ASME Section VIII UG-32.

11115	Compo
Ά	N/A -
'A	N/A -
'A 'A 'A 'A	N/A - N/A - N/A -



Report #: Inspect Date: Page: 91590-MD-05 06/29/2011 7 of 10

91590

Insp. Co. Job #:

11-16-031-20W4 A0431756 Matrix\_Inspection Insp. Company: LSD: Jurisdiction #:

#### Thickness and Remaining Life Evaluation (Continued)

Step 5: Is any measured thickness less than calculated minimum required thickness (T-min)? N/A

If YES, complete Step 6 If NO, proceed to Step 7..

Step 6: Is nature and extent of pitting acceptable as per API 510? N/A

Step 7: Calculate Remaining Life as per API 510. How? (Find last reading; use nominal thickness if nothing available). Short Term Corrosion Rates and Long Term Corrosion Rates.

Components	Remaining Life (Yrs)
N/A - N/A	N/A

Step 8: Contact CNRL Integrity Coordinator to discuss above results.

- Name of CNRL contact: Not Applicable for this Inspection
- Date and time of conversation: Not Applicable for this Inspection

Summary/results of conversation: Not Applicable for this Inspection

#### " Must be Completed" Crack Evaluation by Magnetic Particle or Alternative Inspection

#### MUST BE COMPLETED AND RESOLVED WITH CNRL IMMEDIATELY UPON DISCOVERY OF CRACK-LIKE INDICATIONS

Were any indications found to suggest the vessel contained cracks? **N/A** 

If NO, proceed to "CNRL Criticality Designation".

If YES, Contact CNRL Integrity Coordinator to discuss results.

- Name of CNRL contact: Not Applicable for this Inspection
- Date and time of conversation: Not Applicable for this Inspection

Summary/results of conversation:

Not Applicable for this Inspection



91590-MD-05 Report #: 06/29/2011 Inspect Date: Page:

8 of 10 Insp. Co. Job #: 91590

A0431756 Matrix\_Inspection 11-16-031-20W4 Insp. Company: LSD: Jurisdiction #:

### CNRL Criticality Evaluation – "MUST BE COMPLETED"

The CNRL In-Service Pressure Vessel Inspector MUST answer all the following questions

- Is the vessel fit-for-service? : Yes 1.
- 2. Was the measured thickness less than the calculated minimum required thickness (T-min) for any component?: **No**
- Were MT indications found?: N/A 3.
- Was the remaining life less than 6 years for sour service vessels or less than 10 years for sweet service vessels?: **No** 4.
- Were NCR's or Action Items generated as a result of the inspection? : **No** 5.
- Were UT readings below (Nominal WT Corrosion Allowance) found? : **No**

#### Information on CNRL Owner User Program - Criticality Designation and Required Review

**RED** – Vessel Inspection Results are deemed RED if one of the following occurred:

- The measured thickness was less than the calculated minimum required thickness (T-min) for any component.
- MT indications were found.
- The remaining life was calculated to be less than 6 years for sour-service vessels or less than 10 years for sweet-service vessels.

RED inspection reports must be signed off by the CNRL Chief Inspector.

YELLOW - Vessel Inspection Results are deemed YELLOW if one or more of the following occurred:

- The vessel was declared NOT fit-for-service by the 3<sup>rd</sup> Party In-Service PV Inspector.
- NCR's or Action Items were generated as a result of the inspection.
- UT readings below (Nominal WT Corrosion Allowance) were found.

YELLOW inspection reports must be signed off by the CNRL Pressure Equipment Integrity Coordinator.

GREEN - Vessel Inspection Results are deemed GREEN if all of the following are true:

- The vessel was declared fit-for-service by the 3<sup>rd</sup> Party In-Service PV Inspector.
- UT readings below (Nominal WT Corrosion Allowance) were NOT found.
- MT indications were NOT found.
- NCR's or Action Items were NOT generated as a result of the VE inspection.

GREEN inspection reports must be signed off by the 3rd Party In-Service Pressure Vessel Inspector.


Critica	lity Designation						Green	
Vehicle #:	Kms:		ı	nspector (Name):	Matthew	B Dickinson	PESL:	
Time In:	00:00 Time Out:	00:00 Hrs	s	nspector (Signature	e):		API:	39483
Time In:	00:00 Time Out:	00:00 Hrs	(	CNRL Coordinator	r (Name):		-	
Personnel:				CNRL Coordinator	r (Signature):			
Billing Info:	:			CNRL Chief Inspe	ctor (Signature		reement with re	port contents)
						(I am in full ag	reement with re	port contents)



Report #: 91
Inspect Date: 0
Page:
Insp. Co. Job #:

91590-MD-05 06/29/2011 9 of 10 91590

#### **Equipment Photographs:**





01 nameplate 02 overview





02.1 outside overview

03 previous process leak



Report #: 91590-MD-05 Inspect Date: Page: Insp. Co. Job #:

06/29/2011 10 of 10 91590





#### 04 gouge like scratch

#### 05 PSV overview





06 condensation on tank

Pic 043