


Report #:	1377	98-BV-12	IRISI	NDT Job #:	-	137798	Date:	APRIL 07, 2009	Page	1	of	1	
Client:	CNRL		-	PO/Job #:	1020	0011.5430.1	15-G816	Contact:	KEIT	H MCIN	TOSH		
Job location:	ETZIKOM COMPRESSOR STATION, MEDICINE HAT WEST, A						В	Tel:	780-9	91-764	4		
	LSD: 0	8-24-006-10	W4M					Fax:					
Procedure(s):	UT TH	ICKNESS											
Code(s):	Code(s): ASME SECT VIII												
Item Inspected:	Inlet se	eparator A04	196494				Material:	Carbon St	teel				
Method:	Method: Contact IImmersion Other:						Surface Temp (C): $\square < 5^{\circ} \square > 5^{\circ} / < 60^{\circ} \square > 60^{\circ}$						
Type:	□ P/E	□ T/T □ I	Jual 🗌 I	Automated	TOFI	5	Scanning Su	rface: 🛛 🖓 🤇	DD 🛛 I	D 🗌 (Other:		
Application: 🛛 Laminar 🗋 Shear Wave 🗋 Volumetric 🖾 Thickness Surface Condition: Good													
Instrumentation	1: Manu	facturer: Ki	rautkran	mer	Type:	DMS-2		Instrument	Ser. #:	31530			
Calibration:	Date:	Feb 03, 200)9	Reference F	law Size:			IRISNDT #: 31530					
Calibration Blo	ck(s):	Type: Step	Wedge	- I IRISM	NDT #:	125214	Type:		-	IRISNE)T #:		
		Type:		IRISN	NDT #:		Type:			IRISNE)T #:		
Couplant: Bra	and: Ec	hogel	Type:	971		Cable:	Type:	Coaxial		Lei	ngth:	36''	
		PROBE				S	ETTINGS - dB	3	RAM	NGE - 🗌	INCHES	. ММ	
Manufacturer	Туре	Serial #	Angle	Frequency	Size	Reference Level	Scanning Level	Transfer Value	Screen Size	Skip	Value	Beam Travel	
Krautkramer	Dual	01F988	0	8.0 MHz	0.250	55dB	+6 dB						
		ļ	<u> </u>		 							 	
			<u> </u>		<u> </u>							L	
INSPECTION DETAILS													
Scope: Carry out UT examination of Inlet separator A0496494. Check for corrosion of the shell, heads and elbows to verify the integrity for service and identify any areas of concern. Examination revealed the following:													
Results: UT examination was carried out; all readings taken were 10"band scans with 3 readings per band/location.													
Mini	Minimum, maximum and average scans were taken in each location and recorded.												
All r	All readings were found to be above nominal on the shell, heads and elbows.												
No areas of concern were found at time of inspection.													
Recommendations: Carry out visual external inspection at the next opportunity and also continue to carry out UT Corrosion survey at the required frequency. See attached drawing, pictures and UTM file for locations and thicknesses recorded.													
Final Comment:													
Inlet separator A0496494 was found to be in good shape. Assistant: ADELE GEMMELL Te						Techniciar	n: BLAIR V	VERGE					
ASSISTANT ADELE GENINELL CGSB SNT UT Level: I II III No.#:						\boxtimes CGSB \square SNT UT Level: \boxtimes I \square II \square III No.#: 5586							
Unit: 393 Km: Travel Time:						Signature:							
Start: Stop: Work hrs:													
OT Meal Subsistence required Total hrs: Client Name:													
Consumables:						Signat							



A0496494 UT Readings Readings in inches

LOC 5	1.275	1.317	1.280
LOC 10	1.284	I.285	1.284
LOC 15	1.285	I.285	1.285
LOC 20	1.281	1.282	1.281
LOC 25	1.277	1.301	1.290
LOC 30	0.227	0.230	0.229
LOC 35	0.580	0.592	0.588
LOC 40	0.355	0.369	0.360
LOC 45	0.615	0.620	0.617
LOC 50	0.346	0.359	0.356
LOC 55	0.313	0.325	0.315
LOC 60	0.355	0.364	0.361
LOC 65	1.288	1.293	1.288