



**PRESSURE VESSEL
VISUAL INSPECTION
REPORT**

Report #: **91609-KS-01**
Inspect Date: 07/22/2011
Page: 1 of 13
Insp. Co. Job #: 91609

Criticality Designation:

Green

Insp. Comp: Matrix Inspection District: St Albert - South Field: Duhamel
Location: 03-32-045-21W4 Unit / Skid #: Plant LSD: 03-32-045-21W4
Jurisdiction #: A0102602 Equip Tag #: _____ Serial #: L10124
CRN #: B1788.2 Nat'l Bd #: 6489 Year Built: 1974
Manufacturer: CE NATCO Equipment Description: Other: TREATER
Status: In Service - Equip. Type: Vessel: Treater Service: Sour
MAWP Shell: 75 Psi @ 200 °F Volume: _____ Code Stamp: ☒ Y ☐ N
MAWP Tube: _____ Psi @ _____ °F Height/Length: 360 in. Insulated: ☒ Y ☐ N
MDMT: _____ RT: _____ Size/Diameter.: 120 in. PWHT: ☐ Y ☒ N
Support Saddle Vessel on Original CNRL Inventory List: ☒ Y ☐ N Manway: ☒ Y ☐ N
C.A.: 0.062 in. Coated: Yes Clad: No J.E.: N/A Remote Access: ☐ - _____

Component	Material	Nominal Thk	Diameter	OD/ID	Tube Side	Shell Side
1 Main - Shell	SA285 C	0.500 in.	120.000 in.	OD	<input type="checkbox"/>	<input type="checkbox"/>
2 East - Head	SA516 70	0.500 in.	120.000 in.	OD	<input type="checkbox"/>	<input type="checkbox"/>
3 West - Head	SA516 70	0.500 in.	120.000 in.	OD	<input type="checkbox"/>	<input type="checkbox"/>
4 -					<input type="checkbox"/>	<input type="checkbox"/>
5 -					<input type="checkbox"/>	<input type="checkbox"/>

Static Data: Confirmed ☐ Changed (See Comments) ☒

Comments:

More data added to the vessel static data section of the report. Nameplate is secure and provides adequate information.

PSV Static Data

PSV -1 Tag #: _____ Serial #: _____ CRN: _____
Model #: _____ Capacity: _____ Set Pressure: psi
Manufacturer: _____ Service Company: _____
Inlet Size & Type: _____ in. - Last Service Date: _____
Outlet Size & Type: _____ in. - Block Valve: _____ - -
Carseal Intact: _____ Code Stamp: _____
Shell Side / Tube Side: _____ Out for Service During Insp.: _____ Location of PSV: _____

PSV -2 Tag #: _____ Serial #: _____ CRN: _____
Model #: _____ Capacity: _____ Set Pressure: _____
Manufacturer: _____ Service Company: _____
Inlet Size & Type: _____ - Last Service Date: _____
Outlet Size & Type: _____ - Block Valve: _____ - -
Carseal Intact: _____ Code Stamp: _____
Shell Side / Tube Side: _____ Out for Service During Insp.: _____ Location of PSV: _____

PSV Comments

PSV was removed for service at the time of inspection.
Ensure PSV is properly rated and plumbed for the intended service.



**PRESSURE VESSEL
VISUAL INSPECTION
REPORT**

Report #: **91609-KS-01**
Inspect Date: 07/22/2011
Page: 2 of 13
Insp. Co. Job #: 91609

Insp. Company: Matrix Inspection LSD: 03-32-045-21W4 Jurisdiction #: A0102602

External Inspection Results – VE

Item	N/A	Condition	Comment (Check Status Bar or Press F1 for Help)	NCR	Action Item Integrity	Action Item Maintenance
Nameplate	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Foundation and Supports	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Anchor Bolts	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Grounding	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Insulation Condition	<input type="checkbox"/>	Accept	Minor insulation damage at isolated areas.	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PSV	<input type="checkbox"/>	Accept	PSV removed for servicing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Shell Heads & Nozzles	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Metal Surfaces (Paint)	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Aux Equipment	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cathodic Protection	<input checked="" type="checkbox"/>		N/A	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Alignment	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Flange Connections	<input type="checkbox"/>	Accept	Attached piping removed to isolate the vessel	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Pressure Gauge	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Temperature Gauge	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sight Glass	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Ladder / Platform	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Leaks	<input type="checkbox"/>	No	No evidence of previous process leaks	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Piping from Vessel	<input type="checkbox"/>	Accept	Piping in good condition			
Previous UT Survey	<input checked="" type="checkbox"/>			UT Company:		

External Visual Observations

External inspection was carried out on the vessel. Vessel was off-stream during the plant shut-down to perform a routine inspection and necessary repairs required. The vessel nameplate is secure and readable but provides limited information. The vessel is partially insulated. Part of the vessel is inside the building. Inside section of vessel is painted. Overall condition of the insulated part of the vessel is in good condition with minor damage noted on the south side. All attached instrumentation was found in good physical and working condition. All external painted surfaces show minor paint deterioration and a light general corrosion. All gasket surfaces are free of damage and no evidence of corrosion or pitting observed.

External and internal UT thickness testing results showed no concerns. UT thickness was carried out as accessible due to having limited access because of vessel is partially insulated. Ultrasonic thickness performed with DMS-2 IRIS# 31089. Based on external observations and UT thickness results recorded the vessel was found in good operable condition.

Recommendations:

Ensure PSV is properly rated and plumbed for the intended service.
Attach all required instrumentation and piping disconnected to isolate the vessel.
Continue with regular external visual and ultrasonic thickness survey to maintain the integrity of the vessel.



PRESSURE VESSEL VISUAL INSPECTION REPORT

Report #: **91609-KS-01**
 Inspect Date: 07/22/2011
 Page: 3 of 13
 Insp. Co. Job #: 91609

Insp. Company: Matrix Inspection LSD: 03-32-045-21W4 Jurisdiction #: A0102602

Internal Inspection Results – VI Internal Inspection Performed

Item	N/A	Condition	Comment (Check Status Bar or Press F1 for Help)	NCR	Action Item Integrity	Action Item Maintenance
Shell	<input type="checkbox"/>	Accept	General corrosion and general shallow pitting	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Heads	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Manway	<input type="checkbox"/>	Accept	Shell MW corrosion noted, epoxy repaire done	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gasket Surfaces	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Welds	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Refractory	<input checked="" type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Heating Coils	<input checked="" type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Demister Pad	<input checked="" type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Vane Pack	<input checked="" type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Baffles	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Trays	<input checked="" type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Filter	<input checked="" type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Internal Coating	<input type="checkbox"/>	Accept	East side coated -Minor epoxy repairs done	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Tubesheet	<input checked="" type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Tube Bundle	<input checked="" type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Internal Visual Observations

Internal inspection carried out on the vessel. Internal anodes and vessel firetube was replaced with new. Firetube support frame was noted holed out at some areas but still intact and in acceptable condition to support the firetube. Internal shell at the bottom showed gernal corrosion and shallow piting approx. to a depth of 0.015". Firetube manways external edge and bottom had some epoxy damage and was repaired but no active corrosion noted. Internal instrumentation was found intact and in good condition. Internal ultrasonic thickness inspection was carried out on the shell and west head of the vessel as accessible. All UT thickness readings recorded showed no significant wall loss. All five anode nozzles were found having some epoxy damage. UT thickness scan was carried out on all nozzles and readings were near or above the acceptable range. Shell MW 18" Sch 40 was found corroded at the bottom but remaining thickness was found to be above the T-Min. East side internal of the vessel is coated. Overall condition of the shell and east head, all nozzles and welds were acceptable. Minor epoxy damage was noted on the shell to deflector boxes supports contact points. All epoxy coating damaged areas were repaired. A redundant electric grid inside the east side of vessel was removed.

Overall internal condition of the vessel was found in acceptable condition for future service.

Recommendations:

Continue to monitor the condition with UT thickness of shell, shell manway, all 4" anode nozzles at regular inspection intervals. Continue to perform internal visual and UT thickness to maintain its integrity.



PRESSURE VESSEL
VISUAL INSPECTION
REPORT

Report #: **91609-KS-01**
Inspect Date: 07/22/2011
Page: 4 of 13
Insp. Co. Job #: 91609

Insp. Company: Matrix Inspection LSD: 03-32-045-21W4 Jurisdiction #: A0102602

Firetube Static Data Firetube Inspection Performed

Diameter: 12 in. Nom Thickness: 0.500 in. Bend: U-Tube
Length: _____ Firetube Description: Single U-Tube
Firetube NDE Performed: UT ☐ Report#: _____ ET ☐ Report#: _____
MT ☐ Report#: _____ RT ☐ Report#: _____
PT ☐ Report#: _____ Other ☐ Report#: _____

Firetube Inspection Results

Item	N/A	Condition	Comment (Check Status Bar or Press F1 for Help)	NCR	Action Item Integrity	Action Item Maintenance
Burner	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Stack	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Flange (Throat)	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Tube Sheet	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Hot Side	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Miter	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Return Bend	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Supports	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Butt Welds	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fillet Welds	<input type="checkbox"/>	Accept		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Firetube Visual Observations

New firetube installed at the time of inspection.

Recommendations:



PRESSURE VESSEL
VISUAL INSPECTION
REPORT

Report #: **91609-KS-01**
Inspect Date: 07/22/2011
Page: 5 of 13
Insp. Co. Job #: 91609

Insp. Company: Matrix Inspection LSD: 03-32-045-21W4 Jurisdiction #: A0102602

Vessel NDE and Final Summary:

NDE Performed: UT ☒ Report#: _____ ET ☐ Report#: _____
MT ☐ Report#: _____ RT ☐ Report#: _____
PT ☐ Report#: _____ Other ☐ Report#: _____

Maxi-Trak Observations Summary (Summarize inspection results Max 255 Characters):

Internal shell general pitting to 0.015", Shell MW corroded Min reading 0.220" still above T-Min, all anodes to be replaced, east side shell epoxy damage. Fire tube replaced as per operations decision.

Maxi-Trak Recommendations Summary (Summarize Recommendations Max 255 Characters):

Replace all anodes, Intstall serviced PSV, monitor corrosion on shell, nozzles and perform regular external visual and UT survey.

Actions Corrected at Time of Inspection: (If actions were corrected at the time of Inspection – note the corrected actions here.)

Anodes replaced, epoxy damage rapired, firetube replaced and some instrumentation and external piping replaced.

Additional Visual Observations

Site is overall in very good condition. Operators take great care to keep tidy and clean.

Any other safety concerns or observations from associated equipment: (for example associated piping, buildings, pumps etc...)

None noted



PRESSURE VESSEL
VISUAL INSPECTION
REPORT

Report #: **91609-KS-01**
Inspect Date: 07/22/2011
Page: 6 of 13
Insp. Co. Job #: 91609

Insp. Company: Matrix Inspection LSD: 03-32-045-21W4 Jurisdiction #: A0102602

Thickness and Remaining Life Evaluation “**Must be Completed**”

MUST BE COMPLETED AND RESOLVED WITH CNRL IMMEDIATELY UPON DISCOVERY OF LOW WALL THICKNESS AREAS

Step 1: Was any thickness measurement location found to be less than (Nominal WT – Corrosion Allowance)? **No**

If YES, proceed to Step 2; if NO, proceed to “Crack Evaluation” and “CNRL Criticality Designation”.

Step 2: Which component(s) were found below (Nominal WT – Corrosion Allowance)?

Components found below Nom - CA:

Components
N/A - N/A
N/A - N/A
N/A - N/A
N/A - N/A
N/A - N/A

Perform Steps 3 – 8 for each component with actual thickness less than (Nominal WT – Corrosion Allowance).

Step 3: Describe Location and Extent of Corrosion:

Components	Location and Extent of Corrosion
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection

Notes:

Not Applicable for this Inspection

Step 4:

- For shells and nozzles, calculate minimum required thickness (T-min) as per ASME Section VIII UG-27.
- For heads, calculate minimum required thickness (T-min) as per ASME Section VIII UG-32.

Components	T-Min
N/A - N/A	N/A
N/A - N/A	N/A
N/A - N/A	N/A
N/A - N/A	N/A
N/A - N/A	N/A



PRESSURE VESSEL
VISUAL INSPECTION
REPORT

Report #: **91609-KS-01**
Inspect Date: 07/22/2011
Page: 7 of 13
Insp. Co. Job #: 91609

Insp. Company: Matrix Inspection LSD: 03-32-045-21W4 Jurisdiction #: A0102602

Thickness and Remaining Life Evaluation (Continued)

Step 5: Is any measured thickness less than calculated minimum required thickness (T-min)? **N/A**

*If YES, complete Step 6
If NO, proceed to Step 7..*

Step 6: Is nature and extent of pitting acceptable as per API 510? **N/A**

Step 7: Calculate Remaining Life as per API 510. How? (Find last reading; use nominal thickness if nothing available). Short Term Corrosion Rates and Long Term Corrosion Rates.

Components	Remaining Life (Yrs)
N/A - N/A	N/A
N/A - N/A	N/A
N/A - N/A	N/A
N/A - N/A	N/A
N/A - N/A	N/A

Step 8: Contact CNRL Integrity Coordinator to discuss above results.

- Name of CNRL contact: Not Applicable for this Inspection
- Date and time of conversation: Not Applicable for this Inspection

Summary/results of conversation:
Not Applicable for this Inspection

Crack Evaluation by Magnetic Particle or Alternative Inspection “Must be Completed”

MUST BE COMPLETED AND RESOLVED WITH CNRL IMMEDIATELY UPON DISCOVERY OF CRACK-LIKE INDICATIONS

Were any indications found to suggest the vessel contained cracks? **No**

If NO, proceed to “CNRL Criticality Designation”.

If YES, Contact CNRL Integrity Coordinator to discuss results.

- Name of CNRL contact: Not Applicable for this Inspection
- Date and time of conversation: Not Applicable for this Inspection

Summary/results of conversation:
Not Applicable for this Inspection



PRESSURE VESSEL
VISUAL INSPECTION
REPORT

Report #: **91609-KS-01**
Inspect Date: 07/22/2011
Page: 8 of 13
Insp. Co. Job #: 91609

Insp. Company: Matrix Inspection LSD: 03-32-045-21W4 Jurisdiction #: A0102602

CNRL Criticality Evaluation – “MUST BE COMPLETED”

The CNRL In-Service Pressure Vessel Inspector MUST answer all the following questions

1. Is the vessel fit-for-service? : **Yes**
2. Was the measured thickness less than the calculated minimum required thickness (T-min) for any component?: **No**
3. Were MT indications found?: **N/A**
4. Was the remaining life less than 6 years for sour service vessels or less than 10 years for sweet service vessels?:
5. Were NCR's or Action Items generated as a result of the inspection? : **No**
6. Were UT readings below (Nominal WT – Corrosion Allowance) found? : **No**

Information on CNRL Owner User Program - Criticality Designation and Required Review

RED – Vessel Inspection Results are deemed RED if one of the following occurred:

- The measured thickness was less than the calculated minimum required thickness (T-min) for any component.
- MT indications were found.
- The remaining life was calculated to be less than 6 years for sour-service vessels or less than 10 years for sweet-service vessels.

RED inspection reports must be signed off by the CNRL Chief Inspector.

YELLOW – Vessel Inspection Results are deemed YELLOW if one or more of the following occurred:

- The vessel was declared NOT fit-for-service by the 3rd Party In-Service PV Inspector.
- NCR's or Action Items were generated as a result of the inspection.
- UT readings below (Nominal WT – Corrosion Allowance) were found.

YELLOW inspection reports must be signed off by the CNRL Pressure Equipment Integrity Coordinator.

GREEN – Vessel Inspection Results are deemed GREEN if all of the following are true:

- The vessel was declared fit-for-service by the 3rd Party In-Service PV Inspector.
- UT readings below (Nominal WT – Corrosion Allowance) were NOT found.
- MT indications were NOT found.
- NCR's or Action Items were NOT generated as a result of the VE inspection.

GREEN inspection reports must be signed off by the 3rd Party In-Service Pressure Vessel Inspector.

Criticality Designation



Green

Vehicle #: 324 Kms: _____
Time In: 00:00 Time Out: 00:00 Hrs _____
Time In: 00:00 Time Out: 00:00 Hrs _____
Personnel: _____
Billing Info: _____

Inspector (Name): Kirandeep Singh PESL: 415
Inspector (Signature): _____ API: 33038
CNRL Coordinator (Name): _____
CNRL Coordinator (Signature): _____
CNRL Chief Inspector (Signature): _____
(I am in full agreement with report contents) _____
(I am in full agreement with report contents) _____

Equipment Photographs:



01-Nameplate



02-South side of vessel Insulated



03-North side of vessel inside the vessel



04-Noth side bottom part of vessel



05-Minor insulation damage



06 -West side Firetube ways



07-West side internal view



08-General Corr. and general pitting



09-thermocouple and floater



10-level gage floater



100_0844



11-East side Internal View



12-Shell MW corroded was epoxy repaired



13-East side internal epoxy damage



14-East side electric grid - Removed



15-East side shell



16-Anodes - Replaced