



# Pressure Equipment Static Data

General Information							
Date:	June 16, 2023	Location:	Surface:	10-15-056-27W5			
Client/Owner:	CNRL		UWI/DH:	10-15-056-27W5			
District/Region:	Hinton	Location Access:		All Year			
Area:	Wildhay	Inspection Type(s):		VE      UT      NDE_MT      VI			
Facility:	Compressor						
Pressure Equipment Information							
Equip Name:	Line Heater			CA (in):	N/A	mm:	
Manufacturer:	Alco Gas & Oil			MDMT:	- 20 F		
Provincial #:	A0506174	Unit /Skid #:	N/A		PWHT:	N/A	
S/N:	2004-7184-02	Equip #:	N/A		RT:	N/A (Pipe)	
CRN:	D-3826.21	Year Built:	2004		Manway:	Yes	Size (in):      Firetube Opening
NB #:	N/A	Orientation:	Horizontal				
Zones							
	MAWP (PSI)	MAWT (F)	MAWP (KPA)	MAWT (C)	Comment		
Shell Side	15				Atmospheric pressure		
Coil 1	1800	200					
Piping	Flange Rating	600	MAWP (PSI)	1480	No nameplate info for 2" coil. Flange rating used.		
Components							
	Dia (OD) in.	Type	Material	Nominal (in)	Nominal (mm)	Comment	
Shell	72	Plate	SA-36	0.250			
Head	72	Flat	SA-36	0.375			
Shell 2	30	Plate	SA-36	0.250		Material and nominal assumed	
Pressure Safety Valve(s)							
Zone:	Shell Side						
Equip #							
Location							
Set Press (PSI)							
Capacity		SCFM					
Set Press (KPA)							
Manufacturer							
S/N							
Model							
Inlet Size (in)		Locked Open?					
Outlet Size (in)							
Inlet I/V							
Outlet I/V							
Service Co.							
Serv. Date							
Service Status and Conditions							
Status:	Out of Service		Service:	Sour		Primary Contents - Shell:	Glycol
			Concentration:			Primary Contents - Tube:	Gas
Comments							
Vessel is out of service and disconnected.							
Static data above is for pressure coil. Line heater shell S/N 2004-7184-01.							

AVALANCHE INTEGRITY



REVIEWED

By Tylor Mombourquette at 8:34 am, Jun 27, 2023



## Pressure Vessel External Inspection

<b>Date:</b>		June 16, 2023	<b>Equip Name:</b>		Line Heater
<b>Inspector:</b>		Kyle Bruns	<b>Prov #:</b>		A0506174
<b>Client/Owner:</b>		CNRL	<b>S/N:</b>		2004-7184-02
<b>District/Region:</b>		Hinton	<b>Unit /Skid #:</b>		N/A
<b>Area:</b>		Wildhay	<b>Equip #</b>		N/A
<b>Facility:</b>		Compressor	<b>Location:</b>	<b>Surface:</b>	10-15-056-27W5
				<b>UWI/DH:</b>	10-15-056-27W5
Component	Condition	Comment			
<b>Nameplate</b>	Acceptable	Good condition. Securely attached, legible and all required information is present.			
<b>Grounding</b>	Acceptable	Vessel is grounded through skid.			
<b>Foundation/Supports</b>	Acceptable	Vessel is well supported on saddles, no concerns noted. All anchor bolts are installed and are secure.			
<b>Ladder/Platform</b>	Acceptable	Ladder is in good condition and safe for use.			
<b>Insulation/Cladding</b>	Acceptable	Vessel is 90% insulated and cladded. Insulation is in good overall condition.			
<b>Shell</b>	Acceptable	Shell is in good condition, no concerns noted. Shell is well painted, no external corrosion concerns.			
<b>Heads</b>	Acceptable	Heads are in good condition, no concerns noted.			
<b>Nozzles/Threadolets</b>	Acceptable	All nozzles are in good condition. No concerns noted with deflection, improper thread engagement or bolting (as applicable).			
<b>Piping/Valves</b>	Acceptable	All associated piping is adequately supported and in good condition. No concerns noted with leaks, deflection, thread engagement or bolting (as applicable).			
<b>Appurtenances &amp; Instrumentation</b>	Acceptable	Instrumentation is in good condition, no leaks noted. Pressure/Temperature gauge(s) are in good condition and operating within design limits (as applicable).			
<b>Sight Glass/Level Gauges</b>	Acceptable	Sight glass(es) are in good condition. Rated for current vessel service with no concerns noted.			
<b>Other</b>	N/A				
<b>PSV</b>	N/A	No PSV present.			
<b>NDE Methods</b>	Acceptable	UT survey and MPI performed by Avalanche. No concerns at this time. No indications were noted during MPI.			
<b>Inspection Summary</b>					
<b>Recommendations</b>					<b>NCR #</b>

<b>Fit for Service:</b>		Yes		<b>Signature of Inspector:</b>			
<small>* Fit for Service is only a recommendation based on the results of the current inspection.</small>				<b>Cert #</b>		API 510: 54849	
						AB/SK: 979	
<b>Recommended Intervals:</b>				<b>Quality Systems Manager or Delegate:</b>		Mike Williams	
							
				<b>VE</b>		yrs	
<b>UT</b>		yrs				AB/SK: 200	
<b>PSV</b>		yrs					

PHOTOS



LSD Sign



Site Overview



Nameplates



Overview





## Pressure Vessel Internal Inspection

<b>Date:</b>	June 16, 2023	<b>Equip Name:</b>	Line Heater
<b>Inspector:</b>	Kyle Bruns	<b>Prov #:</b>	A0506174
<b>Client/Owner:</b>	CNRL	<b>S/N:</b>	2004-7184-02
<b>District/Region:</b>	Hinton	<b>Unit /Skid #:</b>	N/A
<b>Area:</b>	Wildhay	<b>Equip #</b>	N/A
<b>Facility:</b>	Compressor	<b>Location:</b>	<b>Surface:</b> 10-15-056-27W5
			<b>UWI/DH:</b> 10-15-056-27W5
Component	Condition	Comment	
<b>Shell</b>	Acceptable	All accessible shell surfaces were in good overall condition. There was limited access to all shell surfaces above and around the process coil. Minor corrosion was visible at the 6 o'clock position in a 38" long area at the back end of shell measured from the back head. The deepest corrosion was measured to be 0.020" deep using a pit gauge. Corrosion is not a significant concern at this time. Product scaling was noted throughout the shell at the 12 o'clock position. Unable to visually confirm any corrosion depths due to the process coil.	
<b>Heads</b>	Acceptable	Both heads were in good overall condition. There was no visible corrosion or mechanical damage noted during inspection. Inspection was limited on the top surface area of the back head due to the process coils.	
<b>Manway</b>	Acceptable	Firetube opening is the manway for the line heater. No visible concerns at time of inspection.	
<b>Nozzles</b>	Acceptable	All accessible nozzles were free of corrosion, mechanical damage or any deflection. Accessible nozzles are in good overall condition.	
<b>Gasket Surfaces</b>	Acceptable	The gasket seating surfaces on the firetube tube sheet and the line heater shell flange were in good overall condition. There was no visible corrosion or mechanical damage. No sealing concerns at this time.	
<b>Internals</b>	Acceptable	All accessible internals including firetube support brackets, fuel gas coil, process coil support brackets, and the process coils were securely in place. There was no visible corrosion or mechanical damage noted. There was no visible fretting at any of the process coil to support plate interfaces.	
<b>Welds</b>	Acceptable	Accessible welds were in good condition. There was no visible corrosion. All accessible welds had full profile and had the same general appearance as the HAZ and the parent material.	
<b>Coating</b>	N/A		
<b>Firetube</b>	Acceptable	24" Firetube was in good overall condition. There was no significant corrosion or mechanical damage noted. Minor corrosion noted inside the stack side tube at the 5-7 o'clock position. There was no visible hot spots or deformation noted during inspection.	
<b>Tubesheet</b>	Acceptable	Firetube tubesheet is in good overall condition. There was no visible corrosion, mechanical damage, or deflection noted at time of inspection.	
<b>Tube Bundle</b>	N/A		
<b>Other</b>	Observation	Thief hatch is in good overall condition and was in good working order. Minor corrosion noted in nozzle neck. All corrosion was less than 0.020" deep. Hatch seal is in poor condition and needs to be replaced.	
<b>NDE Methods</b>	Acceptable	MT and UT was completed on the 24" firetube. No visible significant surface indications noted during MT. Minor internal wall loss noted on the stack side tube at the 5-7 o'clock position of tube. UT thickness readings were taken on all accessible return bends of the process coils. No significant wall loss noted at time of inspection.	
<b>Inspection Summary</b>	Line Heater is in good overall condition. Minor corrosion noted at the 6 o'clock position of shell at the back end of line heater. The deepest corrosion was 0.020" measured with a pit gauge. There was no other significant corrosion or mechanical damage noted.		
	Thief hatch seal was cracked and damaged. No relevant surface indications noted during Firetube MT inspection. No significant wall loss noted during process coil return bend UT.		
	Inspection of the internal upper surfaces of line heater was limited due to the process coils.		
<b>Recommendations</b>			<b>NCR #</b>
Replace thief hatch seal prior to start up.			



## Pressure Vessel Internal Inspection

<b>Fit for Service:</b>	Yes			<b>Signature of Inspector:</b>									
<small>* Fit for Service is only a recommendation based on the results of the current inspection.</small>		<b>Cert #</b>	API 510:	54849									
			AB/SK:	979									
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th colspan="2" style="background-color: #e1eef6;">Recommended Intervals:</th> </tr> <tr> <td style="width: 50%;">VI</td> <td style="width: 50%; text-align: center;">yrs</td> </tr> <tr> <td>UT</td> <td style="text-align: center;">yrs</td> </tr> <tr> <td>PSV</td> <td style="text-align: center;">yrs</td> </tr> </table>		Recommended Intervals:		VI	yrs	UT	yrs	PSV	yrs	<b>Quality Systems Manager or Delegate:</b>		Mike Williams	
		Recommended Intervals:											
		VI	yrs										
		UT	yrs										
PSV	yrs												
<b>Cert #</b>	API 510:	24838											
	AB/SK:	200											

AVALANCHE INTEGRITY



PHOTOS



FIRETUBE OVERVIEW



ATMOSPHERE SIDE OF TUBESHEET



PRODUCT SIDE OF TUBESHEET



MITER SECTION END



STACK SIDE INTERNAL OVERVIEW



BURNER SIDE INTERNAL OVERVIEW



PHOTOS



FIRETUBE OPENING OVERVIEW



TYPICAL FIRETUBE OPENING GASKET SURFACE



EXPANSION TANK THIEF HATCH NOZZLE NECK



EXPANSION TANK THIEF HATCH GASKET CONDITION



INTERNAL OVERVIEW




PROCESS COIL OVERVIEW



PHOTOS



TYPICAL PROCESS COIL SUPPORT TO SHELL WELD



TYPICAL PROCESS COIL/ PLATE INTERFACE



TYPICAL PROCESS COIL/ PLATE INTERFACE



TYPICAL WELD SEAM CONDITION



EXPANSION TANK NOZZLE



FUEL GAS COIL PIPING



PHOTOS



THERMOWELLS



BACK HEAD OVERVIEW




INTERNAL OVERVIEW FROM BACK END



2" DRAIN NOZZLE



FRONT END RETURN BENDS OVERVIEW



BACK END RETURN BENDS OVERVIEW

PHOTOS





GENERAL CORROSION AT BACK END OVERVIEW



TYPICAL CORROSION CLOSE UP AT BACK END



STATIC DATA					
<b>Date:</b>	June 16, 2023		<b>Equip. Name:</b>	Line Heater	
<b>Client/Owner:</b>	CNRL		<b>Provincial #:</b>	A0506174	<b>Equip #:</b> N/A
<b>District:</b>	Hinton		<b>Manufacturer:</b>	Alco Gas & Oil	<b>CRN:</b> D-3826.21
<b>Area:</b>	Wildhay		<b>Year Built:</b>	2004	<b>S/N:</b> 2004-7184-02
<b>Facility:</b>	Compressor		<b>RT (Joint Eff):</b>	N/A (Pipe)	<b>CA:</b> N/A in
<b>Location/LSD:</b>	SF:	10-15-056-27W5	UWI/DH:	10-15-056-27W5	
<b>Notes:</b>					





# UT CORROSION SURVEY REPORT READINGS

AIR-104

<b>Date:</b>	June 16, 2023	<b>Area:</b>	Wildhay	<b>Equip Name:</b>	Line Heater	<b>Equip #:</b>	N/A
<b>Client:</b>	CNRL	<b>LSD:</b>	SF: 10-15-056-27W5 / UWI: 10-15-056-27W5	<b>Prov #:</b>	A0506174	<b>S/N:</b>	2004-7184-02

VESSEL TMLS																	
TML ID	Baseline		Previous		Current												
	01-Jan-04	01-Jan-04	01-Jan-04	01-Jan-04	16-Jun-23	16-Jun-23	SIZE (OD)	NOM	STCR (/YR)	LTCR (/YR)	Tmin	ST RL (YRS)	LT RL (YRS)	% Loss	Zone	Component / Type	
05	0.375	0.375	0.375	0.375	0.372	0.375	72.000	0.375	0.0002	0.0002	0.216	50.0	50.0	0.80%	Shell Side	Head	Flat
10	0.250	0.250	0.250	0.250	0.247	0.253	72.000	0.250	0.0002	0.0002	0.032	50.0	50.0	1.20%	Shell Side	Shell	Plate
15	0.250	0.250	0.250	0.250	0.241	0.245	72.000	0.250	0.0005	0.0005	0.032	50.0	50.0	3.60%	Shell Side	Shell	Plate
20	0.250	0.250	0.250	0.250	0.219	0.233	72.000	0.250	0.0016	0.0016	0.032	50.0	50.0	12.40%	Shell Side	Shell	Plate
25	0.250	0.250	0.250	0.250	0.246	0.249	72.000	0.250	0.0002	0.0002	0.032	50.0	50.0	1.60%	Shell Side	Shell	Plate
30	0.250	0.250	0.250	0.250	0.243	0.247	72.000	0.250	0.0004	0.0004	0.032	50.0	50.0	2.80%	Shell Side	Shell	Plate
35	0.375	0.375	0.375	0.375	0.371	0.374	72.000	0.375	0.0002	0.0002	0.216	50.0	50.0	1.07%	Shell Side	Head	Flat
40	0.250	0.250	0.250	0.250	0.234	0.247	30.000	0.250	0.0008	0.0008	0.013	50.0	50.0	6.40%	Shell Side	Shell 2	Plate
45	0.250	0.250	0.250	0.250	0.245	0.247	30.000	0.250	0.0003	0.0003	0.013	50.0	50.0	2.00%	Shell Side	Shell 2	Plate





## UT CORROSION SURVEY REPORT READINGS

### ATTACHMENT / PIPING / NOZZLE TMLS

TML ID	Baseline		Previous		Current													
	01-Jan-04	01-Jan-04	01-Jan-04	01-Jan-04	16-Jun-23	16-Jun-23	SIZE (OD)	NOM	STCR (/YR)	LTCR (/YR)	Tmin	ST RL (YRS)	LT RL (YRS)	% Loss	SCH	Zone	Shape	Type
50	0.154	0.154	0.154	0.154	0.149	0.164	2.375	0.154	0.0003	0.0003	0.085	50.0	50.0	3.25%	STD	Piping	90°	Piping
55	0.154	0.154	0.154	0.154	0.144	0.157	2.375	0.154	0.0005	0.0005	0.085	50.0	50.0	6.49%	STD	Piping	90°	Piping
60	0.154	0.154	0.154	0.154	0.141	0.150	2.375	0.154	0.0007	0.0007	0.085	50.0	50.0	8.44%	STD	Piping	90°	Piping
65	0.154	0.154	0.154	0.154	0.133	0.154	2.375	0.154	0.0011	0.0011	0.085	44.2	44.2	13.64%	STD	Piping	90°	Piping
70	0.337	0.337	0.337	0.337	0.337	0.343	4.5	0.337	0.0000	0.0000	0.195	50.0	50.0	0.00%	XS	Coil 1	360°	Piping
75	0.337	0.337	0.337	0.337	0.329	0.337	4.5	0.337	0.0004	0.0004	0.195	50.0	50.0	2.37%	XS	Coil 1	360°	Piping

Comments:	TML 20: Corrosion noted.
	TML 65: Erosion noted.

*\*Disclaimer*

*Corrosion rates and remaining life calculations may not be accurate for any of the following reasons: i) year built and nominal used as baseline in calculations, ii) short time period between survey dates, iii) previous survey data was point readings instead of full scans. Client to perform follow up calculations as required.*

*Corrosion rates and remaining life calculations are not able to be performed in the following scenarios: i) baseline survey on new equipment, ii) when year built or in-service date is unknown, iii) Tmin is not able to be calculated, iv) no previous inspection history is available to provide previous date and readings needed for calculations.*

*If requested by client, the Tmin used for "Piping" Type is the greater of Pressure Design Thickness or API 574 – Table 7 Default Minimum Structural Thickness.*




# UT CORROSION SURVEY REPORT READINGS

**Notes:**

- \*All readings are in:        inches
- \*Piping T<sub>min</sub> calculated: Pressure Design Calcs
- \*RL maximum is 50 years.
- \*% Wall loss is based on current low vs nominal.
- \*Baseline is based off nominal if no previous readings available and started in year equipment was fabricated, unless other information is available to prove in-service date.
- \*Previous readings taken from baseline if no past readings/survey data are available.
- \* Day/Month used for Baseline and Previous readings is arbitrary if no dates are provided.
- \* If no corrosion comments are made on piping, general low thickness was noted.

UT EQUIPMENT & PROCEDURES					
Probe	Wave	Freq.	Size	Manuf.	Serial #
Dual	Long - 0°	5 Mhz	1/4"	Stresstel	23B00CR7
<u>UT Set</u>		<u>Serial #</u>		<u>Cal Date</u>	<u>Cal Block</u>
DMS GO+		GOPLS18010127		03-Jan-2023	1" C/S Step
<u>Procedure(s):</u>			UT-01		AI-CR-01

TECHNICIAN SIGN-OFF		
Inspector:	Kyle Bruns	CGSB Certifications:
		10294
Signature:		UT I / MT II / PT II / RT II





## NDE REPORT

STATIC DATA					
Date:	June 16, 2023		Equip. Name:	Line Heater	
Client/Owner:	CNRL		Provincial #:	A0506174	Equip #: N/A
District:	Hinton		Manufacturer:	Alco Gas & Oil	CRN: D-3826.21
Area:	Wildhay		Year Built:	2004	S/N: 2004-7184-02
Facility:	Compressor		RT (Joint Eff):	N/A (Pipe)	CA: N/A in
Location/LSD:	SF:	10-15-056-27W5	UWI/DH:	10-15-056-27W5	
CRITERIA / SURFACE CONDITION					
INSPECTION METHOD(S):	UT	MT		ACCEPTANCE CRITERIA:	CLIENT EVALUATION
PROCEDURE(S):	MT-2A		UT-01	SPECIFICATION(S):	AS PER CLIENT SPEC.
SURFACE CONDITION:	WIRE WHEEL CLEANED	AS WELDED		MATERIAL / THICKNESS:	CARBON STEEL 0.375"
MT/PT					
MINIMUM LIGHT INTENSITY: $\geq 100$ fc Visible, $\geq 1000$ $\mu$ W/cm <sup>2</sup>					
LIGHTING TYPE:	Ambient Lighting				
EQUIPMENT TYPE	SERIAL #	CALIBRATION DATE		MT CONSUMABLES	
BLACKLIGHT				MEDIUM:	MAGNAFLUX 7HF (BWMP)
LIGHT METER				CONTRAST:	MAGNAFLUX WCP-2
YOKE	N3177		June 16, 2023		APPLICATION: SPRAY
YOKE TYPE	AC	CONTINUOUS	120 V	LEG SPACING: 3" - 8"	
PRODUCT	MFG / TYPE	BATCH #	DWELL (MIN)	APPLICATION METHOD	METHOD TYPE
PENETRANT:					
CLEANER:					
DEVELOPER:					
TEST RESULTS					

**MT SCOPE:**

A WET BLACK ON WHITE MAGNETIC PARTICLE EXAMINATION WAS PERFORMED ON THE FOLLOWING LIST OF WELDS AS REQUESTED BY CLIENT. THE MT WAS DONE ON THE WELDS AS WELL AS A 1"-2" AREA TO EACH SIDE.

- 1- ATMOSPHERE SIDE TUBE TO TUBE SHEET FILLET WELDS
- 2- PRODUCT SIDE TUBE TO TUBE SHEET FILLET WELDS
- 3- ALL TUBE TO TUBE BUTT AND MITER SECTION WELDS
- 4- FIRETUBE SUPPORT BRACKET FILLET WELD

**MT RESULTS:**


NO VISIBLE RELEVANT SURFACE INDICATIONS NOTED AT TIME OF INSPECTION. SEE BELOW FOR LOCATIONS.

**UT SCOPE:**


ZERO DEGREE UT THICKNESS READINGS WERE TAKEN IN SELECT AREAS OF BOTH SIDES OF FIRETUBE AS WELL AS THE MITER SECTION. UT WAS ALSO COMPLETED ON ALL ACCESSIBLE RETURN BENDS OF THE 4" PROCESS COIL INSIDE OF THE LINE HEATER AS REQUESTED BY THE CLIENT.

**UT RESULTS:**

MINOR INTERNAL CORROSION WAS NOTED THROUGHOUT THE 6 O'CLOCK POSITION OF THE STACK SIDE TUBE. THERE WAS NO SIGNIFICANT WALL LOSS NOTED IN ANY OF THE INSPECTED RETURN BENDS. SEE BELOW FOR LOCATIONS AND RESULTS.

TECHNICIAN:	Kyle Bruns	ASSISTANT:	Melissa Reeves
SIGNATURE:		CLIENT:	
CGSB/SNT CERTS:	10294 UT I / MT II / PT II / RT II	SIGNATURE:	

TEST RESULTS / PHOTOS




O.D	24"
LENGTH	28'
NOM.	0.375"

ASSUMED

LOCATION	LOW	AVG
05	0.356"	0.367"
10	0.357"	0.366"
15	0.353"	0.366"
20	0.362"	0.369"
25	0.361"	0.377"
30	0.367"	0.372"
35	0.372"	0.381"
40	0.351"	0.373"
45	0.336"	0.364
50	0.341"	0.367"
55	0.351"	0.369"

TEST RESULTS / PHOTOS



LOCATION	LOW	AVG
05	0.309"	0.323"
10	0.317"	0.332"
15	0.327"	0.337"
20	0.339"	0.346"
25	0.304"	0.328"
30	0.319"	0.329"
35	0.321"	0.341"
40	0.321"	0.332"
45	0.346"	0.353"
50	0.302"	0.329"
55	0.328"	0.349"
60	0.321"	0.339"
65	0.328"	0.347"

4.5" O.D. - 0.337" ASSUMED NOMINAL