

## Ultrasonic Inspection Report

Report #:	125209	-UT-BV-09	IRISN	NDT Job #:	1	125209	Date:	MARCH 26, 2008	Page	<b>1</b> of	1		
Client:	CNRL PO/Job #: 16980:					592.5430.1	15-G829	Contact:	BRAD	BODNAR	_		
Job location:	CHIN COULEE, MEDICINE HAT WEST, ALBERTA							Tel:	(403)	634-2453			
LSD. 03-19-008-16 W4M Fax: (403) 223-8318													
Procedure(s):	re(s): UT THICKNESS												
Code(s):	Code(s): ASME SECT VIII												
Item Inspected: Test Separator A3028074 Material: Carbon Steel													
Method:	•						Surface Temp (C): $\boxtimes < 5^{\circ}$ $\square > 5^{\circ} / < 60^{\circ}$ $\square > 60^{\circ}$						
Type:	Type: ☐ P/E ☐ T/T ☐ Dual ☐ Automated ☐ TOFD							Scanning Surface:					
Application: ☐ Laminar ☐ Shear Wave ☐ Volumetric ☐ Thickness Surface Condition: ☐ Good													
Instrumentation: Manufacturer: Krautkramer Type:								Instrumen	t Ser. #:	31530			
Calibration: Date: Jan 10, 2008 Reference Flaw Size:								IRISNDT #: <b>31530</b>					
Calibration Block(s): Type: Step Wedge - I IRISNDT #: 1							Type:	IRISNDT #:					
Type: IRISNDT #:							Type:			IRISNDT #:			
Couplant: Br	and: Ec	hogel	Type:	971		Cable:	Type:	Coaxial		Length:	36"		
Probe							ETTINGS - dI	3	RAN	GE - 🗌 INCHES	S 🗌 MM		
Manufacturer	Type	Serial #	Angle	Frequency	Size	Reference Level	Scanning Level	Transfer Value	Screen Size	Skip Value	Beam Travel		
Krautkramer	Dual	01F988	0	8.0 MHz	0.250	55dB	+6 dB	, ,,,,,,,	~				
INSPECTION DETAILS  OF A STATE OF THE STATE													
Scope: Carry out UT Examination of Test Separator A3028074. Check for corrosion of the Shell, Heads and Elbows to verify the integrity for service and identify any areas of concern. Examination revealed the following:													
are megral, for service and identity any areas or concern. Danimum of revealed the following.													
Results: UT examination was carried out; all readings taken were 10"band scans with three readings per band/location.  Minimun, Maximum and Average scans were taken in each location and recorded.													
All readings were found to be above nominal on the Shell, Heads and Elbows.  No areas of concern were found at the time of inspection. Vessel out of service.													
130 areas of concern were found at the time of hispection. Vessel out of service.													
Recommendations: Carry out Visual External inspection at the next opportunity and also continue to carry out UT													
Corrosion survey at the required frequency. See attached drawing, pictures and UTM file for locations and thicknesses recorded.													
See attached drawing, pictures and O 1191 the for locations and unicknesses recorded.													
Final Comment: Test Separator A3028074 is fit for service.													
Assistant:						Technician: BLAIR VERGE							
☐ CGSB ☐ SNT UT Level: ☐ I ☐ III ☐ III No.#:						☐ CGSB ☐ SNT UT Level: ☐ I ☐ II ☐ III No.#: 5586							
Unit: 393 Km: Travel Time:							Signature:						
Start:	Start: Stop: Work hrs:												
OT Meal	otal hrs:	Client Na	Client Name:										
Consumables:		Signat	ure:										
						I							

of

## CORROSION INSPECTION SERVICES



