

Perilon Inspection Inc.

Box 359 Duchess, Ab (403) 501-6013 dale toews@platinum.ca

VESSEL SHEAR WAVE REPORT				
CLIENT	CNRL	Equip Ident:	A0191662	
		Inspec Date m/d/y	09/16/2015	
CLIENT REP	Carson Petersen	Facility	Ralston 5-14 Battery	
	Ralston 5-14	LSD	05-14-018-10W4MW4M	

NDE Examiner: Dale Toews Helper:

Equip Ident: A0191662 Equip Descrip: Treater Firetube

UT Equipment: USMGO SN: 12105417 Cal Due: June 26, 2016

Work: Complete shear wave UT on steel blisters on firetube. Determine if blister has caused cracks within the

metal.

General Commetnts

60 degree scan from the tubesheet was limited because of the bolt holes in the tubesheet. Scanning was mostly done from between the bolt holes.

70 degree scan from the tubesheet was impossible, because horizontal distance to the firetube was too short.

Scanning of the small blister was limited:

- 1. The surface of the metal (inside firetube) was too rough (general corrosion) to get a consistent signal.
- 2. Scanning from outside the tube, there was not enough space between the tubes.
- 3. Firetube gusset between tubes. Tubes not flipped to scan other side.



Perilon Inspection Inc.

Perilon Report No Inspec Date m/d/y Page A0191662 09/16/2015 2 of

+ 12 dB

A No A0191662 Eq No Ser No Equip Treater Firetube

45 Degree Scan

Scan from position A and B, large and small blister, small blister scan area limited

Ref Level: 47.2 dB Probe: Krautkramer, 45 degree, 3.5 MHz, 0.5 inch Scan

Scan Sens: 47.2 dB

Calibration: IIW metric, 1 inch carbon steel plate, 6 mm side drilled hole, ASME 5 Article 5 (UT)

Sound path to hole: 80 mm Screen Height: 80% FSH

Acceptance Standard: Indications greater than 20% examined to determine if they are cracks.

Results: No cracks discovered.

Scan from position C and D, large blister only, surface too rough for small blister


Ref Level: 37.6 db Probe: Krautkramer, 45 degree, 5 MHz, 0.25 inch Scan Sens: 37.6 db + 12 dB

Calibration: IIW metric, 1 inch carbon steel plate, 6 mm side drilled hole, ASME 5 Article 5 (UT)

Sound path to hole: 19 mm Screen Height: 80% FSH

Acceptance Standard: Indications greater than 20% examined to determine if they are cracks.

Results: No cracks discovered.





Perilon Report No Inspec Date m/d/y Page A0191662 09/16/2015 3 of

A No A0191662 Eq No Ser No Equip Treater Firetube

60 Degree Scan

Scan from position A and B, large blister complete, small blister scan area limited

Ref Level: 54.6 dB Probe: Krautkramer, 60 degree, 3.5 MHz, 0.5 inch Scan Sens:

ns: 54.6 dB + 12 dB

Calibration: IIW metric, 1 inch carbon steel plate, 6 mm side drilled hole, ASME 5 Article 5 (UT)

Sound path to hole: 85 mm Screen Height: 80% FSH

Acceptance Standard: Indications greater than 20% examined to determine if they are cracks.

Results: No cracks discovered.

Scan from position C and D, large blister only, surface too rough for small blister


Ref Level: 55 dB Probe: Krautkramer, 60 degree, 5 MHz, 0.25 inch Scan Sens: 55 dB + 12 dB

Calibration: IIW metric, 1 inch carbon steel plate, 6 mm side drilled hole, ASME 5 Article 5 (UT)

Sound path to hole: 35 mm Screen Height: 80% FSH

Acceptance Standard: Indications greater than 20% examined to determine if they are cracks.

Results: No cracks discovered.





Perilon Inspection Inc. Inspection Inc. Inspection Inc.

Perilon Report No Page

A0191662 09/16/2015 of

Ser No Treater Firetube A No A0191662 Eq No Equip

70 Degree Scan

Scan from position A and B

Not possible.

Scan from position C and D, large blister only, surface too rough for small blister

Ref Level:

Probe:

Krautkramer, 70 degree, 5 MHz, 0.25 inch

59.4 dB + 12 dB

Calibration:

IIW metric, 1 inch carbon steel plate, 6 mm side drilled hole, ASME 5 Article 5 (UT)

Sound path to hole:


48 mm

Screen Height:

80% FSH

Acceptance Standard: Indications greater than 20% examined to determine if they are cracks.

Results: No cracks discovered.



Inspector Information


Inspector	Dale Toews	PESL Reg Number	000036
Signature		API 510 Number	23064
		CGSB Lev 2 UT, MT Reg Number	10498



Perilon Inspection Inc.

Perilon Report No Inspec Date m/d/y Page A0191662 09/16/2015

A No A0191662 Eq No Ser No Equip Treater Firetube







Perilon Inspection Inc. Inspec Date m/d/y

Perilon Report No

A0191662 09/16/2015

Eq No Ser No A No A0191662 Equip Treater Firetube

