

Report #: 156850-MD-02
Inspect Date: 07/04/2012
Page: 1 of 15
Insp. Co. Job #: 156850

Criticality Designation:				Yellow				
Insp. Comp: Matrix_Insp	ection	District:	Grande Pra	irie - North		Field	d: South	Hamburg
Location: 10-10-096-		Jnit / Skid #:			•	LSE		096-12W6
Jurisdiction #: A04926				00	-	Serial #	#: HS	-9828
CRN #: P0183.2	21	Nat'l Bd #:	N/	Ά	Y	ear Buil	t: 2	000
Manufacturer: Larsen & D'Ami	co Mfg Ltd.	E	quipment Des	scription: O	ther: Horizonta	al Separa	ator	
Status: In Service -		Equ	iip. Type: Ves	ssel: Separa	tor		Service:	Sweet
MAWP Shell: 720 Psi	@ 125	°F	Volume:	8.58	m³		Code Stamp:	\boxtimes Y \square N
MAWP Tube:	_ @		ght/Length:	15	Ft.		Insulated:	\square Y \boxtimes N
MDMT:	RT: <u>RT-1</u>		e/Diameter.: _		O.D.		PWHT:	\boxtimes Y \square N
Support Saddle		Ū	inal CNRL Inv	,	□Y ⊠N		Manway:	⊠Y □N
C.A.: 3.2 mn	n_ Coated: N	0	Clad: No	J.E.:	1.00 Rem	ote Acc	ess: 🗌	
Component	Ма	terial	Nomin	al Thk	Diameter	OD/ID	Tube Side	Shell Side
1 Main - Shell				in. 6	60.000 in.	OD		\boxtimes
2 North - Head				in. 6	60.000 in.	OD		\boxtimes
3 South - Head				in. 6	60.000 in.	OD		\boxtimes
4 -								
5 -								
Static Data: Confirmed	Changed (See	e Comments	s) 🖂					
Static Data Updated Report updated for internal insp	pections during	3 2012 TA						
PSV Static Data								
PSV –1 Tag #: 254		Serial #:	424653-2-A	10		CRN: 0	G2369.5C	
Model #: 26KA12-12	20/S7	_	25900 SCF		Set Pres			
Manufacturer: Farris		_ ' '			Service Com		•	
Inlet Size & Type: 3.00 ii	n Flanged				Last Service		·	
Outlet Size & Type: 4.00 in	n Flanged	_	Block Valve: Upstream - Carsealed - Open					pen
Carseal Intact: Yes		Code Stamp: Yes						
Shell Side / Tube Side: Sh	nell Side	Out for S	Service During	Insp.:	Location of	PSV: C	n Vessel	
PSV –2 Tag #:		Serial #:				CRN:		
Model #:		Capacity:			Set Pres			
Manufacturer:		_ oupdoity.	-		Service Comp			
Inlet Size & Type:	-				Last Service	Doto		
Outlet Size & Type:	_	_		Bloc				
Carseal Intact:		_			Code St	tamp:		
Shell Side / Tube Side: Out for Service During Insp.: Location of PSV:								
PSV Comments								
Due for service								
_ 10 .0. 001 1100								



Report #: 156850-MD-02
Inspect Date: 07/04/2012
Page: 2 of 15
Insp. Co. Job #: 156850

National and control in the distribution and						
		nspection	LSD:10-10-096-12W6 Jurisdic	tion #:	A04	92612
External Inspection Results – VE External Inspection Performed						
Item	N/A	Condition	Comment (Check Status Bar or Press F1 for Help)	NCR	Action Item Integrity	Action Item Maintenance
Nameplate		Accept	Firmly affixed and legible			
Foundation and Supports		Accept	Welded saddles anchored to skid			
Anchor Bolts		Accept	Tight with minor surface corrosion			
Grounding		Accept	Grounded by skid			
Insulation Condition		Reject	Manway thru wall caulking is deteriorated			
PSV		Reject	Due for service			
Shell Heads & Nozzles		Accept	Scratches and minor surface corrosion throughout			
Metal Surfaces (Paint)		Reject	Weathered & chipped exposing base metal			
Aux Equipment		-	No auxiliary equipment			
Cathodic Protection	\boxtimes		No external anode			
Alignment		Accept	Level with skid			
Flange Connections		Accept	Adequate hardware and thread engagement			
Pressure Gauge		•	No pressure gauge			
Temperature Gauge			No temperature gauge			
Sight Glass		Accept	Clear with no evidence of leaks			
Ladder / Platform		•	No ladders or platforms	一		
Leaks		No	No leaks noted at the time of inspection	一百		
Piping from Vessel	Ħ	Accept	Adequately supported and secure			
Previous UT Survey		Yes		ompan	y: N/A	
External Visual Observations						<u> </u>
External visual Observations	<u> </u>					
The coating is weathered, scratched and chipped exposing the base metal to minor surface corrosion throughout the vessel No pitting evident at the time of inspection						
There is condensation noted throughout the vessel which is accelerating corrosion between the flanges, on the piping and hardware on the bottom of the vessel.						
The manway thru wall cau	lking	is deteriorat	ed allowing for moisture ingress.			
The manway is in accepta	ble co	ondition as w	vell as the davit arm and hardware.			
The PSV is due for service	9					
A UT corrosion survey wa	s perf	ormed with i	no significant metal losses recorded at the time of ins	pection	١.	
Recommendations:						
Service the PSV						
Reseal the thru wall caulking to prevent moisture ingress						
Clean and touch up the coating to aid in the protection against corrosion.						



Report #: 156850-MD-02
Inspect Date: 07/04/2012
Page: 3 of 15
sp. Co. Job #: 156850

Cariadi	CHILL	aturai			шър. С	.O. JOD #.	100000
Insp. Company: Matrix_Inspection LSD: 10-10-096-12W6 Jurisdiction #: A0492612					92612		
Internal Inspection Results – VI Internal Inspection Performed							
Item	N/A	Condition	Comment (Check Status Bar or Press F1 for Help)			Action Item Integrity	Action Item Maintenance
Shell	П	Accept	Minor flash co	orrosion from wash out		T Ď	П
Heads		Accept		al/ service related damage			
Manway		Accept		al/ service related damage			
Gasket Surfaces	TH	Accept		errated sealing surface			
Welds	ᅥᆖ	Accept		al/ service related damage			
Refractory		'		Not applicable			
Heating Coils			Not applicable				
Demister Pad	一一	Reject		regated and product build-up			
Vane Pack		,	Not applicable	<u> </u>			
Baffles		Accept		-up on baffle plate			
Trays			Not applicable	<u> </u>			
Filter			Not applicable				
Internal Coating			Not applicable				
Tubesheet			Not applicable			 	
Tube Bundle			Not applicable				
		<u> </u>	110t applicable				Ш
Internal Visual Observation	ıs						
The vessel was blinded,	opene	d and cleane	ed for internal i	nspections July 04 2012			
The overall internal cond	ition of	the vessel i	s good				
It should be noted that th	ere is i	oroduct build	1-un on the he	ads, shell, baffles and demiste	r		
The demister is sagged and segregated with mild product build-up on the mesh. The sagging of the demister pad has resulting in the support harness out of position and partially in the outlet nozzle							
The baffles are in acceptable condition with no evidence of mechanical or service related damage. There is no evidence of "knife-edging" but it should be noted that there is mild product build-up adhered to the baffle surface							
There is minor flash corrosion on the exposed shell and head surfaces from washing and oxidation							
Recommendations:							
Remove and clean the demister pad and reinstall							



Report #: 156850-MD-02
Inspect Date: 07/04/2012
Page: 4 of 15
sp. Co. Job #: 156850

		aturai				ilisp. C	0. JOD #.	130030
Insp. Company:Ma	trix_In	spection	LSD:	10-10-096-	12W6	Jurisdiction #:	A04	92612
Firetube Static Data N/A (Not Applicable)								
Diameter: Not Applicable Nom Thickness: Not Applicable Bend: Not Applicable								
Length: Not Applicable Firetube Description: Not Applicable								
UT Report#: Not Applicable ET Report#: Not Applicable								
	Firetube NDE MT Report#: Not Applicable PT Report#: Not Applicable							
Performed:	PT	=	t#: Not Applic		Other	Report#: Not		
Finatula Inconstina Decult							7 (5) (1) (1)	
Firetube Inspection Result	S	1					A atiana Itana	A ation Itama
Item	N/A	Condition	(Che	Commer neck Status Bar or Pre		NCR	Action Item Integrity	Action Item Maintenance
Burner				Inspection Carrie			, ,	
Stack				Inspection Carrie				
Flange (Throat)				Inspection Carrie				
Tube Sheet				Inspection Carrie				
Hot Side				Inspection Carrie				
Miter				Inspection Carrie				
Return Bend				Inspection Carrie				
Supports				Inspection Carrie				
Butt Welds				Inspection Carrie				
Fillet Welds			No Firetube Ir	Inspection Carrie	d Out			
Firetube Visual Observation	ne							
No Firetube Inspection Carried Out								
Recommendations:								
No Firetube Inspection C	arried	Out						



Report #: 156850-MD-02
Inspect Date: 07/04/2012
Page: 5 of 15
Insp. Co. Job #: 156850

Insp. Company:	Matrix_Inspection	LSD: 10-10-096-	12W6	Jurisdiction #:	A0492612		
Vessel NDE and Final	Summary:						
NDE Performe	UT ⊠ Report#:		ET RT Other	Report#: Report#:			
Maxi-Trak Observation	s Summary (Summarize i	nspection results Max 255	Characters):				
PSV due for service Corrosion between the flanges, on the piping & hardware on the bottom of the vessel The manway thru wall caulking deteriorated TA 2012 - Demister pad is out of position with build-up and segregation							
Maxi-Trak Recommend	dations Summary (Summa	arize Recommendations M	ax 255 Charact	ers):			
Clean and touch up t	caulking to prevent moistu the coating to aid in the proclean and reinstall demiste	otection against corrosion					
Actions Corrected at T	ime of Inspection: (If action	s were corrected at the time of Ins	spection – note the o	orrected actions here.)			
The demister pad wa	s removed, cleaned and	reinstalled					
Additional Visual Obse	rvations						
No additional visual observations woe made at the time of inspection							
Any other safety conce	rns or observations from	associated equipment: (fo	r example asso	ciated piping, buildings, լ	oumps etc)		
No safety concerns a	at the time of inspection						



Report #: 19
Inspect Date:
Page:

Insp. Co. Job #:

156850-MD-02 07/04/2012 6 of 15 156850

Insp. Company: Matrix_Inspection LSD: 10-10-096-12W6 Jurisdiction #: A0492612

Thickness and Remaining Life Evaluation

" Must be Completed"

MUST BE COMPLETED AND RESOLVED WITH CNRL IMMEDIATELY UPON DISCOVERY OF LOW WALL THICKNESS AREAS

Step 1: Was any thickness measurement location found to be less than (Nominal WT - Corrosion Allowance)?: No

If YES, proceed to Step 2; if NO, proceed to "Crack Evaluation" and "CNRL Criticality Designation".

Step 2: Which component(s) were found below (Nominal WT - Corrosion Allowance)?

Components found below Nom - CA:

Components					
N/A - N/A					
N/A - N/A					
N/A - N/A					
N/A - N/A					
N/A - N/A					

Perform Steps 3 – 8 for each component with actual thickness less than (Nominal WT – Corrosion Allowance).

Step 3: Describe Location and Extent of Corrosion:

Components

Location and Extent of Corrosion

N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection

Notes:

Not Applicable for this Inspection

Step 4:

- For shells and nozzles, calculate minimum required thickness (T-min) as per ASME Section VIII UG-27.
- For heads, calculate minimum required thickness (T-min) as per ASME Section VIII UG-32.

I -IVIIN
N/A



Report #:
Inspect Date:
Page:

Insp. Co. Job #:

156850-MD-02 07/04/2012 7 of 15

156850

Insp. Company: Matrix_Inspection LSD: 10-10-096-12W6 Jurisdiction #: A0492612

Thickness and Remaining Life Evaluation (Continued)

Step 5: Is any measured thickness less than calculated minimum required thickness (T-min)? N/A

If YES, complete Step 6
If NO, proceed to Step 7...

Step 6: Is nature and extent of pitting acceptable as per API 510? N/A

Step 7: Calculate Remaining Life as per API 510. How? (Find last reading; use nominal thickness if nothing available). Short Term Corrosion Rates and Long Term Corrosion Rates.

Components	Remaining Life (Yrs)
N/A - N/A	N/A

Step 8: Contact CNRL Integrity Coordinator to discuss above results.

- Name of CNRL contact: Not Applicable for this Inspection
- Date and time of conversation: Not Applicable for this Inspection

Summary/results of conversation:

Not Applicable for this Inspection

Crack Evaluation by Magnetic Particle or Alternative Inspection "Must be Completed"

MUST BE COMPLETED AND RESOLVED WITH CNRL IMMEDIATELY UPON DISCOVERY OF CRACK-LIKE INDICATIONS

Were any indications found to suggest the vessel contained cracks? N/A

If NO, proceed to "CNRL Criticality Designation".

If YES, Contact CNRL Integrity Coordinator to discuss results.

- Name of CNRL contact: Not Applicable for this Inspection
- Date and time of conversation: Not Applicable for this Inspection

Summary/results of conversation:

Not Applicable for this Inspection



Report #: 156850-MD-02
Inspect Date: 07/04/2012
Page: 8 of 15
Insp. Co. Job #: 156850

Insp. Company: Matrix_Inspection LSD: 10-10-096-12W6 Jurisdiction #: A0492612

CNRL Criticality Evaluation – "MUST BE COMPLETED"

The CNRL In-Service Pressure Vessel Inspector MUST answer all the following questions

- Is the vessel fit-for-service? : Yes
- 2. Was the measured thickness less than the calculated minimum required thickness (T-min) for any component?: **No**
- 3. Were MT indications found?: **N/A**
- 4. Was the remaining life less than 6 years for sour service vessels or less than 10 years for sweet service vessels?: **No**
- 5. Were NCR's or Action Items generated as a result of the inspection? : Yes
- 6. Were UT readings below (Nominal WT Corrosion Allowance) found?: No

Information on CNRL Owner User Program - Criticality Designation and Required Review

RED – Vessel Inspection Results are deemed RED if one of the following occurred:

- The measured thickness was less than the calculated minimum required thickness (T-min) for any component.
- MT indications were found.
- The remaining life was calculated to be less than 6 years for sour-service vessels or less than 10 years for sweet-service vessels.

RED inspection reports must be signed off by the CNRL Chief Inspector.

YELLOW – Vessel Inspection Results are deemed YELLOW if one or more of the following occurred:

- The vessel was declared NOT fit-for-service by the 3rd Party In-Service PV Inspector.
- NCR's or Action Items were generated as a result of the inspection.
- UT readings below (Nominal WT Corrosion Allowance) were found.

YELLOW inspection reports must be signed off by the CNRL Pressure Equipment Integrity Coordinator.

GREEN - Vessel Inspection Results are deemed GREEN if all of the following are true:

- The vessel was declared fit-for-service by the 3rd Party In-Service PV Inspector.
- UT readings below (Nominal WT Corrosion Allowance) were NOT found.
- MT indications were NOT found.
- NCR's or Action Items were NOT generated as a result of the VE inspection.

GREEN inspection reports must be signed off by the 3rd Party In-Service Pressure Vessel Inspector.

Critica	lity Designation	Yellan
Vehicle #:	380 Kms:	Inspector (Name): Matthew B Dickinson PESL: 601
Time In:	00:00 Time Out: 00:00 Hrs	Inspector (Signature): Matthew Dickinson 2012.11.15
Time In:	00:00 Time Out: 00:00 Hrs	CNRL Coordinator (Name):
Personnel:		CNRL Coordinator (Signature):
Billing Info:	AFE :	CNRL Chief Inspector (Signature): (I am in full agreement with report contents)
		(I am in full agreement with report contents)



Report #: 156850-MD-02
Inspect Date: 07/04/2012
Page: 9 of 15
Insp. Co. Job #: 156850

Equipment Photographs:



01 nameplate



02 overview



Report #: 156850-MD-02
Inspect Date: 07/04/2012
Page: 10 of 15
Insp. Co. Job #: 156850



03 manway overview



04 deteriorated caulking seal

Report #: 156850-MD-02
Inspect Date: 07/04/2012
Page: 11 of 15
Insp. Co. Job #: 156850



05 corrosion between flanges



06 surface corrosion



Report #: 156850-MD-02
Inspect Date: 07/04/2012
Page: 12 of 15
Insp. Co. Job #: 156850



07 PSV overview




Report #: 156850-MD-02
Inspect Date: 07/04/2012
Page: 13 of 15
Insp. Co. Job #: 156850

Equipment Photographs:



08 demister pad overview



09 out of position

Report #: 156850-MD-02
Inspect Date: 07/04/2012
Page: 14 of 15
Insp. Co. Job #: 156850



10 flash corrosion



11 flash corrosion on welds

Report #: 156850-MD-02
Inspect Date: 07/04/2012
Page: 15 of 15
Insp. Co. Job #: 156850



12 build-up on baffle