		PR VIS	ESSURE '	VESSEL	Re Inspec	eport #:	156835-MD-01 07/06/2012
Canadian Na	atural	RE	PORT	Lonon	Insp. Co.	Page: Job #:	1 of 14 156835
Criticality Designation:		1	Yellow	<u>//</u>			
Insp. Comp: Matrix Inspe	ection District:	Grande	Prairie - No	rth	Fiel	d: Sout	h Hamburg
Location: 12-29-096-1	1W6 Unit / Skid #:		N/A		LSI	D: 12-29	9-096-11W6
Jurisdiction #: A020138	Equip Tag #:		V-13A		Serial	#: 8	2-609-1
CRN #: E5298.2	2 Nat'l Bd #:		N/A		Year Bui	lt:	1982
Manufacturer: Dacro Industries	E	quipment	Description	: Other: Storage	Tank (bi	ullet)	
Status: In Service - Stan MAWP Shell: 155 Psi	1009 Equ	Ip. Type: Volum	Vessel: Bull	let m ³		Service	
MAWP Tube:	<u>@ 150 1</u> @ Hei	aht/l enat	e. <u> </u>	 Ft.		Insulated	
MDMT: -29 °F	RT: RT-2 Size	/Diameter	r.: 144	in. O.D.		PWHT	
Support Saddle	Vessel on Orig	inal CNRI	Inventory L	ist: 🛛 Y 🗌 N	1	Manway	/: ⊠Y □N
C.A.: 1.6 mm	Coated: No	Clad: No	J	.E.: <u>N/A</u> Re	mote Acc	cess: 🗌	
Component	Material	No	minal Thk	Diameter	OD/ID	Tube Side	Shell Side
1 Main - Shell	SA-516-70	1	.000 in.	144.000 in.	OD		
2 North - Head	SA-516-70	0	.708 in.	144.000 in.	OD		
3 South - Head	SA-516-70	0	.708 in.	144.000 in.	OD		
4 Mid - Shell	SA-516-70	0	0.751 in.	144.000 in.	OD		
Static Data: Confirmed M	Changed (See Commente						
PSV Static Data							
PSV –1 Tag #: <u>N/A</u>	Serial #:	82C372	8		CRN: N	N/A	
Model #: N/A	Capacity:	54048 \$	SCFM	Set Pre	essure: 1	55 psi	
Manufacturer: Consolidate	d Flanged			Service Con	npany: <u>I</u>		
Outlet Size & Type: 8.00 in	- Flanged		F	Last Service Block Valve: N/A		uly 2012	
Carseal Intact: Yes			L	Code S	Stamp: N	/es	
Shell Side / Tube Side: She	ell Side Out for S	Service Du	uring Insp.: _	N Location o	f PSV:	On Vessel	
PSV –2 Tag #:	Serial #:				CRN:		
Model #:	Capacity:			Set Pre	essure:		
Manufacturer:				Service Con	npany: _		
Inlet Size & Type:	-		-	Last Service	e Date: _		
Carseal Intact:	-		Ľ		 Stamn:		
Shell Side / Tube Side:	Out for S	Service Du	urina Insp.:	Location o	f PSV:		
PSV Comments			<u> </u>				



PRESSURE VESSEL VISUAL INSPECTION REPORT

156835-MD-01 07/06/2012 2 of 14

156835

Canadian Natura

40.00.000.4414/0

10001001

Insp. Company: <u>Matrix_Inspection</u>			LSD:12-29-096-11000 Jurisdiction #:A0201361				201301	
External Inspection Results – VE External Inspection Performed								
Item	N/A	Condition	(C	Comment (Check Status Bar or Press F1 for Help)		Action Item Integrity	Action Item Maintenance	
Nameplate		Accept	Firmly affixe	d and legible				
Foundation and Supports	3	Accept	Saddle supp	ports with mesh exposed			\square	
Anchor Bolts		Reject	Loose anche	ors on saddle supports			\square	
Grounding		Accept	Grounded d	irectly to saddle				
Insulation Condition			Bullet is not	insulated				
PSV		Accept	Vents to atm	Vents to atmosphere				
Shell Heads & Nozzles		Accept	Mechanical	damage below the paint 0.032"	deep 🗌			
Metal Surfaces (Paint)		Accept	Weathered of	Weathered exposing the base metal			\square	
Aux Equipment			No aux equi	pment on bullet				
Cathodic Protection			No anode o	n suction bullet				
Alignment		Accept	Aligned in a	North to South direction				
Flange Connections		Reject	Loose hardware on valve to pipe flange				\square	
Pressure Gauge			No pressure	No pressure gauge on bullet				
Temperature Gauge		Accept	-20 - 120 C:	-20 - 120 C: lense is cracked			\square	
Sight Glass			No sight gla	ss on bottle				
Ladder / Platform		Accept	Firmly affixed ladder & cage, secure platform					
Leaks		No	No evidence	No evidence of any previous process leaks				
Piping from Vessel		Accept	Secure and	adequately supported		÷		
Previous UT Survey		Yes	Not marked	performed in 2005	UT Compa	ny: AITEC		

External Visual Observations

The overall condition of the bullet is good.

The coating is weathered and chipping exposing the base metal to minor surface corrosion. The tell-tale holes are open with no evidence of leaks.

There is mechanical damage noted below the paint throughout the bullet head and shells with a maximum measured depth of 0.032"

The saddles and supports are partially fireproofed, exposed for inspections on the anchor bolts There are loose anchor bolts on the saddles There is a loose npt plug on the top of the bullet ball valve

There are loose nuts to stud assembly on the 6" valve to flange connection on the top of the bullet

The temperature gauge sight lense is cracked

The tell tale holes are open with no evidence of leaks present at the time of inspection

A UT corrosion survey was performed at the time of inspection with no significant wall losses noted at the time of inspection

Recommendations:

Clean the vessel and touch up the coating to aid in corrosion protection. Consider replacing the temperature gauge sight lense Ensure the saddle anchors are secure prior to fireproofing Secure npt plug Ensure all flange connections are secure and tight



PRESSURE VESSEL VISUAL INSPECTION REPORT

Jurisdiction #:

156835-MD-01 07/06/2012 3 of 14

156835

any: Matrix Inspection

LSD:

12-29-096-11W6

A0201381

Internal Inspection Results – VI Internal Inspection Performed						
Item	N/A	Condition	Comment (Check Status Bar or Press F1 for Help)	NCR	Action Item Integrity	Action Item Maintenance
Shell		Accept	0.040" pitting in 3 rd shell from the South			
Heads		Accept	Minor surface corrosion throughout			
Manway		Accept	No recordable mechanical/ service damage			
Gasket Surfaces		Accept	Adequate serrated sealing surface			
Welds		Accept	No recordable mechanical/ service damage			
Refractory			Not applicable			
Heating Coils	\square		Not applicable			
Demister Pad			Not applicable			
Vane Pack			Not applicable			
Baffles			Not applicable			
Trays			Not applicable			
Filter			Not applicable			
Internal Coating	\square		Not applicable			
Tubesheet			Not applicable			
Tube Bundle			Not applicable			

Internal Visual Observations

Insp. Company:

The vessel was opened for internal inspections

The internal condition of the vessel wsa not cleaned; therefore, an as found condition inspection was performed

The overall condition of the bullet is good

An MT examination was previously performed prior to TA

The entire internal surface of the bullet has a thin scale film with no significant evidence of mechanical damage or service damage

There is a pit on the 3rd shell from the North head (6 o'clock position) 0.040" deep, 0.75" long by 0.25" wide - acceptable to API 510

Recommendations:

Clean and remove scale film from the bullet

				PRESSUR		1	F	Report #:	156835-MD-01
							Insp	ect Date:	07/06/2012
Conselle		A		REPORT				Page:	4 of 14
Canadia	an N	atural					Insp. C	o. Job #:	156835
Insp. Company: Ma	trix_In	spection	LSD:	12-29-096-11\	N6	Jurisd	iction #:	A02	01381
Firetube Static Data N/A (N	√ot Ap	oplicable)							
Diameter: Not Applicable Nom Thickness: Not Applicable Bend: Not Applicable									
Length: Not Applical	ole		Firetube D	escription: Not Ap	plicable				
	UT Report#: Not Applicable ET Report#: Not Applicable								
Firetube NDE MT Report#: Not Applicable RT Report#: Not Applicable									
r choimed.	ΡT	Repor	rt#: Not Applic	able	Other	Repo	ort#: Not	Applicable	
Firetube Inspection Results									
	, 	1						Action Itom	Action Itom
Item	N/A	Condition	(Che	Comment eck Status Bar or Press I	=1 for Help)		NCR	Integrity	Maintenance
Burner			No Firetube Ir	spection Carried C	Dut				
Stack			No Firetube Ir	nspection Carried C	Dut				
Flange (Throat)			No Firetube Ir	nspection Carried C	Dut				
Tube Sheet	\square		No Firetube Ir	nspection Carried C	Dut				
Hot Side			No Firetube Ir	nspection Carried C	Dut				
Miter			No Firetube Ir	nspection Carried C	Dut				
Return Bend			No Firetube Ir	nspection Carried C	Dut				
Supports			No Firetube Ir	nspection Carried C	Dut				
Butt Welds			No Firetube Ir	spection Carried C	Dut		_ <u> </u>		
Fillet Welds			No Firetube Ir	spection Carried C	Dut				
Firetube Visual Observation	s								
No Firetube Inspection Ca	arried	Out							
Recommendations:									
No Firetube Inspection Ca	arried	Out							

Canadian Natural		PRESSURE VES VISUAL INSPEC ⁻ REPORT	SEL Report # Inspect Date Page Insp. Co. Job #		156835-MD-01 07/06/2012 5 of 14 156835				
Insp. Company: Matrix	Inspection	LSD:	12-29-096-11W6	Juris	diction #:	A0201381			
Vessel NDE and Final Summa	a ry: T⊠ Repor	rt#:	ET	Rep	ort#:				
P	T 🔲 Repor	rt#:	Other		ort#:				
Maxi-Trak Observations Summ	Maxi-Trak Observations Summary (Summarize inspection results Max 255 Characters):								
Loose anchor saddles Loose nut to stud assembly on 6" valve to pipe flange connection on the top of the bullet Coating is weathered Loose npt plug Thin film scale on the internal surface of the shell and heads									
Maxi-Trak Recommendations S	Summary (Sum	ımarize Recom	mendations Max 255 Cha	racters):					
Clean vessel & touch up the Consider replacing the tempe Ensure the saddle anchors an Remove scale film from bulle	Clean vessel & touch up the paint Secure npt plug Consider replacing the temperature gauge sight lense Ensure full thread engagement on all flange connections Ensure the saddle anchors are secure prior to fireproofing Remove scale film from bullet								
Actions Corrected at Time of In	nspection: (If ac	tions were correcte	ed at the time of Inspection – note	the corrected	d actions here.)				
Additional Visual Observations									
No additional visual observations									
Any other safety concerns or ot	oservations fro	m associated e	equipment: (for example a	ssociated	piping, buildings, p	oumps etc)			
1/2 or full face masks recommended for cleaning the bullet									



Insp. Company:

Matrix_Inspection

12-29-096-11W6

Jurisdiction #:

A0201381

156835-MD-01

07/06/2012

6 of 14

156835

Thickness and Remaining Life Evaluation "Must be Completed"

LSD:

MUST BE COMPLETED AND RESOLVED WITH CNRL IMMEDIATELY UPON DISCOVERY OF LOW WALL THICKNESS AREAS

Step 1: Was any thickness measurement location found to be less than (Nominal WT - Corrosion Allowance)?: No

If YES, proceed to Step 2; if NO, proceed to "Crack Evaluation" and "CNRL Criticality Designation".

Step 2: Which component(s) were found below (Nominal WT - Corrosion Allowance)?

Components found below Nom - CA:

Components							
N/A - N/A							
N/A - N/A							
N/A - N/A							
N/A - N/A							
N/A - N/A							

Perform Steps 3 – 8 for each component with actual thickness less than (Nominal WT – Corrosion Allowance).

Step 3: Describe Location and Extent of Corrosion:

Components	Location and Extent of Corrosion
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection

Notes:

Not Applicable for this Inspection

Step 4:

- For shells and nozzles, calculate minimum required thickness (T-min) as per ASME Section VIII UG-27.
- For heads, calculate minimum required thickness (T-min) as per ASME Section VIII UG-32.

Components	T-Min
N/A - N/A	N/A



Insp. Company:

Matrix_Inspection

12-29-096-11W6

Jurisdiction #:

A0201381

156835-MD-01

07/06/2012

7 of 14

156835

Thickness and Remaining Life Evaluation (Continued)

Step 5: Is any measured thickness less than calculated minimum required thickness (T-min)? N/A

LSD:

If YES, complete Step 6 If NO, proceed to Step 7..

Step 6: Is nature and extent of pitting acceptable as per API 510? N/A

Step 7: Calculate Remaining Life as per API 510. How? (Find last reading; use nominal thickness if nothing available). Short Term Corrosion Rates and Long Term Corrosion Rates.

Components	Remaining Life (Yrs)
N/A - N/A	N/A

Step 8: Contact CNRL Integrity Coordinator to discuss above results.

- Name of CNRL contact: Not Applicable for this Inspection
- Date and time of conversation: Not Applicable for this Inspection

Summary/results of conversation: Not Applicable for this Inspection

Crack Evaluation by Magnetic Particle or Alternative Inspection "Must be Completed"

MUST BE COMPLETED AND RESOLVED WITH CNRL IMMEDIATELY UPON DISCOVERY OF CRACK-LIKE INDICATIONS

Were any indications found to suggest the vessel contained cracks? No

If NO, proceed to "CNRL Criticality Designation".

If YES, Contact CNRL Integrity Coordinator to discuss results.

- Name of CNRL contact: Not Applicable for this Inspection
- Date and time of conversation: Not Applicable for this Inspection

Summary/results of conversation: Not Applicable for this Inspection



156835-MD-01 07/06/2012 8 of 14

156835

Insp. Company:

Matrix_Inspection

12-29-096-11W6

Jurisdiction #:

A0201381

CNRL Criticality Evaluation – "MUST BE COMPLETED"

The CNRL In-Service Pressure Vessel Inspector MUST answer all the following questions

LSD:

- 1. Is the vessel fit-for-service? : Yes
- 2. Was the measured thickness less than the calculated minimum required thickness (T-min) for any component?: No
- 3. Were MT indications found?: No
- 4. Was the remaining life less than 6 years for sour service vessels or less than 10 years for sweet service vessels?: No
- 5. Were NCR's or Action Items generated as a result of the inspection? : Yes
- 6. Were UT readings below (Nominal WT Corrosion Allowance) found? : No

Information on CNRL Owner User Program - Criticality Designation and Required Review

RED – Vessel Inspection Results are deemed RED if <u>one</u> of the following occurred:

- The measured thickness was less than the calculated minimum required thickness (T-min) for any component.
- MT indications were found.
- The remaining life was calculated to be less than 6 years for sour-service vessels or less than 10 years for sweet-service vessels.

RED inspection reports must be signed off by the CNRL Chief Inspector.

YELLOW – Vessel Inspection Results are deemed YELLOW if one or more of the following occurred:

- The vessel was declared NOT fit-for-service by the 3rd Party In-Service PV Inspector.
- NCR's or Action Items were generated as a result of the inspection.
- UT readings below (Nominal WT Corrosion Allowance) were found.

YELLOW inspection reports must be signed off by the CNRL Pressure Equipment Integrity Coordinator.

GREEN – Vessel Inspection Results are deemed GREEN if <u>all</u> of the following are true:

- The vessel was declared fit-for-service by the 3rd Party In-Service PV Inspector.
- UT readings below (Nominal WT Corrosion Allowance) were NOT found.
- MT indications were NOT found.
- NCR's or Action Items were NOT generated as a result of the VE inspection.

GREEN inspection reports must be signed off by the 3rd Party In-Service Pressure Vessel Inspector.

Critica	ality Designation	Yellow
Vehicle #:	380 Kms:	Inspector (Name): Matthew B Dickinson PESL: 601
Time In:	00:00 Time Out: 00:00 Hrs	Inspector (Signature): Matthew Dickinson 2012.11.15 16:04:35 - API: 39483
Time In:	00:00 Time Out: 00:00 Hrs	CNRL Coordinator (Name):
Personnel:	DH	CNRL Coordinator (Signature):
Billing Info:	AFE :	(I am in full agreement with report contents)
		(I am in full agreement with report contents)



Equipment Photographs:



01 nameplate



02 overview





03 cracked temperature gauge



04 overview after installation





05 loose anchor bolts



06 exposed fireproofing





07 PSV overview



08 loose npt plug





09 loose hardware



10 manway overview





11 film scale throughout bullet



12 pit