

156960-MD-07 Report #: Inspect Date: 10/16/2012 1 of 14

Page: Insp. Co. Job #: 156960

Criticality Designation	:	Yellow	/				
Insp. Comp: Matrix_Ins	pection District: (	Grande Prairie - Nort	th	Field:	Chi	ncaga	
Location: 01-24-096	-05W6 Unit / Skid #:	N/A		LSD:	01-24-0	096-05W6	
Jurisdiction #: A01468	344 Equip Tag #:	V-301C		Serial #:	79-0	87-05C	
CRN #: D 319			Y	ear Built:	1	979	
Manufacturer: KML Manufact		ipment Description:					
Status: Out of Service		Type: Vessel: Tow			Service:	Sweet	
MAWP Shell: 8619 kPa		Volume: N/A		Co	ode Stamp:	⊠Y □N	
MAWP Tube:	@ Height	t/Length: 8992	mm			$\square$ Y $\boxtimes$ N	
MDMT: -20 °F	RT: RT-1 Size/Di	iameter.: 1677 ı	mr I.D.		PWHT:	$\boxtimes$ Y $\square$ N	
Support Skirt	Vessel on Origina	al CNRL Inventory Lis	st: X Y N		Manway:	$\boxtimes$ Y $\square$ N	
C.A.: 0.063 in	. Coated: N/A Cla	ad: <u>N/A</u> J.E	E.: <u>1.00</u> Remo	ote Acces	s: 🗌		
Component	Material	Nominal Thk	Diameter (	OD/ID	Tube Side	Shell Side	
1 Main - Shell	SA-516-70	88.500 mm	1677.000 mm	ID		$\boxtimes$	
2 Top - Head	SA-516-70	69.270 mm	1677.000 mm	ID		$\boxtimes$	
3 Bottom - Head	SA-516-70	69.270 mm	1677.000 mm	ID		$\boxtimes$	
4 -							
5 -							
Static Data: Confirmed 🖂	Changed (See Comments)	7	"				
Comments: Static data confirmed	Comments:						
PSV Static Data							
PSV -1 Tag #: N/A	Serial #: N	I/A		RN: N/A			
Model #: N/A	Capacity: N		Set Press				
Manufacturer: N/A			Service Comp				
Inlet Size & Type:	-		Last Service D	·			
Outlet Size & Type:		B	lock Valve: -				
Carseal Intact: N/A		٥,	Code Sta				
Shell Side / Tube Side:	Out for Ser	vice During Insp.:	Location of F			<u> </u>	
PSV –2 Tag #:	Serial #:			RN:			
Model #:	Capacity:		 Set Press	-			
Manufacturer:	Capacity		Service Comp				
			Last Service D				
Inlet Size & Type:	<u> </u>	D		Date.			
Outlet Size & Type:	<del>-</del>	D	lock Valve: -	<u>-</u>			
Carseal Intact:		des Budes less.	Code Sta				
Shell Side / Tube Side:	Out for Ser	vice During Insp.:	Location of F	75V:			
PSV Comments							
Not applicable							



Report #: 156960-MD-07
Inspect Date: 10/16/2012
Page: 2 of 14
Insp. Co. Job #: 156960

Insp. Company:	Matrix_Ir	nspection	LSD:	01-24-096-05W6	Jurisdict	tion #:	A01	46844	_
External Inspection Results – VE External Inspection Performed									
Item	N/A	Condition	(C	Comment heck Status Bar or Press F1 for Help)		NCR	Action Item Integrity	Action Item Maintenance	
Nameplate		Accept	Legible and	firmly affixed to North side					
Foundation and Suppo	rts	Accept	Welded skir	t anchored to skid					
Anchor Bolts		Accept	Secure with	minor surface corrosion					
Grounding		Accept	Grounded d	irectly to South side of skirt					
Insulation Condition		Reject	Piping clade	ling damaged and punctured				$\boxtimes$	
PSV	$\boxtimes$		Not applicat	ole					
Shell Heads & Nozzles		Accept	Minor surface	ce corrosion through out					
Metal Surfaces (Paint)		Accept	Chipped and	d flaking exposing base metal				$\boxtimes$	
Aux Equipment	$\boxtimes$		Not applicat	ole					
Cathodic Protection	$\boxtimes$		No external	anode					
Alignment		Accept	Vertical and	upright					
Flange Connections		Accept	Adequate th	read engagement and hardware	Э				
Pressure Gauge	$\boxtimes$		No pressure	gauge					
Temperature Gauge		Reject	Multiple gau	iges, 2 not within range				$\boxtimes$	
Sight Glass	$\boxtimes$		No sight gla	ss					
Ladder / Platform		Accept	Mechanical	damage on West top platform s	upport				
Leaks		No	No evidence	e of leaks					
Piping from Vessel		Accept	Riser saddle	e and lug supports for associate	d piping				
Previous UT Survey		Yes	Locations m	arked, no history provided	UT Co	ompany	y: N/A		
External Visual Observations									
At the time of inspection the dehydrator was not in service and the vessel is tagged out of service  The coating is flaking and chipped throughout exposing the base metal to minor surface corrosion with no evidence of pitting.									

There are two 24" manways on the vessel. The East side manway, hardware and davit arm are in acceptable condition The top head davit arm and pin have been removed

The two 0-300 C temperature gauges are not within design temp range and the 0-500 C gauge needle is at the 500 C mark

All platforms and ladders are secure with well supported cages on the ladder

There is moss growth on the top 8" inlet elbow cladding interface that may result in MIC

The outlet piping has a small section of cladding/insulation removed, the insulation is exposed, discolored and deteriorating which may result in CUI to the piping system

The top platform support beam is bent on the West side

There is mechanical damage noted thru out the surfaces on the shells

There is also mechanical damage on the top head below the paint

A UT corrosion survey was performed at the time of inspection with no significant wall losses recorded.

#### Recommendations:

Remove/ replace insulation on piping

Remove moss and treat area

Consider replacing temp gauges if temp is expected to exceed 300 C

Clean and touch up the coating to aid in the protection against corrosion

If this vessel is to be moved and/or placed into service the lifting lugs and top nozzle should be MT examined as well as ABSA document AB-10 completed



Report #: Inspect Date:

**156960-MD-07** 10/16/2012 3 of 14

Page: 3 of 14 Insp. Co. Job #: 156960

	Insp. Company: Ma	trix_In	spection	LSD:	01-24-096-05W6	Jurisdiction #:	A01	46844	_
Ī	nternal Inspection Results	– VI I	N/A (Not Ap	plicable)					_
	Item	N/A			Comment ock Status Bar or Press F1 for Help)	NCR	Action Item Integrity	Action Item Maintenance	
	Shell				spection Carried Out				1
	Heads				spection Carried Out				1
	Manway				spection Carried Out				1
	Gasket Surfaces				spection Carried Out				
	Welds				spection Carried Out				1
	Refractory				spection Carried Out				1
	Heating Coils				spection Carried Out				
	Demister Pad				spection Carried Out				1
	Vane Pack	$\boxtimes$			spection Carried Out				1
	Baffles	$\boxtimes$			spection Carried Out				7
	Trays	$\boxtimes$			spection Carried Out				7
	Filter	$\boxtimes$			spection Carried Out				
	Internal Coating	$\boxtimes$			spection Carried Out				7
	Tubesheet				spection Carried Out				1
	Tube Bundle	$\boxtimes$			spection Carried Out				1
Ir	nternal Visual Observations	}				·			
Ē	No Internal Inspection Ca		\4						_
	No internal inspection cal	illea c	Jul						
_	ecommendations:								
	No Internal Inspection Ca	rriea (	Jut						
1									



Report #: **156960-MD-07**Inspect Date: 10/16/2012
Page: 4 of 14

Insp. Co. Job #: 156960 Matrix\_Inspection 01-24-096-05W6 A0146844 LSD: Jurisdiction #: Insp. Company: Firetube Static Data N/A (Not Applicable) Diameter: Not Applicable Nom Thickness: Not Applicable Bend: Not Applicable Length: Not Applicable Firetube Description: Not Applicable UT 🔲 Report#: Not Applicable ET 🗌 Report#: Not Applicable Firetube NDE MT  $\square$ RT 🗌 Report#: Not Applicable Report#: Not Applicable Performed: PT 🗌 Report#: Not Applicable Other Report#: Not Applicable Firetube Inspection Results Action Item Action Item Comment N/A Condition **NCR** Item (Check Status Bar or Press F1 for Help) Integrity Maintenance  $\boxtimes$ No Firetube Inspection Carried Out Burner  $\boxtimes$ Stack No Firetube Inspection Carried Out Flange (Throat)  $\boxtimes$ No Firetube Inspection Carried Out Ш Ш **Tube Sheet**  $\boxtimes$ No Firetube Inspection Carried Out П П Hot Side  $\boxtimes$ No Firetube Inspection Carried Out Miter  $\boxtimes$ No Firetube Inspection Carried Out Return Bend  $\boxtimes$ No Firetube Inspection Carried Out П  $\boxtimes$ Supports No Firetube Inspection Carried Out П **Butt Welds**  $\boxtimes$ No Firetube Inspection Carried Out  $\boxtimes$ Fillet Welds No Firetube Inspection Carried Out Firetube Visual Observations No Firetube Inspection Carried Out Recommendations: No Firetube Inspection Carried Out



Report #: **156960-MD-07**Inspect Date: 10/16/2012
Page: 5 of 14

Insp. Co. Job #: 156960 Matrix Inspection 01-24-096-05W6 A0146844 Insp. Company: LSD: Jurisdiction #: **Vessel NDE and Final Summary:** UT 🛛 Report#: ET 🗌 Report#: RT 🗌 NDE Performed:  $\mathsf{MT} \square$ Report#: Report#: PT 🗌 Report#: Other Report#: Maxi-Trak Observations Summary (Summarize inspection results Max 255 Characters): Coating deteriorated exposing base metal to surface corrosion Damaged insulation on piping 2 temperature gauges not within range Moss growth on top 8" elbow at the cladding interface Maxi-Trak Recommendations Summary (Summarize Recommendations Max 255 Characters): Remove/ replace insulation on piping Remove moss and treat area Consider replacing temp gauges if temp is expected to exceed 300 C Clean and touch up the coating to aid in the protection against corrosion Actions Corrected at Time of Inspection: (If actions were corrected at the time of Inspection - note the corrected actions here.) No actions were corrected at the time of inspection Additional Visual Observations No additional visual observations Any other safety concerns or observations from associated equipment: (for example associated piping, buildings, pumps etc...) No safety concerns noted at the time of inspection



Report #: Inspect Date: 156960-MD-07 10/16/2012 6 of 14

156960

Page: Insp. Co. Job #:

Insp. Company: Matrix\_Inspection

LSD: 01-24-096-05W6

Jurisdiction #:

A0146844

### Thickness and Remaining Life Evaluation

## " Must be Completed"

## MUST BE COMPLETED AND RESOLVED WITH CNRL IMMEDIATELY UPON DISCOVERY OF LOW WALL THICKNESS AREAS

Step 1: Was any thickness measurement location found to be less than (Nominal WT - Corrosion Allowance)?: No

If YES, proceed to Step 2; if NO, proceed to "Crack Evaluation" and "CNRL Criticality Designation".

Step 2: Which component(s) were found below (Nominal WT - Corrosion Allowance)?

Components found below Nom - CA:

Components			
Top - Head			
- Shell			
Bottom - Head			
Bottom - Drain Nozzle			
N/A - N/A			

Perform Steps 3 – 8 for each component with actual thickness less than (Nominal WT – Corrosion Allowance).

Step 3: Describe Location and Extent of Corrosion:

Components

**Location and Extent of Corrosion** 

N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection
N/A - N/A	Not Applicable for this Inspection

#### Notes

Circumferential stress used for nozzles

#### Step 4:

- For shells and nozzles, calculate minimum required thickness (T-min) as per ASME Section VIII UG-27.
- For heads, calculate minimum required thickness (T-min) as per ASME Section VIII UG-32.

Components	T-Min
Top - Head	2.374
- Shell	1.162
Bottom - Head	2.374
Bottom - Drain Nozzle	0.302
N/A - N/A	N/A



01-24-096-05W6

Report #: Inspect Date: 156960-MD-07 10/16/2012 7 of 14

A0146844

Jurisdiction #:

Page: Insp. Co. Job #: 156960

Thickness and Remaining Life Evaluation (Continued)

Matrix\_Inspection

Step 5: Is any measured thickness less than calculated minimum required thickness (T-min)? N/A

LSD:

If YES, complete Step 6 If NO, proceed to Step 7..

Insp. Company:

Step 6: Is nature and extent of pitting acceptable as per API 510? N/A

Step 7: Calculate Remaining Life as per API 510. How? (Find last reading; use nominal thickness if nothing available). Short Term Corrosion Rates and Long Term Corrosion Rates.

Components	Remaining Life (Yrs)
Top - Head	99
- Shell	99
Bottom - Head	99
Bottom - Drain Nozzle	99
N/A - N/A	N/A

Step 8: Contact CNRL Integrity Coordinator to discuss above results.

- Name of CNRL contact: Not Applicable for this Inspection
- Date and time of conversation: Not Applicable for this Inspection

Summary/results of conversation: Not Applicable for this Inspection

#### " Must be Completed" Crack Evaluation by Magnetic Particle or Alternative Inspection

#### MUST BE COMPLETED AND RESOLVED WITH CNRL IMMEDIATELY UPON DISCOVERY OF CRACK-LIKE INDICATIONS

Were any indications found to suggest the vessel contained cracks? **N/A** 

If NO, proceed to "CNRL Criticality Designation".

If YES, Contact CNRL Integrity Coordinator to discuss results.

- Name of CNRL contact: Not Applicable for this Inspection
- Date and time of conversation: Not Applicable for this Inspection

Summary/results of conversation:

Not Applicable for this Inspection



Report #: Inspect Date: 156960-MD-07 10/16/2012 8 of 14

Page: 8 of 14 Insp. Co. Job #: 156960

Insp. Company: Matrix\_Inspection LSD: 01-24-096-05W6 Jurisdiction #: A0146844

## CNRL Criticality Evaluation – "MUST BE COMPLETED"

The CNRL In-Service Pressure Vessel Inspector MUST answer all the following questions

- 1. Is the vessel fit-for-service?: Yes
- 2. Was the measured thickness less than the calculated minimum required thickness (T-min) for any component?: No
- 3. Were MT indications found?: **N/A**
- 4. Was the remaining life less than 6 years for sour service vessels or less than 10 years for sweet service vessels?: **No**
- 5. Were NCR's or Action Items generated as a result of the inspection? : Yes
- 6. Were UT readings below (Nominal WT Corrosion Allowance) found? : No

#### Information on CNRL Owner User Program - Criticality Designation and Required Review

RED – Vessel Inspection Results are deemed RED if one of the following occurred:

- The measured thickness was less than the calculated minimum required thickness (T-min) for any component.
- MT indications were found.
- The remaining life was calculated to be less than 6 years for sour-service vessels or less than 10 years for sweet-service vessels.

RED inspection reports must be signed off by the CNRL Chief Inspector.

YELLOW - Vessel Inspection Results are deemed YELLOW if one or more of the following occurred:

- The vessel was declared NOT fit-for-service by the 3<sup>rd</sup> Party In-Service PV Inspector.
- NCR's or Action Items were generated as a result of the inspection.
- UT readings below (Nominal WT Corrosion Allowance) were found.

YELLOW inspection reports must be signed off by the CNRL Pressure Equipment Integrity Coordinator.

GREEN - Vessel Inspection Results are deemed GREEN if all of the following are true:

- The vessel was declared fit-for-service by the 3<sup>rd</sup> Party In-Service PV Inspector.
- UT readings below (Nominal WT Corrosion Allowance) were NOT found.
- MT indications were NOT found.
- NCR's or Action Items were NOT generated as a result of the VE inspection.

GREEN inspection reports must be signed off by the 3<sup>rd</sup> Party In-Service Pressure Vessel Inspector.

Critica	lity Designation	Yellow	
Vehicle #:	380 Kms:	Inspector (Name): Matthew B	Dickinson PESL: 601
Time In:	00:00 Time Out: 00:00 Hrs	Inspector (Signature):	API: 39483
Time In:	00:00 Time Out: 00:00 Hrs	CNRL Coordinator (Name):	
Personnel:		CNRL Coordinator (Signature):	Coordinate Signature
Billing Info:	AFE :	CNRL Chief Inspector (Signature):	(I am in full agreement with report contents)
			(I am in full agreement with report contents)



Report #: 156960-MD-07
Inspect Date: 10/16/2012
Page: 9 of 14
Insp. Co. Job #: 156960

### **Equipment Photographs:**



01 nameplate



02 overview

Report #: 156960-MD-07
Inspect Date: 10/16/2012
Page: 10 of 14
Insp. Co. Job #: 156960



03 paint deterioration



04 not within range

Report #: 156960-MD-07
Inspect Date: 10/16/2012
Page: 11 of 14
Insp. Co. Job #: 156960



05 surface corrosion



06 damaged cladding

Report #: 156960-MD-07
Inspect Date: 10/16/2012
Page: 12 of 14
Insp. Co. Job #: 156960



07 mechanical damage



08 bent platform support

Report #: 156960-MD-07
Inspect Date: 10/16/2012
Page: 13 of 14
Insp. Co. Job #: 156960



09 surface corrosion



10 damaged cladding

Report #: 156960-MD-07
Inspect Date: 10/16/2012
Page: 14 of 14
Insp. Co. Job #: 156960



11 moss growth



12 punctured cladding