



Mountain West Services Ltd.

## Inspection Report - CNRL # 7125

[\[www.mtnwest.ca\]](http://www.mtnwest.ca) [\[Company Index Page\]](#) [\[Vessels\]](#) [\[Pipelines\]](#) [\[SMART\]](#) [\[Incidents\]](#) [\[Work Orders\]](#) [\[Management of Change\]](#)

### 244015- LINE HEATER

#### UT External

<b>Province:</b>	Alberta	<b>Manway:</b>	NO
<b>District:</b>	GPOU	<b>Coating:</b>	No
<b>Location:</b>	MONTNEY	<b>Inspect Date:</b>	10/27/2006
<b>LSD:</b>	13-19-073-10W6	<b>Inspection Interval:</b>	48
<b>CRN:</b>		<b>Next Inspection:</b>	10/27/2010
<b>Skid/Equipment Number:</b>	SKID0252	<b>MAWP:</b>	10 PSI 68.948 KPa
<b>Service:</b>		<b>Temperature:</b>	1500 F 815.56 C
<b>Status:</b>	In Service	<b>Outstanding NCRs:</b>	0

#### General:

2006 Ultrasonic Corrosion Survey.

#### Safety Valves:

<b>Status:</b> In Service	<b>Examination Methods:</b> UT	<b>Access:</b> External	<b>Cleaning:</b> Good
---------------------------	--------------------------------	-------------------------	-----------------------

#### External:

Refer to 2006 VT External inspection report as part of this thorough inspection.

#### Internal:

The line heater tube bundle nozzles were UT inspected for wall loss.

Hunt Inspections's Ultrasonic Corrosion Survey Project #C10093, as reported on Drawing #177, noted all nozzle thickness readings to be above ASME B31.3 code requirements at time of inspection. The calculated retirement date is 2026 with a program maximum of 20 years.

The associated piping was also inspected.

Caution was generated on 3" piping TML 177-05. Calculations indicate the area is well above minimum required thickness for design conditions.

Nominal thickness of the 3" piping = .438". T-min = .2545". Lows of .337" were recorded within the

TML.

Caution was generated on nozzle TML 177-40. Wall loss showing here. Calculations indicate the area is well above minimum required thickness for design conditions. Nominal thickness of the 3" nozzle = .300". T-min = .1265". Lows of .237" were recorded within the TML.

Cautions were generated on piping TML's 177-25 and 177-45. Calculations indicate the areas are well above minimum required thickness for design conditions. The elbows appear to be at the low end of the 12.5% allowable mill undertolerance.

Next inspection is 4 years or 1/2 remaining life, whichever is less.

**Recommendations:**

Recommend 4 year interval for next UT inspection.

Ultrasonic Corrosion Survey due again in 2010. Calculate STCR and LTCR corrosion rates at that time to determine retirement dates.

**Inspector's Declaration:** I have witnessed the above inspections and certify that they have been done in accordance with our manual and that the information is accurate. I certify that the status of the pressure equipment detailed here is:

**Suitable to be returned to service:** Yes

**Repairs complete:** N/A

**Repairs are still required:** No

**Suggested Inspection Interval:** 48

**Inspector:** Duane Paetkau Cert #000087 **Date:** 3/13/2007

**Chief Inspector:** I certify that the information on this report is true and that all inspections required by the Owner/User Quality Assurance Program# AQP-8047 which expires in 12/06/05 have been done.

**Chief Inspector:** Jim Damiani Cert 00037  
**Date:** 3/28/2007

[\[Back To Start Page\]](#) [\[MtnWest.Ca\]](#)