





A2791337_Nameplate_09JUn09



A2791337_Sump_09Jun09



A2791337_Manway_09Jun09



A2791337_Internal_09Jun09



A2791337_Welds_09Jun09



A2791337_External condition of vessel and sump section_20May09



A2791337_vessel external condition_20May09