

MAGNETIC PARTICLE EXAMINATION REPORT

Customer: CNRL						Rpt. N	Rpt. No.: MT- 002		
Location: EAST WATTS, 04-09-31-16W4						Job #	545		
Examination of: FIRETUBE POST REPAIR						Date:	SEP	T 26, 200)8
Part/Seri	al Number:	A02	228209			P.O.:			
Acceptance Standard: ASME VIII – DIV 1 APPENDIX 6						Page:	1	of _	1
Examina	tion Standa	rd: ASN	MEV ART.7						
	∑ Yoke	AND MA	ATERIALS C DC	Base Meta		Residual	Blast	Amps:	5 7 5
BLACK :	0		NA	Mod		Seria		NA	5.75
INDICA'			Magnaflux	— Mod Mod	-		l No.:	07H09	K
	NATION RE		- Inglimituri		7111		111000	0.110	
SCOPE: TO PERFORM A BLACK AND WHITE MAGNETIC PARTICLE INSPECTION ON ALL REPAIRED AREAS ON THE LEFT AND RIGHT FIRETUBE. THE RIGHT FIRE TUBE HAD ONE AREA ON THE CIRC WELD, AND TEN AREAS OF CORROSION RUNNING ALONG THE EXHAUST TUBE AT THE 9:00 POSITION. THE LEFT FIRETUBE HAD TWO AREAS ON THE CIRC WELDS, AND EIGHT AREAS OF CORROSION RUNNING ALONG THE EXHAUST TUBE AT THE 9:00 POSITION. FINDINGS: NO RELEVANT INDICATIONS FOUND DURING TIME OF INSPECTION RESULTS: THE ABOVE MENTIONED ITEMS WERE FOUND TO CONTAIN NO RELEVANT INDICATIONS AND IS ACCEPTABLE TO BE BEGIN WELD BUILD UP.									
INTERPRET ABILITY. Technicia	PECTION PERF ATION IS DONE	☐ MT2 W ORMED PRIC IN ACCORD	RY VISIBLE FMP DR TO MAGNETIC ANCE WITH THE CGSB/ASNT	PARTICLE E ABOVE MEN	FIONED STANDA	ARDS, TO THE BE		PROFESSIO	
Ass't:									
					Reg. #:				
			OFESSIONAL OPIN M IN FULL AGREE			ON IS THE RESPO	NSIBILIT	Y OF THE	
Customer	representative	•			TD*	Date:	SEPT 2	26 2008	
Total Hour	es: S.	т. (O.T. Tin	ne In:	Time Out:	KM.	Sub	os.	
Consumab		White Co	ntrast Paint x1, l	Black Magn	etic Particle				