



A0227873\_Name Plate\_06Jun07



## VESSEL INSPECTION SUMMARY

Client:	CNRL District:	Medicine Hat - West	Field:	09-17-11-16W4		
Facility:				09-17-11-16W4		
	.0227873 Equip Tag #:			LM-2191		
CRN #:	H0330.2 Nat'l Bd #:		Year Built:	1987		
Manufacturer: Natco		ipment Description: Horizo				
Status: Out Of Service Date Removed From Service: Service: Sour MAWP Shell 75 Psi @ 200 °F Height/Length: 360 in. Code Stamp: X Y X N						
MAWP Shell 75	Psi @ 200 °F Heigh	t/Length: 360	in. (	Code Stamp: X Y N		
MAWP Tube		Diameter: 96 in.	I.D.	Insulated: ⊠ Y ☐ N		
Support Type: Sa		Volume:	ft <sup>3</sup> / m <sup>3</sup>	PWHT: □ Y ⊠ N		
C.A. 1.6	<del></del>			Manway: ⊠ Y □ N		
	Material Nominal Minimum	Component	Material	Nominal Minimum		
	SA-516-70 12.7 mm					
	SA-516-70 18.0 mm					
South Head	SA-516-70 14.3 mm					
PSV Static Data						
PSV –1 Tag #:	Serial #:		CRN:			
Model #:	Capacity:	SCFM	_	Select		
Manufacturer:			ervice Company:			
Shell/Tube Side: She	all / Tubo		Service Date:			
Size In:	Size Out:		Connection Type:			
	es / No Number of PSV's		7 1	No Access Scaff. Req.		
				No Access Scall, Neq.		
	Serial #:		CRN: _			
Model #:	Capacity:	SCFM	Set Pressure: _	Select		
Manufacturer:		Sei	rvice Company: _			
Shell/Tube Shell	I / Tube		Service Date: _			
Size In:	Size Out:	Co	onnection Type: _			
Carseal Intact: Yes	s / No Number of PSV's		Location:			
External Inspection Results	s - VE 🕅					
Last Report #:	Last Report Da	ate.	Summar	y Report #:		
·						
Item Y N		Item Y		Comment		
Foundation 🛛 🗆		Paint 🛛				
Grounding 🛛 🗆		Cathodic Protection				
Insulation 🗵 🗆		Fireproofing				
Piping 🛛 🗆		Ladders/Platforms				
Supports 🛛 🗆		Berms				
Anchor Bolting 🛛 🗆		Davit Arm				
TMLs ⊠ □		Pressure Gauge				
		Temp. Gauge				
Internal Inspection Results	- VI 🖂					
		II	N. N. A.	0		
Item Y N		Item Y	N N/A Acc	Comment		
Shell 🗵 🗆		Demister				
Heads 🛛 🗆		Vane Pack				
Manway 🛛 🗆		Baffles 🖂				
Gasket Surfaces 🗵 🗆		Trays 🖂				
Welds 🛛 🗆		Filter				
Refractory		Internal Coating				
Heating Coils 🛛 🗆		Tubesheet				
Refractory		Tube Bundle				
<u> </u>						

Edmonton	(780) 437-4747	Fort McMurray	(780) 743-1536	Cold Lake	(780) 594-1114	Mailing Address
Calgary	(403) 279-6121	Grande Prairie	(780) 532-2283	Red Deer	(403) 347-1742	5311 – 86 Street
Nisku	(780) 955-7616	High Level	(780) 841-0470	Tulsa, OK	(918) 446-8773	Edmonton, Alberta
Barrhead	(780) 674-3018	Lloydminster	(780) 875-6455	Houston, TX	(281) 476-4444	T6E 5T8



## **VESSEL INSPECTION** SUMMARY


Report #: 127020-WF-07 Report Date: 06/07/2007 Page: of 2 IRISNDT #: 127020

Client:	CNRL	LSD:	09-17-11-1	6W4	Jurisdiction #:	A0227873	
Additional Attachment	s ⊠ # of pages _	7		to Vessel Insp	pection Report # 127	7020-WF-07	
	MT PT	ET [	RT 🗌 OTH	ER 🗌			
NDE Report # NCR Raised □ Op	erational Action Item	Daisad   D	anair Action Itam	Daisad 🗆	Deferred Action Item	Doised	
		Raised L Re	epair Action Item	Raised 🔲	Deferred Action Item	n Raised 🔲	
An internal/externa		s carried out on	Group Free Wate	er KO and the	findings are as follow	/S:	
<ul><li>The vessel was</li><li>The sight glasse</li><li>An external UT</li></ul>	al insulation on the sein good condition with s, temperature and p survey was performed V scaffold required.	n the paint intact ressure gauges	on all areas with were in good cor	out insulation. Idition.	good condition.		
<ul><li>east manways. The</li><li>The corrugated of</li></ul>	se areas were recoat	ed. acked with proce	ess sludge. The b	undles have a	ing breaks on the bot lso fallen slightly out condition.		
Recommendations:							
	iffuser bundles at the	next shutdown	to align them prop	perly.			
·			<b>.</b>	·			
Unit #228	<del></del>		onsumables:	Inspector: Wes Farquh	ar	PESL:	
<u></u>	Out Hrs _ Out Hrs				(Print)	API: 29669	_
	Out 1113 _			I am in full agre	(Signature) ement with report contents		
				l			
		•	743-1536 532-2283	Cold Lake Red Deer	(780) 594-1114 (403) 347-1742	Mailing Address 5311 – 86 Street	



## CORROSION **INSPECTION SERVICES**

Page







A0227873\_Corrugated Diffuser Bundles Fallen Out Of Alignment\_06Jun07





A0227873\_Free Water K.O\_06Jun07

5442 – 56 Avenue SE, Calgary, Alberta, T2C 4M6 Phone: (403) 279-6121 Fax: (403) 236-0716

Edmonton (780) 437-2022 Lloydminster (780) 875-6455 Barrhead (780) 674-3018





A0227873\_Internal View North side\_06Jun07





A0227873\_Pitting North Manway\_06Jun07

5442 – 56 Avenue SE, Calgary, Alberta, T2C 4M6 Phone: (403) 279-6121 Fax: (403) 236-0716

Edmonton (780) 437-2022 Lloydminster (780) 875-6455 Barrhead (780) 674-3018





A0227873\_Pitting South West Manway\_06Jun07