



Part 1 – Facility and Equipment Information

Facility / Field Name: North Cecil (1450)

Location:

Part 2 - Assessment Type

Interval assessment has been performed as per TC-OVR-PRO-INT-000036 – check applicable box

Individual Equipment:

Provide the equipment number:

Multiple Equipment:

Provide the equipment numbers or refer to Section 4 for the file location:

Like Service Comparison:

Provide the equipment numbers or refer to Section 4 for the file location:

Part 3 – Summary of Findings / Issues / Action Items

Move PE equipment inspection intervals on select equipment from 36 to 60 months. 13 inspections required as per overdue equipment.

PSV intervals moved back from 72 months to 60 months.. Service Due PSV's as per assessment in 2024.

Part 4 – Inspection Interval

Previous Interval: 36 Months

New Interval: 60 Months

Assessment Spreadsheet File or Form Location: R:\Integrity\GP North\CECIL NORTH (1450)\1060 Vessel Integrity\03 Risk Management\04 Interval Revisions

Note: If the assigned inspection interval is not the same for all equipment being assessed, the interval may be identified on the assessment Form or Spreadsheet.

Part 5 – Approvals / Rejection

Date:

Final Approval: Asset Integrity

Name: Jerry Zaderey

Cert. #: PESL# 225

Comments: Completed above summary of findings/Issues/Action Items in 2024

Accept  
 Reject

Signature

Final Approval: Operations (Foreman level or above)

Name: Dan Wiebe

Position: Foreman

Comments:

Accept  
 Reject

Signature

Note: Excursion of the typical plant or field operating /production conditions (temperature, pressure, equipment failure) requires an Asset Integrity review of the original inspection interval assessment to confirm that the assigned inspection interval is still valid.











ID	COOL NORTH 1482	16-04-084-0764 PLANT	2760-11	KS27.2	Plant	PLATE EXCHANGER	EXCHANGER	N	1987	VULCAN	N SERVICE	200			02/16/2021	7/10/2018	VE, UT	VE, UT	Insensitive	VE - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	N/A	7%	N/A	0.00089415	140.388347	20	YES	100%	NO	None	2018	UT - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	YES	72	72	60	2018	2024	None	U34 not found. Open action item. Recommended to inspect and repair piping. 2023 UT of UT inspectors show no concerns. Maintain current interval.	Risk Duetime (SAR)	Decrease inspection interval to 60 months.
2760-11	COOL NORTH 1482	16-04-084-0764 PLANT	2760-11	KS27.2	Plant	PLATE EXCHANGER	EXCHANGER	N	1987	VULCAN	N SERVICE	200			02/16/2021	7/10/2018	VE, UT	VE, UT	Insensitive	VE - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	N/A	7%	N/A	0.00089415	140.388347	20	YES	100%	NO	None	2018	UT - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	YES	72	72	60 <td>2018</td> <td>2024</td> <td>None</td> <td>U34 not found. Open action item. Recommended to inspect and repair piping. 2023 UT of UT inspectors show no concerns. Maintain current interval.</td> <td>Risk Duetime (SAR)</td> <td>Decrease inspection interval to 60 months.</td>	2018	2024	None	U34 not found. Open action item. Recommended to inspect and repair piping. 2023 UT of UT inspectors show no concerns. Maintain current interval.	Risk Duetime (SAR)	Decrease inspection interval to 60 months.
2760-11	COOL NORTH 1482	16-04-084-0764 PLANT	2760-11	KS27.2	Plant	PLATE EXCHANGER	EXCHANGER	N	1987	VULCAN	N SERVICE	200			02/16/2021	7/10/2018	VE, UT	VE, UT	Insensitive	VE - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	N/A	7%	N/A	0.00089415	140.388347	20	YES	100%	NO	None	2018	UT - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	YES	72	72	60 <td>2018</td> <td>2024</td> <td>None</td> <td>U34 not found. Open action item. Recommended to inspect and repair piping. 2023 UT of UT inspectors show no concerns. Maintain current interval.</td> <td>Risk Duetime (SAR)</td> <td>Decrease inspection interval to 60 months.</td>	2018	2024	None	U34 not found. Open action item. Recommended to inspect and repair piping. 2023 UT of UT inspectors show no concerns. Maintain current interval.	Risk Duetime (SAR)	Decrease inspection interval to 60 months.
AK01941	COOL NORTH 1482	16-04-084-0764 PLANT	6138-21	MS02.2	Plant	AMINE STRIPPERS AND BELLOWS ACCUMULATOR	ACCUMULATOR	Y	1988	FREEDON MANUFACTURING LTD.	N SERVICE	75			02/16/2021	7/10/2018	VE, UT	VE, UT, W	Insensitive	VE - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	0.2068	7%	20-Shell	0.00817429	17.70233554	50	YES	100%	NO	None	2018	UT - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	YES	72	72	60 <td>2018</td> <td>2024</td> <td>None</td> <td>Open action item. Recommended to inspect and repair piping. 2023 UT of UT inspectors show no concerns. Maintain current interval.</td> <td>Risk Duetime (SAR)</td> <td>Decrease inspection interval to 60 months.</td>	2018	2024	None	Open action item. Recommended to inspect and repair piping. 2023 UT of UT inspectors show no concerns. Maintain current interval.	Risk Duetime (SAR)	Decrease inspection interval to 60 months.
AK02750	COOL NORTH 1482	16-04-084-0764 PLANT	6138-27	MS02.2	Plant	AMINE FINE PARTICULATE FILTERS	FILTERS	N	1987	FREEDON MANUFACTURING LTD.	N SERVICE	200			02/16/2021	7/10/2018	VE, UT	VE, UT, W	Insensitive	VE - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	0.0226	7%	15-Head	0.05443751	90.31082025	20	YES	100%	NO	None	2018	VE - Minor leak found on top head cover. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	YES	72	72	60 <td>2018</td> <td>2024</td> <td>None</td> <td>Open action item. Recommended to inspect and repair piping. 2023 UT of UT inspectors show no concerns. Maintain current interval.</td> <td>Risk Duetime (SAR)</td> <td>Decrease inspection interval to 60 months.</td>	2018	2024	None	Open action item. Recommended to inspect and repair piping. 2023 UT of UT inspectors show no concerns. Maintain current interval.	Risk Duetime (SAR)	Decrease inspection interval to 60 months.
AK04850	COOL NORTH 1482	16-04-084-0764 PLANT	6138-26	MS02.2	Plant	AMINE CHANNEL FILTERS	FILTERS	N	1988	FREEDON MANUFACTURING LTD.	N SERVICE	200			02/16/2021	7/10/2018	VE, UT	VE, UT, W	Insensitive	VE - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	0.0226	7%	05-Shell	N/A	N/A	N/A	YES	100%	NO	None	2018	UT - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	YES	72	72	60 <td>2018</td> <td>2024</td> <td>None</td> <td>Manufacturers in 47 report 23 hours Manufacturing Effluent from Maximal 23 hours Manufacturing Effluent. 2023 UT of UT inspectors show no concerns. 2023 UT of UT inspectors show no concerns. Maintain current interval.</td> <td>Risk Duetime (SAR)</td> <td>Decrease inspection interval to 60 months.</td>	2018	2024	None	Manufacturers in 47 report 23 hours Manufacturing Effluent from Maximal 23 hours Manufacturing Effluent. 2023 UT of UT inspectors show no concerns. 2023 UT of UT inspectors show no concerns. Maintain current interval.	Risk Duetime (SAR)	Decrease inspection interval to 60 months.
AK04940	COOL NORTH 1482	16-04-084-0764 PLANT	1301	MS02.2	Plant	FLAME KNOCK OUT DRUM	FLAME KNOCK OUT DRUM	Y	1988	KING INDUSTRIAL INC.	N SERVICE	50			02/16/2021	7/10/2018	VE, UT	VE, UT, W	Insensitive	VE - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	0.0226	7%	35- Heads 1	0.0224	45.96136286	20	YES	100%	NO	None	2018	UT - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	#N/A	72	60 <td>2018</td> <td>2024</td> <td>None</td> <td>Open action item. Set damaged during 2023 UT of UT inspectors show no concerns. Maintain current interval.</td> <td>Risk Duetime (SAR)</td> <td>Decrease inspection interval to 60 months.</td>	2018	2024	None	Open action item. Set damaged during 2023 UT of UT inspectors show no concerns. Maintain current interval.	Risk Duetime (SAR)	Decrease inspection interval to 60 months.	
AK04940	COOL NORTH 1482	16-04-084-0764 PLANT	1301	MS02.2	Plant	FLAME KNOCK OUT DRUM	FLAME KNOCK OUT DRUM	Y	1988	KING INDUSTRIAL INC.	N SERVICE	50			02/16/2021	7/10/2018	VE, UT	VE, UT, W	Insensitive	VE - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	0.0209	7%	50- Heads 1	0.0202	85.07920229	40	YES	100%	NO	None	2018	UT - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	#N/A	72	60 <td>2018</td> <td>2024</td> <td>None</td> <td>Open action item. Set damaged during 2023 UT of UT inspectors show no concerns. Maintain current interval.</td> <td>Risk Duetime (SAR)</td> <td>Decrease inspection interval to 60 months.</td>	2018	2024	None	Open action item. Set damaged during 2023 UT of UT inspectors show no concerns. Maintain current interval.	Risk Duetime (SAR)	Decrease inspection interval to 60 months.	
AK01333	COOL NORTH 1482	16-04-084-0764	3008	MS04.2	Sub-Plant	VERTICAL SEPARATOR	SEPARATOR	N	1988	ROY GARFIELD SERVICE LTD.	N SERVICE	1400			02/16/2021	7/10/2018	VE, UT	VE, UT	Insensitive	VE - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	0.0214	7%	15-Shell	0.14663571	93.38889317	20	YES	100%	NO	None	2018	VE - General moderate external corrosion (0.025 to 0.032) noted on top head and top piping. Moderate external surface corrosion observed on top head of vessel and outer piping in building. Moderate leak was found on piping. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	YES	72	72	60 <td>2018</td> <td>2024</td> <td>NCR Admin - Missing 1-1</td> <td>U34 not found. Open action item. Repair or replace piping. 2023 UT of UT inspectors show no concerns. 2023 UT of UT inspectors show no concerns. Maintain current interval.</td> <td>Risk Duetime (SAR)</td> <td>Decrease inspection interval to 60 months.</td>	2018	2024	NCR Admin - Missing 1-1	U34 not found. Open action item. Repair or replace piping. 2023 UT of UT inspectors show no concerns. 2023 UT of UT inspectors show no concerns. Maintain current interval.	Risk Duetime (SAR)	Decrease inspection interval to 60 months.
CS028	COOL NORTH 1482	16-04-084-0764	PV-022	LS17A.23	WELLTOP	FUEL GAS SCRUBBER	SEPARATOR	N	2001	COPLAC	N SERVICE	125		SOUR	02/16/2021	7/10/2018	VE, UT	VE, UT	Insensitive	VE - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	Above nominal	7%	N/A	N/A	N/A	N/A	YES	100%	NO	VISUAL NOT SECURELY MONITORED	2018	UT - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	YES	72	120	120 <td>2018</td> <td>2024</td> <td>None</td> <td>U34 not found. Open action item. Inspect and repair piping. 2023 UT of UT inspectors show no concerns. Maintain current interval.</td> <td>Risk Duetime (SAR)</td> <td>Maintain inspection interval at 120 months.</td>	2018	2024	None	U34 not found. Open action item. Inspect and repair piping. 2023 UT of UT inspectors show no concerns. Maintain current interval.	Risk Duetime (SAR)	Maintain inspection interval at 120 months.
CS037	COOL NORTH 1482	16-04-084-0764	1228	FS02.2	WELLTOP	FUEL GAS SCRUBBER	SEPARATOR	N	1988	ROY GARFIELD SERVICE LTD.	N SERVICE	200			02/16/2021	7/10/2018	VE, UT	VE, UT	Insensitive	VE - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	Above nominal	7%	N/A	N/A	N/A	N/A	YES	100%	NO	None	2018	UT - No concerns. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA. UT - 784, 85 and 88 on piping had measurements below 100% but above 75% TSCA.	YES	72	120	120 <td>2018</td> <td>2024</td> <td>None</td> <td>U34 not found. Open action item. Inspect and repair piping. 2023 UT of UT inspectors show no concerns. Maintain current interval.</td> <td>Risk Duetime (SAR)</td> <td>Maintain inspection interval at 120 months.</td>	2018	2024	None	U34 not found. Open action item. Inspect and repair piping. 2023 UT of UT inspectors show no concerns. Maintain current interval.	Risk Duetime (SAR)	Maintain inspection interval at 120 months.



