



A0218190_Nameplate_03Feb10

5311 – 86 Street, Edmonton, Alberta T6E 5T8 Phone: (780) 437-2022 Fax: (780) 430-6022

Red Deer (403) 347-1742 Oklahoma City, OK (405) 495-6677 Tulsa, OK (918) 446-8773



VESSEL INSPECTION SUMMARY

Report #: 141148-PM-18 Inspect Date: 02/03/2010 1 of 4 Page: IRISNDT #: 141148

Client:	Client: CNRL				District: St. Albert				Field: Endiang				
Facility:				Uı	Jnit / Skid #: N/A			-	LSE		034-15W4		
Jurisdiction #:				quip Tag #: N/A			-	Serial #	#: 26	904A			
CRN #:				Nat'l Bd #:			Year Built: 1984			984			
Manufacturer:	Manufacturer: Western Rock Bit Co. Ltd. Equipment Description: Propane Bullet												
	In Service - Date Removed From Service: Service: Sweet												
MAWP Shell:	1724	kPa	_ @ _	46	°C	Height/L			77	in.		Code Stamp:	\boxtimes Y \square N
MAWP Tube:			_ @ _			Size/Diar	neter.: _		in.	O.D.		Insulated:	
MDMT:			_ RT:	RT-2		Vo	olume: _	6	8.6	m³		PWHT:	
Support Type:	Sad	dle	_									Manway:	\boxtimes Y \square N
C.A.:			_ Coate	ed: 🔲 Y	Y 🗌 N Clad: 🗌 Y 🗍 N J.E.: Remote Access: 🗌								
Comp	onent			Mate	erial		Nomin	al Thk	Diame	eter	OD/ID	Tube Side	Shell Side
	- Head			SA-5	516-70 19.620 mm			0 mm	2744.00	0 mm	OD		
	- Shell			SA-516-70			19.760 mm 2744.000		0 mm	OD			
	-												
	-												
	-												
Comments:													
PSV Static Data													
						//					ODN		1
PSV –1 Ta						ial #:				0.45	CRN: _		
Mode					Capa	icity:				Set Pre			
Manufactu						-				ice Con			
Inlet Size & Type:Outlet Size & Type:										Service	_		
					-				Block Valv	code S			
Carseal Intact: Shell Side / Tube Side:											f PSV:		
Sileli Side	i i i ube Si	iue								alion o			
PSV –2 Ta	ıg #:				_	ial #:					CRN:		
Mode	el #:				Сара	city:				Set Pre	ssure:		
Manufactu						_			Servi	ice Con	npany:		
Inlet Size	& Type:		-										
Outlet Size	_		-						Block Valv				
	al Intact: ₋									Code S			
Shell Side	/ Tube Si	ide:			-				Loc	ation of	f PSV:		
PSV Comments													"
Could not acce	ss PSV's.	They	are loca	ated on	top of	vessel op	posite er	nd of pla	tform. Wil	l need a	a man lift	or scafolding	to access.
	-4		50 Di	700) 45-	000 5	(780) 438-143							



VESSEL INSPECTION SUMMARY

Report #: 141148-PM-18
Inspect Date: 02/03/2010
Page: 2 of 4
IRISNDT #: 141148

Client: CNRL				LSD:06-28-034-15W4 Jurisdiction #:A0218190				0218190	
External Inspection Results - VE									
Item	Y	N	N/A	Condition	Comment	NCR	Action Item	Priority	
Nameplate	\boxtimes			Accept					
Foundation and Supports	\boxtimes			Accept					
Anchor Bolts	\boxtimes			Accept					
Grounding	\boxtimes			Accept					
Insulation Condition			\boxtimes						
PSV	\boxtimes				Could not access PSV's		\boxtimes		
Shell & Heads	\boxtimes			Accept					
Metal Surfaces (Paint)	\boxtimes			Accept					
Aux Equipment									
Cathodic Protection									
Alignment	\boxtimes			Accept					
Flange Connections	\boxtimes			Accept					
Pressure Gauge									
Piping from Vessel	\boxtimes			Accept					
Temperature Gauge									
Sight Glass	\boxtimes			Accept					
Leaks		\boxtimes							
Current UT Survey	\boxtimes					UT	Company:		
Previous UT Survey					UT	Company:			
LEGEND: Priority 0 - General Recommendations Priority 1 - Goal date is 30 days from the activity date Priority 2 - Goal date is 90 days from the activity date. External Visual Observations Priority 3 - Goal date is 1 Year from the activity date. Priority 4 - Goal date is 5 Years from the activity date. Manual Review Required By Customer Representative -									
External Visual Observations	<u> </u>				Ivialiuai Neview Nequ	ned by Cust	oniei Kepiese	illative -	
An external visual inspection was performed on the vessel and the findings are as follows: The vessel was operating at time of inspection. No process leaks or vibrations were noted The paint is on shell and piping in very good condition with very isolated areas of paint flaking down to clean bare metal. All piping, flanges and bolting were in good condition. Manway is in good condition with some paint flaking with mild general corrosion. Bolting shows general corrosion where paint has failed but in acceptable condition.									
Ladder and platform is in good condition and secure The vessel is supported by saddles welded to shell and welded to metal skid. Vessel is secure and level. External UT was performed with no significant wall losses noted. Could not access PSV's. Refer to the attached photos, UT data and drawing for inspection findings. The vessel appears to be in good operating condition for continued service based on the external visual observations and UT thicknesses recorded and that overpressure protection has been verified.									

5311 – 86 Street, Edmonton, Alberta T6E 5T8 Phone: (780) 437-2022 Fax: (780) 438-1436

 Calgary
 (403) 279-6121

 Lloydminster
 (780) 875-6455

 Barhead
 (780) 674-3018

 Nisku
 (780) 955-7616

780) 438-1436
Cold Lake (780) 594-1114
Fort McMurray (780) 743-1536
High Level (780) 956-4094
Red Deer (403) 347-1742
Medicine Hat (403) 527-6284

Corpus Christi, TX
Deer Park, TX
Matrix, Houston, TX
Texas City, TX
Tulsa, OK

(361) 888-4700
(281) 476-4444
(713) 722-7177
(490) 945-2262
(918) 446-8773



(403) 279-6121

(780) 875-6455 (780) 674-3018 (780) 955-7616

Calgary

Nisku

Lloydminster Barhead

VESSEL INSPECTION SUMMARY

Report #: 141148-PM-18
Inspect Date: 02/03/2010
Page: 3 of 4

							IKISNUT #.	141140	
Client:	CN	NRL		LSD:	06-28-034-15W4	Jurisdiction	#: A0	218190	
Internal Inspection Results – VI N/A (Not Applicable)									
Item	Υ	N	N/A	Condition	Comment	NCR	Action Item	Priority	
Shell									
Heads									
Manway									
Gasket Surfaces									
Welds									
Refractory									
Heating Coils									
Demister Pad									
Vane Pack									
Baffles									
Trays									
Filter									
Internal Coating									
Tubesheet									
Tube Bundle									
Priority 0 - General Recommendations. Priority 1 - Goal date is 30 days from the activity date. Priority 2 - Goal date is 90 days from the activity date. Priority 2 - Goal date is 90 days from the activity date.									
Internal Visual Observations					Manual Review Require	d By Custom	er Represent	ative -	
5311 - 86 Street, Edmonton, Alberta	T6E	5T8 Pho	ne: (780) 4	437-2022 Fax: (780)) 438-1436				

Cold Lake

Fort McMurray High Level Red Deer

Medicine Hat

(780) 594-1114

(780) 594-1114 (780) 743-1536 (780) 956-4094 (403) 347-1742 (403) 527-6284 (361) 888-4700

(281) 476-4444 (713) 722-7177 (490) 945-2262

Corpus Christi, TX

Deer Park, TX Matrix, Houston, TX Texas City, TX Tulsa, OK



VESSEL INSPECTION SUMMARY

Report #: 141148-PM-18
Inspect Date: 02/03/2010
 Page: 4 of 4
IRISNDT #: 141148

Client: C	NRL LSD:	06-28-03	4-15W4 Juri	sdiction #: A	0218190				
		Attack	ned to Vessel Inspection	on Report #					
Attached to Vessel Inspection Report #Additional Attachments # of pages Specify									
	T D PT ET [THER 🗌						
NDE Report #:									
Items Raised: NCR	Operational Ac	tion Item	_ Repair Action Item _	Deferred Act	ion Item <u>Yes</u>				
Action Items / Recommendatio									
· Continue to inspect	vessel at regular schedu	uled intervals and	insure that overpressu	re protection has beer	n verified.				
Actions Corrected at Time of Ir	ispection: (If actions were co	orrected at the time of	Inspection – note the correct	ed actions here.)					
Meets Code Criteria: -		Re-	Inspection Required -						
		ļ.							
Recommended Inspection Int			T						
VE Inspect. Last Inspe	ction: -	Interval (yrs)		Next Inspection:	- 0000				
VI Inspect. Last Inspe	ction: -	Interval (yrs)		Next Inspection:	- 0000				
UT Inspect. Last Inspe	ction: -	Interval (yrs)		Next Inspection:	- 0000				
PSV Service Last Inspe	ction: -	Interval (yrs)		Next Inspection:	- 0000				
		Consumables:	Inconcetors						
	S:	Consumables:	Inspector: Pamela Maze	PESL	: 351				
	:00 Hrs		- (n)	int) Pamela Maze CN = Pamela Maze, C = CA, O = IRISNDT APPROPRIE					
	:00 Hrs		- Vamela Maz C	IRISNDT AP gn3010.05.10 10:28:47-06'00'	:				
Personnel: MB		-	Client Representative:	: (Print)					
P.O.# / W.O.#/AFE #:		-	I am in full agreement with	(Print) (Sign)					
5311 – 86 Street, Edmonton, Alberta T6l	F 5T8 Phone: (780) //37 2022 Fov	(780) 438-1436	report contents:	(Sign)					
Calgary (403) 279-6121 Lloydminster (780) 875-6455	- 3.31 Hono. (100) 401-2022 1 dA. (Cold Lake (7	780) 594-1114 780) 743-1536	Corpus Christi, TX Deer Park, TX	(361) 888-4700 (281) 476-4444				
Barhead (780) 674-3018 Nisku (780) 955-7616		High Level (7	780) 743-1336 780) 956-4094 403) 347-1742	Matrix, Houston, TX Texas City, TX	(713) 722-7177 (490) 945-2262				
(100) 000-1010			403) 527-6284	Tulsa, OK	(918) 446-8773				





A0218190_Overview_03Feb10

5311 – 86 Street, Edmonton, Alberta T6E 5T8 Phone: (780) 437-2022 Fax: (780) 430-6022

Red Deer (403) 347-1742 Oklahoma City, OK (405) 495-6677 Tulsa, OK (918) 446-8773