





Corrosion/pitting at shell to floor weld

Approximately 0.200 inches loss



Repair patch

8.0 x 6.0 inches



Repair patches

6.0 x 6.0 inches