




Transmitter valving – signs of leaking



Stainless to carbon flanges – no CP isolation kit installed



1 inch hole through corrosion



Overview



Manway



Door plate