

## VESSEL INSPECTION REPORT

CLIENT CNRL	DISTRICT Wolf Lake	FACILITY/UNIT  Burnt Lake		.D/LSD <b>67-3W4M</b>
EQUIPMENT JUR. # <b>420792</b>	EQUIPMENT # BLP-E-160	SERIAL # 97-1630		Exchanger
NAT'L BD #	MAWP@TEMP 827kPa @ 163°C	CRN# <b>N5243.2</b>	MANUFACTURER Exchanger Ind	YEAR BUILT 1997
мрмт -29°С	STATUS In service	manway <b>N</b> o	LENGTH 0.76m HEIGHT	DIAMETER 0.53m
RT 3 PWHT YES□ NO ☒	SERVICE Sales oil		NOMINAL THICKNESS	MATERIAL
VOLUME	COATED/CLAD	SHELL	0.375"	SA-516-70N
VOLOIVIL	COATED/CEAD	Channel HEAD	0.3125"	SA-516-70N
SADDLE	INSULATED Yes			
5. ISSLE		CORR.ALLOW.	0.0625"	

#### **PSV STATIC DATA**

TAG#	S/N	MANUFACTURER	MODEL	CRN
SET PRESSURE	SHELL/TUBE SIDE	SERVICE DATE	SERVICE COMPANY	SIZE IN
CAPACITY	CONNECTION TYPE	CARSEAL INTACT	LOCATION	SIZE OUT
TAG#	S/N	MANUFACTURER	MODEL	CRN#
SET PRESSURE	SHELL/TUBE SIDE	SERVICE DATE	SERVICE COMPANY	SIZE IN
CAPACITY	CONNECTION TYPE	CARSEAL INTACT	LOCATION	SIZE OUT

### **SUMMARY OBSERVATIONS**

Sensitive leak test performed on the tubes – 10 PSI, no leaks noted. Tubesheet in good condition. No corrosion noted in the channel head. Vessel and piping in good condition. Insulation and cladding are good.

### **SUMMARY RECOMMENDATIONS**

NA

UNIT# KM
IN OUT HRS
IN OUT HRS
PERSONNEL M SALES

I, the undersigned have performed the stated inspections as directed by the client and that the statements with in this report are correct and represent inspection findings to the best of my abilities

MARTEN SALES API510 #25527

INSPECTOR NAME and CERTIFICATION NUMBER

INSPECTOR SIGNATURE

CLIENT SIGNATURE & JOB NUMBER



# VESSEL INSPECTION REPORT

REPORT# 71155

DATE Sept 22-06

PAGE 2 of 3

IRISNDT# 117068

CLIENT	DISTRICT	FACILITY/UNIT	FIELD/LSD
CNRL	Wolf Lake	Burnt Lake	14-14-067-3W4M
EQUIPMENT JUR. #	EQUIPMENT #	SERIAL #	EQUIPMENT DESCRIPTION
420792	BLP-E-160	97-1630	Sales Oil Exchanger

### **EXTERNAL INSPECTION RESULTS**

Item	Comment	Item	Comment
Foundation	Structural/Piles	Paint	NA
Grounding	Through piles	Cathodic Protect	NA
Insulation	In good condition	Fireproofing	NA
Piping	Associated piping in good condition	Ladders/Platforms	NA
Supports	OK	Berms	NA
Anchor Bolting	OK	Davit Arm	NA

Comment

#### **DETAILED OBSERVATIONS AND RECOMMENDATIONS**

The vessel is mounted on two saddles with piles for support.

A 10-PSI air pressure sensitive leak test was performed on the tube sheet and tubes by applying the pressure to the shell side and snoop testing the tubesheet and tube ends.

No leaks were found.

No tube sheet corrosion was visible

The exchanger channel was internally inspected, with no corrosion found.

The vessel and piping are secure and in good condition. The insulation/cladding is in relatively good condition.

The nameplate is affixed and legible.

The PSV's were removed for service at the time of inspection.



