

INSPECTION DEFICIENCY REPORT

PRIORITY	0	- Immediate Action Required – Remove Equipment from Service
	1	- Action Required within 14 days
	2	X - Action Required within 30 days
	3	- Action Required at next available maintenance opportunity

FACILITY: Hussar Field DATE: August 8, 2012 REPORT #: IDR 120808AFb

STATIC DATA

Prov. Reg. #	<u>A0547598</u>	CRN:	<u>P-3515.213</u>	Serial #	<u>14532</u>
Equipment Location(LSD):	<u>07-09-25-21 W4M</u>	Equipment ID #:	<u>66100501</u>	<input checked="" type="checkbox"/> Sweet	<input type="checkbox"/> Sour
Equipment Description:	<u>Flodrip Separator</u>	Service:	<u>Natural Gas</u>		
Manufacturer:	<u>Crimtech Services Ltd.</u>	Year Built:	<u>2005</u>		
MAWP	<u>1480</u> psi	@	<u>100</u> °F	MDMT:	<u>- 29</u> °C Capacity: <u> </u> m3

IDENTIFIED DEFICIENCY

-The piping support for the 1" drain piping was not aligned with the piping.
-The inlet piping support is missing the U-bolt clamp.

RECOMMENDED ACTION

LEAVE "AS-IS"
 PERFORM REPAIR
 PERFORM ALTERATION
 REPLACE UNIT
 INTEGRITY ASSESSMENT REQUIRED

Comments: *Ensure piping is supported & u-clamps installed.*

INSPECTION PERFORMED BY

QUALITY INSPECTOR
 LEAD INSPECTOR
 CONTRACTED INSPECTOR

Adam Fitzgerald _____ August 14, 2012
Print Name Signature Date

DEFICIENCY REPORT ISSUED TO

Name	Position	Date
<u>Henry Hollman</u>	<u>HUSSAR FIELD FOREMAN</u>	<u>Aug. 1/13</u>
<u>PAUL FAUSTON</u>		

RECOMMENDED ACTION COMPLETED

Job File # Comments : _____

Print Name Signature Date

✓ 2

