	GENERA	L TANK	INFORMATIO	ON				
District: Slave Lake			Skid No.:	CB38				
Facility: Central Pads			Location (LSD): 16-07-081-20W4					
Name & Equip No: AST - C81071			Orientation: Vertical					
Company: CNRL			Cost Code:					
Status: Not In Service			Operating Province: Alberta					
			Unique ID: ONCOR ID: 65397					
	TANK	NAME	PLATE DATA					
Registration Number: C81071			Registration Nu	umber (0	Other):			
Serial Number: F-95-474-3			Tank Height:		288.00	(In)	7315.20	(mm)
Manufacturer: G.L.M. TANKS			Tank Diameter	7	183.00	(In)	4648.20	(mm)
Year Built: 1995			Tank Volume:		750.00			
Type: 12F			Floor Material:					
Secondary Containment: Yes			Floor Thickness	s:	0.25	(In)	6.35	(mm)
External Cathodic Protection: Yes			Roof Material:					
Corrosion Allowance: (In) (mm)			Roof Thickness	5:	0.19	(In)	4.76	(mm)
Internally Coated:			Containment L	ength:		(In)		(mm)
Skid Mounted: No			Containment V	Vidth:		(In)		(mm)
Tank Heat Type: FIRETUBE			Containment H	leight:		(In)		(mm)
Lining Coated Type:			Deck Material:					
Portable: No			Deck Thickness	s:		(In)		(mm)
Elevated: Yes			Double Walls: No					
Anodes: No			Insulated:	Yes				
Internal Access: No			Shell Material:		A-36			
			Shell Thickness: 0.19 (In) 4.76 (mm)			(mm)		
SERV	ICE CONDITION	ONS-IN	DICATE ALL	THAT A	APPLY			
Sweet ✓ Sour	Oil			Gas			Water	
Amine LPG	Cond	ensate		Air			Glycol	
Other (Describe):								
		СОМРО	NENTS	- 1			1	
Name		Di	Outside iameter(in.)		Stress Value (PSI)		Nomina Thickness(1	
			,	\dashv				- ,
TYPE STATED AAS 12F ED. 11.	GEN	NERAL (COMMENTS				1	

3,305

 Registration #:
 C81071
 Equipment Name:
 AST
 Province:
 Alberta

 District:
 Slave Lake
 LSD:
 16-07-081-20W4
 Location:
 Central Pads

CRN: Skid Number: CB38 Service:

- CNRL

 Manway:
 Coating:
 Equipment Number:
 C81071

 MAWP (psi):
 (psi)
 Temp:
 (F)
 Serial Number:
 F-95-474-3

Outstanding NCR's: No No.: 0

General:

Internal Inspection

Inspection Date:	May 22, 2013	Inspection Interval:	ı	Next Insp. Date:		
<u>Item</u>	Condition	Inspection Comments				
General Condition	Accept	GOOD CONDITION.				
Insulation	Accept	MINOR BLISTERS OBSERVED.				
Containmen	Accept	STEEL RING WITH POLY LINER.				
External Corrosion	N/A	INSULATED.				
External Welds	N/A	INSULATED.				
Bolted Tanks	N/A					
Bolted Tanks	N/A					
Manway	Accept	MANWAY & MANWAY DOORS IN GOOD CONDIT	ION.			
Supports/Structural	Accept	ALL SUPPORTS IN PLACE & IN GOOD CONDITION	N.			
Internal Welds	Accept	GOOD CONDITION.				
		NO DAMAGE OBSERVED.				
Coating	N/A					
Floor	Accept	PERFORMED SPOT UT AND MFL FLOOR SCAN. N	O DAMAGE OBSER	VED.		
Shell	Accept	GOOD CONDITION.				
Roof	Accept	GOOD CONDITION.				
Internal components	Accept	FIRETUBE IN GOOD CONDITION.				
Anodes	N/A					
NDE	Accept	PERFORMED SPOT UT ON FLOOR & 1ST SHELL S	SECTION.			
		PERFORMED MFL FLOOR SCAN.				
Other	N/A					
Recommendations:	TANK IS FIT FOR	R SERVICE.	Inspected By:	Jamey Tanasichuk	ABSA PESL #:	000411

 $\textbf{INSPECTOR:} \quad \textbf{I have witnessed/done the above inspections and certify that they have been done in accordance with our accordance with the expectation of the ex$

approved manual and that the information is accurate. I certify that the status of the Pressure equipment

detailed here is:

Suitable to be returned to service Repairs complete(AB-40 attached)
Repairs are still required: Suggested Inspection interval:

Inspector: Jamey Tanasichuk ABSA PESL #: 000411 Signature: _____ Date: May 22, 2013




TOTAL INTEGRITY MANAGEMENT SOLUTIONS

STORAGE TANK SURVEY DRAWING

#	LOW	AVG	#	LOW	AVG
05	0.212	0.235	35	0.188	0.195
10	0.245	0.255	40	0.189	0.195
15	0.233	0.250	45	0.190	0.200
20	0.236	0.250			
25	0.248	0.255			
30	0.187	0.200			


NOTE: EACH TML REPRESENTS A 12" x 12" SCANNING AREA



OWNER: CNRL	SERIAL # F-95-474-3	INSPECTED BY: JAMES TANASICHUK
EQUIPMENT NAME: TANK	NB#	1 21
REGISTRATION # C81071	OWNER ID	Jacob 1.
EQUIPMENT # C81071	ONCOR ID	PAGE 1 / 2



MAGNETIC FLUX LEAKAGE (MFL) REPORT



SCOPE

MAGNETIC FLUX LEAKAGE FLOOR SCAN PERFORMED ON TANK FLOOR.
ANY AREAS OF NOTABLE UNDERSIDE CORROSION THAT ARE LOCATED SHALL BE PROVED WITH UT THICKNESS VERIFICATION.

RESULTS

NO SIGNS OF UNDERSIDE CORROSION WERE FOUND USING THE MFL AND UT SCAN.

OWNER: CNRL	SERIAL # F-95-474-3	INSPECTED BY: JUSTIN ORICHOWSKI
EQUIPMENT NAME: TANK	NB#	
REGISTRATION # C81071	OWNER ID	J. China
EQUIPMENT # C81071	ONCOR ID	PAGE 2 / 2



TOTAL INTEGRITY MANAGEMENT SOLUTIONS













		_
OWNER: CNRL	SERIAL # F-95-474-3	NOTES
EQUIPMENT NAME: TANK	NB#	
REGISTRATION # C81071	OWNER ID	
EQUIPMENT # C81071		

PAGE 1 / 2



TOTAL INTEGRITY MANAGEMENT SOLUTIONS





•	
1	
	L
	·
	·
·	·
	·
	·
	·
	·
	·
	·
	·
	·
	·
	·
-	

OWNER: CNRL	SERIAL # F-95-474-3	NOTES PAGE 2 / 2
EQUIPMENT NAME: TANK	NB#	
REGISTRATION # C81071	OWNER ID	
EQUIPMENT # C81071		