	G	ENERA	L TANK	INFORMATIO	ON				
District: Slave Lake			Skid No.: CB33						
Facility: Central Pads			Location (LSD): 01-07-081-20W4						
Name & Equip No: AST - C81068			Orientation:	Vertical					
Company: CNRL				Cost Code:					
Status: Operating				Operating Prov	rince:	Alberta			
Unit:	W.O/P.O No.:			Unique ID:				ONCOR ID: 65	5412
		TANK	NAME	PLATE DATA					
Registration Number: C8:	1068			Registration Number (Other):					
Serial Number: G-97-338-9	90			Tank Height: 288.00 (In) 7315.20 (mn			(mm)		
Manufacturer: G.L.M. TAN	NKS			Tank Diameter	:	207.00	(In)	5257.80	(mm)
Year Built: 1998				Tank Volume:		1000.00			
Type:				Floor Material:					
Secondary Containment:	Yes			Floor Thicknes	s:	0.25	(In)	6.35	(mm)
External Cathodic Protection:	Yes			Roof Material:					
Corrosion Allowance: (In) (mm)			Roof Thickness	s:	0.25	(In)	6.35	(mm)	
Internally Coated:			Containment L	ength:		(In)		(mm)	
Skid Mounted: No			Containment Width: (In)			(mm)			
Tank Heat Type: FIRETUBE			Containment Height: (In) (mm)			(mm)			
Lining Coated Type:			Deck Material:						
Portable: No			Deck Thicknes	s:		(In)		(mm)	
Elevated: Yes			Double Walls:	No					
Anodes: No				Insulated: Yes					
Internal Access: Yes				Shell Material: A-36 OR EQ					
				Shell Thickness: 0.25 (In) 6.35 (mm)					
	SERVICE CO	NDITI	ONS-IN	DICATE ALL	THAT A	<b>APPLY</b>			
Sweet	Sour	Oil			Gas			Water	
Amine	LPG	Condensate			Air			Glycol	
Other (Describe):									
COMPONENTS									
Name			Di	Outside iameter(in.)		Stress Value (PSI)		Nomina Thickness(1	
		GEN	NERAL (	COMMENTS					
SECONDARY SHELL THICKNES	SS 0.1875".								
PICS: 373-375.	PICS: 373-375.								

 Registration #:
 C81068
 Equipment Name:
 AST
 Province:
 Alberta

 District:
 Slave Lake
 LSD:
 01-07-081-20W4
 Location:
 Central Pads

CRN: Skid Number: CB33 Service:

 Manway:
 Coating:
 Equipment Number:
 C81068

 MAWP (psi):
 (psi)
 Temp:
 (F)
 Serial Number:
 G-97-338-90

Outstanding NCR's: No No.: 0

General:

## **Internal Inspection**

Inspection Date:	May 22, 2013	Inspection Interval:	ı	Next Insp. Date:		
<u>Item</u>	Condition	Inspection Comments				
General Condition	Accept	GOOD CONDITION.				
Insulation	Accept	MINOR BLISTERS/HOLIDAYS OBSERVED.				
Containmen	N/A					
External Corrosion	N/A	INSULATED.				
External Welds	N/A	INSULATED.				
Bolted Tanks	N/A					
Bolted Tanks	N/A					
Manway	Accept	GOOD CONDITION.				
Supports/Structural	Accept	ALL SUPPORTS IN GOOD CONDITION.				
Internal Welds	Accept	GOOD CONDITION.				
		NO DAMAGE OBSERVED.				
Coating	N/A					
Floor	Accept	PERFORMED SPOT UT AND MFL FLOOR SCAN.	NO DAMAGE OBSER'	VED.		
Shell	Accept	GOOD CONDITION.				
Roof	Accept	GOOD CONDITION.				
Internal components	Concern	FIRETUBE OBSERVED TO BE DISTORTED ON B	URNER SIDE.			
Anodes	N/A					
NDE	Accept	PERFORMED SPOT UT ON FLOOR & 1ST SHELL	SECTION.			
		PERFORMED MFL FLOOR SCAN.				
Other	N/A					
Recommendations:	TANK IS FIT FOR	R SERVICE.	Inspected By:	Jamey Tanasichuk	ABSA PESL #:	000411
		) SANDBLAST AND INSPECT				
	FIRETUBE.					

INSPECTOR: I have witnessed/done the above inspections and certify that they have been done in accordance with our

approved manual and that the information is accurate. I certify that the status of the Pressure equipment

detailed here is:

Suitable to be returned to service Repairs complete(AB-40 attached)
Repairs are still required: Suggested Inspection interval:

Inspector: Jamey Tanasichuk ABSA PESL #: 000411 Signature: \_\_\_ Date: May 22, 2013




TOTAL INTEGRITY MANAGEMENT SOLUTIONS

## STORAGE TANK SURVEY DRAWING

#	LOW	AVG	#	LOW	AVG
05	0.230	0.245	35	0.246	0.255
10	0.233	0.245	40	0.244	0.260
15	0.240	0.250	45	0.250	0.260
20	0.239	0.250			
25	0.241	0.250			
30	0.248	0.255			


NOTE: EACH TML REPRESENTS A 12" x 12" SCANNING AREA



OWNER: CNRL	SERIAL # G-97-338-90	INSPECTED BY: JAMES TANASICHUK
EQUIPMENT NAME: TANK	NB#	121
REGISTRATION # C81068	OWNER ID	Jacob Milli
EQUIPMENT # C81068	ONCOR ID	PAGE 1 / 2



MAGNETIC FLUX LEAKAGE (MFL) REPORT



## SCOPE

MAGNETIC FLUX LEAKAGE FLOOR SCAN PERFORMED ON TANK FLOOR.
ANY AREAS OF NOTABLE UNDERSIDE CORROSION THAT ARE LOCATED SHALL BE PROVED WITH UT
THICKNESS VERIFICATION.

## **RESULTS**

NO SIGNS OF UNDERSIDE CORROSION WERE FOUND USING THE MFL AND UT SCAN.

OWNER: CNRL	SERIAL # G-97-338-90	INSPECTED BY: JUSTIN ORICHOWSKI
EQUIPMENT NAME: TANK	NB#	
REGISTRATION # C81068	OWNER ID	J. Clan
EQUIPMENT # C81068	ONCOR ID	PAGE 2 / 2



TOTAL INTEGRITY MANAGEMENT SOLUTIONS













OWNER: CNRL	SERIAL # G-97-338-90	NOTE
EQUIPMENT NAME: TANK	NB#	
REGISTRATION # C81068	OWNER ID	
EQUIPMENT # C81068		



TOTAL INTEGRITY MANAGEMENT SOLUTIONS







EQUIPMENT # C81068



OWNER: CNRL	SERIAL # G-97-338-90	NOTES PAGE 2 / 2
EQUIPMENT NAME: TANK	NB#	
REGISTRATION # C81068	OWNER ID	