		GENERA	L TANK	INFORMATIO	ON				
District: Slave L	ake			Skid No.:	BAR1				
Facility: Barney Pads			Location (LSD): 09-13-080-21W4						
Name & Equip No: AST - C81055			Orientation: Vertical						
Company: CNRL				Cost Code:					
Status: Shut-Ir	1			Operating Province: Alberta					
Unit:	W.O/P.O No	u:		Unique ID: ONCOR ID: 64856					
		TANK	NAME	PLATE DATA					
			Registration Nu	ımber (0	Other):				
Serial Number: F-9	7-019-12			Tank Height:		288.00	(In)	7315.20	(mm)
Manufacturer: GLI	M TANKS & EQUIPMENT LTD			Tank Diameter	:	183.00	(In)	4648.20	(mm)
Year Built: 1997				Tank Volume: 750.00					
Туре:				Floor Material:					
Secondary Containme	nt: Yes			Floor Thickness: 0.25 (In)		6.35	(mm)		
External Cathodic Protection: Yes			Roof Material:						
Corrosion Allowance: (In) (mm)			Roof Thickness	i:	0.19	(In)	4.78	(mm)	
Internally Coated: No			Containment L	ength:		(In)		(mm)	
Skid Mounted: No			Containment Width: (In)			(mm)			
Tank Heat Type: FIRETUBE			Containment Height: (In) (I			(mm)			
Lining Coated Type: N/A			Deck Material:						
Portable: No			Deck Thickness	5:		(In)		(mm)	
Elevated: Yes			Double Walls: No						
Anodes: No			Insulated: Yes						
Internal Access: Y	'es			Shell Material: A-36 OR EQ					
				!			(mm)		
	SER	VICE CONDITI	ONS-IN	DICATE ALL	THAT A	APPLY			
Sweet	Sour	Oil			Gas			Water	
Amine	LPG	Cond	ensate		Air			Glycol	
Other (Describe):			COMP.	NENTC					
			СОМРО	Outside	<u> </u>	Stress		Nomina	
Name		Di	ameter(in.)		Value (PSI)		Thickness(1		
					\dashv				
EQUIPMENT NAME: TA PICS: 365 - 367.	NK TK 108B.	GEI	NERAL (COMMENTS					

Registration #:C81055Equipment Name:ASTProvince:AlbertaDistrict:Slave LakeLSD:09-13-080-21W4Location:Barney Pads

CRN: Skid Number: BAR1 Service:

 Manway:
 Coating:
 Equipment Number:
 C81055

 MAWP (psi):
 (psi)
 Temp:
 (F)
 Serial Number:
 F-97-019-12

Outstanding NCR's: No No.: 0

General:

Internal Inspection

Inspection Date:	May 23, 2013	Inspection Interval:	İ	Next Insp. Date:		
<u>Item</u>	Condition	Inspection Comments				
General Condition	Accept	GOOD CONDITION.				
Insulation	Accept	GOOD CONDITION.				
Containmen	Accept	GRAVEL BERM WITH POLY LINER.				
External Corrosion	N/A	INSULATED.				
External Welds	N/A	INSULATED.				
Bolted Tanks	N/A					
Bolted Tanks	N/A					
Manway	Accept	MANWAY & MANWAY DOORS IN GOOD COND	ITION.			
Supports/Structural	Accept	GOOD CONDITION.				
Internal Welds	Accept	GOOD CONDITION.				
Coating	N/A					
Floor	Accept	PERFORMED SPOT UT & MFL FLOOR SCAN.				
		NO DAMAGE OBSERVED.				
Shell	Accept	GOOD CONDITION.				
Dark	At	MINOR DENT/BULGE ON SOUTHEAST SHELL R	OUGHLY 4" FROM FL	OOR.		
Roof	Accept	GOOD CONDITION.				
Internal components	Accept	GOOD CONDITION.				
Anodes	N/A					
NDE	Accept	PERFORMED SPOT UT ON FLOOR & 1ST SHELL PERFORMED MFL FLOOR SCAN.	L SECTION.			
Other	Concern	TWO TRANSPORTATION SKIDS OBSERVED TO	BE BREAKING AWAY	FROM TANK.		
Recommendations:	TANK IS FIT FO	R SERVICE.	Inspected By:	Jamey Tanasichuk	ABSA PESL #:	000411
	RECOMMEND TO) RE-ATTACH TRANSPORTATION				
	SKIDS BEFORE	MOVING TANK.				
	·	·	·	· ·	· ·	•

INSPECTOR: I have witnessed/done the above inspections and certify that they have been done in accordance with our approved manual and that the information is accurate. I certify that the status of the Pressure equipment

detailed here is:

Suitable to be returned to service Repairs complete(AB-40 attached)
Repairs are still required: Suggested Inspection interval:

Inspector: Jamey Tanasichuk ABSA PESL #: 000411 Signature: ____ Date: May 23, 2013




TOTAL INTEGRITY MANAGEMENT SOLUTIONS

STORAGE TANK SURVEY DRAWING

#	LOW	AVG	#	LOW	AVG
05	0.232	0.250	35	0.184	0.195
10	0.236	0.250	40	0.182	0.190
15	0.246	0.260	45	0.182	0.190
20	0.225	0.240			
25	0.239	0.250			
30	0.184	0.195			


NOTE: EACH TML REPRESENTS A 12" x 12" SCANNING AREA



OWNER: CNRL	SERIAL # F-97-019-12	INSPECTED BY: JAMES TANASICHUK
EQUIPMENT NAME: TANK	NB#	121
REGISTRATION # C81055	OWNER ID	Ja Call
EQUIPMENT # C81055	ONCOR ID	PAGE 1 / 2



MAGNETIC FLUX LEAKAGE (MFL) REPORT



SCOPE

MAGNETIC FLUX LEAKAGE FLOOR SCAN PERFORMED ON TANK FLOOR.
ANY AREAS OF NOTABLE UNDERSIDE CORROSION THAT ARE LOCATED SHALL BE PROVED WITH UT
THICKNESS VERIFICATION.

RESULTS

NO SIGNS OF UNDERSIDE CORROSION WERE FOUND USING THE MFL AND UT SCAN.


OWNER: CNRL	SERIAL # F-97-019-12	INSPECTED BY: JUSTIN ORICHOWSKI
EQUIPMENT NAME: TANK	NB#	
REGISTRATION # C81055	OWNER ID	4. Cline
EQUIPMENT # C81055	ONCOR ID	PAGE 2 / 2



TOTAL INTEGRITY MANAGEMENT SOLUTIONS











EQUIPMENT # C81055



OWNER: CNRL	SERIAL # F-97-019-12	PAGE
EQUIPMENT NAME: TANK	NB#	
REGISTRATION # C81055	OWNER ID	

PAGE 1 / 2




TOTAL INTEGRITY MANAGEMENT SOLUTIONS









OWNER: CNRL	SERIAL # F-97-019-12	NOTES PAGE 2 / 2
EQUIPMENT NAME: TANK	NB#	
REGISTRATION # C81055	OWNER ID	

EQUIPMENT # C81055