Certificate of Inspection

ANDERSON EXPLORATION LIMITED
1600, 324 - 8 AVENUE SW

CALGARY, AB
T2P 2Z5

Obed /Edson
Gunderson
H-3-63-11

LOCATION: OBED CREEK, 7-31-52-22-W5M
DESCRIPTION: INDIRECT FIRED HEATER COIL
COMPANY CODE:
MANUFACTURER: MALONEY INDUSTRIES INC.

PREFERRED RE-INSP. INTERVAL: Yr.

YEAR BUILT: 2000
CRN: K1237.12
SERIAL #: 00-C4936-3001

VOLUME: 1.95 M3
HEATING SURFACE:
SURFACE AREA:

Safety Valves

PART	MAX. AUTHORIZED WORKING PRESSURE	MAX. TEMP	MIN. TEMP	VALVE ID	SETTING	CAPACITY	LOCATION
COIL	30000 KPA	93 C	−40 C	SV1			TO BE INSTALLED
COIL	13962 KPA	93 C	−40 C	SV2			TO BE INSTALLED
COIL	13962 KPA	93 C	−29 C	SV3			TO BE INSTALLED

OWNER INSTRUCTIONS/REMARKS:

NOT SUBJECT TO ANNUAL FEES AS PER REGULATIONS PART 4 SECTION 28 (h)
DIRECT OR INDIRECT FIRED OIL AND GAS PROCESS HEATERS OF THE COIL TYPE;

OWNER TO VERIFY INTEGRITY OF VESSEL BY PERIODIC INSPECTION PROGRAM.

VERIFY THAT VESSEL/BOILER IS PROTECTED BY AN ACCEPTABLE ASME CODE PRESSURE RELIEF VALVE, OF ADEQUATE
CAPACITY, SET AT NO MORE THAN MAXIMUM PRESSURE AUTHORIZED AND INSTALLED IN ACCORDANCE WITH THE SAFETY
CODES ACT & REGULATIONS.

VESSEL/BOILER TO BE INSTALLED IN ACCORDANCE WITH THE SAFETY CODES ACT AND REGULATIONS.

Safety Codes Officer: LEE, SAI-BONG

Signature: _____

NOTE: REQUIREMENTS OF THE SAFETY CODES ACT AND THE REGULATIONS ISSUED THEREUNDER:

The owner or person in charge shall report all accidents involving a boiler, pressure vessel or pressure piping system to the district Safety Codes Officer immediately and shall send a full report in writing to the Administrator as required by the Act. No repairs or alterations may be made unless authorized by a Safety Codes Officer.

A457189