

Certificate of Inspection

DEVON CANADA CORPORATION
324-8 AVENUE SW, SUITE 1600
ATTN: COLIN MCGOVERN
CALGARY, AB
T2P 2Z5

*Pinto Area
Wapiti*

PREFERRED RE-INSPECTION INTERVAL: Yr.

YEAR BUILT: 2001
CRN: P6654.2
SERIAL #: 6334-401-1

LOCATION: LSD 11-28-56-26W5M
DESCRIPTION: INDIRECT FIRED HEATER COILS
COMPANY CODE:
MANUFACTURER: COMPLETE PACKAGE

VOLUME: 0.484 M3
HEATING SURFACE: 41.99 M2
SURFACE AREA:
Safety Valves

PART	MAX. AUTHORIZED WORKING PRESSURE	MAX. TEMP	MIN. TEMP	VALVE ID	SETTING	CAPACITY	LOCATION
COIL 1	34474 KPA	93 C	-22 C	SV1			TO BE INSTALLED
COIL 2	13962 KPA	93 C	-29 C	SV2			TO BE INSTALLED
COIL 3	13962 KPA	93 C	-29 C	SV3			TO BE INSTALLED

SCANNED
NOV 05 2015

OWNER INSTRUCTIONS/REMARKS:

NOT SUBJECT TO ANNUAL FEES AS PER REGULATIONS PART 4 SECTION 28 (h)
DIRECT OR INDIRECT FIRED OIL AND GAS PROCESS HEATERS OF THE COIL TYPE;

OWNER TO VERIFY INTEGRITY OF VESSEL BY PERIODIC INSPECTION PROGRAM.

VERIFY THAT VESSEL/BOILER IS PROTECTED BY AN ACCEPTABLE ASME CODE PRESSURE RELIEF VALVE, OF ADEQUATE CAPACITY, SET AT NO MORE THAN MAXIMUM PRESSURE AUTHORIZED AND INSTALLED IN ACCORDANCE WITH THE SAFETY CODES ACT & REGULATIONS.

VESSEL/BOILER TO BE INSTALLED IN ACCORDANCE WITH THE SAFETY CODES ACT AND REGULATIONS.

Safety Codes Officer: LAKE, HAROLD

Signature: *Harold Lake*

NOTE: REQUIREMENTS OF THE SAFETY CODES ACT AND THE REGULATIONS ISSUED THEREUNDER:

The owner or person in charge shall report all accidents involving a boiler, pressure vessel or pressure piping system to the district Safety Codes Officer immediately and shall send a full report in writing to the Administrator as required by the Act. No repairs or alterations may be made unless authorized by a Safety Codes Officer.

A465654