

## PRESSURE EQUIPMENT INSPECTION INTERVAL APPROVAL

	Part 1 – Facility and	Equipment Information	
Facility / Field Name: Hilda North, Hilda South		Location: 09-33-018-02W4, 0	04-26-017-02W4
Interval assessment has	Part 2 - Ass been performed as pe	essment Type r TC-OVR-PRO-INT-000036 – e	check applicable box
Individual Equipment:			check applicable box
Provide the equipment number:			
Multiple Equipment:			
Provide the equipment numbers or re	fer to Section 4 for the	file location:	
Like Service Comparison:			
Provide the equipment numbers or re	fer to Section 4 for the	file location:	
Pa	ort 3 – Summary of Find	lings / Issues / Action Items	
UT thickness reading & calculated co Inspection intervals extended to 6 year vibrating service) using current inspe A0117669 Separator at 04-26-017-02V	ars (compressor bottle ection results.	service) and 6 years (sour) 10	9 years (sweet service non-
	Part 4 – Insp	ection Interval	
Previous Interval: New Interval: 36, 72, 120 mg	R:\Integrity\Medicine Hat\Hilda North (1920)\1060 Vessel Integrity\04 Inspection Data\2017 R:\Integrity\Medicine Hat\Hilda South (1921)\1060 Vessel Integrity\04 Inspection Data\2017		
Note: If the assigned inspection intervon the assessment Form or Spreadsh	val is not the same for	AND THE PROPERTY OF THE PROPER	I, the interval may be identified
	Part 5 – Appro	ovals / Rejection	
Final Approval: Asset Integrity Name: Kelly Matsalla	Comments: Approved month interval as not	I for inspection to 72, 120 ed in assessment sheet.	⊠ Accept
Dec 6, 2017			Reject
Cert. #: ABSA PESL #1001			Signature
Final Approval: Operations (Foreman level or above)	Comments:		Accept
Name: Justin Sullivan			Reject
Position: Foremen			Signature
Note: Excursion of the typical plant or fie Integrity review of the original insp	eld operating /production cor ection interval assessment t	ditions (temperature, pressure, equipo confirm that the assigned inspection	pment failure) requires an Asset on interval is still valid.