

15-17-82-DSW4


A2683353



VESSEL (A): 2683353  
DATE OF INSPECTION: 1997 Jul 24



# Certificate of Inspection



NORTHSTAR ENERGY CORPORATION  
ATTN: DARELL SEIB;3000, 400 - 3 AVENUE SW

CALGARY, ALBERTA  
T2P 4H2

LOCATION: SURMOUNT WEST COMPRESSOR STN. LSD: 15-17-82-8-W4M

COMPANY CODE: C-300

PREFERRED RE-INSP. INTERVAL: 4.00 Yrs

DESCRIPTION: GLYCOL CONTACTOR

CRN: K3379.2

MANUFACTURER: PRESSON MANUFACTURING LTD.

SERIAL #: 4916-20

YEAR BUILT: 1990

HEATING SURFACE: 0.0 M2

SURFACE AREA: 0.0 M2

VOLUME: 6.47 M3

### SAFETY VALVES

PART	MAX. AUTHORIZED WORKING PRESSURE	MAX. TEMP	MIN. TEMP	VALVE ID	SETTING	CAPACITY LOCATION
CON	12,411 KPA	65 C	-29 C	SW005	12,411 KPA	516 M3/MIN VESSEL

### OWNER INSTRUCTIONS/REMARKS:

OWNER TO VERIFY INTEGRITY OF VESSEL BY PERIODIC INSPECTION PROGRAM.

VERIFY THAT VESSEL IS PROTECTED BY A 'UV' SAFETY RELIEF VALVE, OF ADEQUATE CAPACITY, SET AT NO MORE THAN MAXIMUM PRESSURE AUTHORIZED, HAS BEEN INSTALLED IN ACCORDANCE WITH THE REGULATIONS.

SAFETY CODES OFFICER: LITVINCHUK, WILLIAM

SIGNATURE: 

### NOTE: REQUIREMENTS OF THE SAFETY CODES ACT AND THE REGULATIONS ISSUED THEREUNDER:

THE OWNER OR PERSON IN CHARGE SHALL REPORT ALL ACCIDENTS INVOLVING A BOILER, PRESSURE VESSEL OR PRESSURE PIPING SYSTEM TO THE DISTRICT SAFETY CODES OFFICER IMMEDIATELY AND SHALL SEND A FULL REPORT IN WRITING TO THE ADMINISTRATOR/CHIEF INSPECTOR AS REQUIRED BY THE ACT. NO REPAIRS OR ALTERATIONS MAY BE MADE UNLESS AUTHORIZED BY A SAFETY CODES OFFICER.