8764 Page 1 of 2



Inspection Report - Barrick #8764

[www.mtnwest.ca] [Company Index Page] [Vessels] [Pipelines] [SMART] [Incidents] [Work Orders] [Management of Change]

102369- FWKO

UT External

| Province: | Alberta | Manway: | Yes |
|---------------------------|----------------|-------------------------|-------------------|
| District: | STURGEON LAKE | Coating: | |
| Location: | STURLS | Inspect Date: | 2/20/2010 |
| LSD: | 10-29-071-23W5 | Inspection Interval: | 48 |
| CRN: | A9372.2 | Next Inspection: | 2/20/2014 |
| Skid/Equipment Number: | PKG54776 | MAWP: | 50 PSI 344.74 KPa |
| Service: | SOUR | Temperature: | 200 F 93.33 C |
| Status: | In Service | Outstanding NCRs: | 0 |

| Camanal | ١. |
|-----------|----|
| t -eneral | |
| | |

Safety Valves:

PSV <u>FLD2219</u> Protects the Shell Of the Vessel. Set Pressure of 50 PSI / 344.74 KPa. Capacity: 3469SCFM / 98.23m3/min

Status: In Service | Examination Methods: UT | Access: External | Cleaning:

External:

Refer to the External inspection report in this database as part of this thorough inspection.

Internal:

Hunt Inspections's Ultrasonic Corrosion Survey Project #C40290A, as reported on Drawing # 447, noted all vessel thickness readings to be above ASME Section VIII, Div. 1 code requirements at time of inspection. The calculated retirement date is 2030 with a program maximum of 20 years. Cautions were noted, calculations confirmed thickness readings to be above code at Band:447-35, 40, 43, , Nom: .375", Low: .276 ",

T-min: .2175 ". Band:447-55, 57, Nom: .375", Low: .294 ", T-min: .0424 ". Band: 447-90, Nom:

8764 Page 2 of 2

| .216", Low: .154 ", T-min: .0044 ". | |
|--|--|
| Recommendations: | |
| Next inspection is 4 years or 1/2 remaining life, whichever is less. | |

Inspector's Declaration: I have witnessed the above inspections and certify that they have been done in accordance with our manual and that the information is accurate. I certify that the status of the pressure equipment detailed here is:

| Suitable to be returned to service: Yes | Repairs complete: N/A | |
|--|-----------------------------------|--|
| Repairs are still required: No | Suggested Inspection Interval: 48 | |
| Inspector: John Bourne Cert 000193 Date: 8/24/2010 | | |

Chief Inspector: I certify that the information on this report is true and that all inspections required by the Owner/User Quality Assurance Program# AQP-9013 which expires in 12/11/2010 have been done.

| Chief Inspector: Jim Damiani Cert 00037 | |
|---|--|
| Date: 8/30/2010 | |

[Back To Start Page] [MtnWest.Ca]