FLD2097 Page 1 of 2



PSV Inventory

[www.mtnwest.ca] [Company Index Page] [Vessels] [Pipelines] [SMART] [Incidents] [Work Orders] [Management of Change]

FLD2097

Status:	Out Of Service	Back Pressure:	PSI KPa
LSD:	<u>06-11-069-21W5</u>	Inlet Size:	2 IN 50.8 MM
District/Unit:	STURGEON LAKE	Outlet Size:	2 IN 50.8 MM
Location:	STURLS	Capacity:	212 SCFM 6 m3/min
Skid/Equipment Number:	PKG55552	Inlet Block Valves:	No Locked Open?: NA
CRN:	OG1316.2C	Outlet Block Valves:	No Locked Open?: NA
Make::	TAYLOR	Process:	SOUR
Model:	8200-2MG/1X	ANSI Rating Inlet:	MNPT
Code Stamp:	UV	ANSI Rating Outlet:	FNPT
Serial Number:	13096-19	Location on Vessel:	+ 6 ' END OF FLARE KNOCK OUT TANK
Set Pressure:	15 PSI 103.42 KPa		

[Click here for extended PSV data]

List of Service Reports:

Last Inspection: 9/4/2007	Inspecting Company: IDEAL PRECISION VALVE	Condition: Good		
Service Interval: 60	Company Reference No.: FLD2097	Service: Sour		
Next Inspection: 9/4/2012	Technician Name:	Installed:		
Pre-Test: No	Pre-Test Results:			
Comments:				

Pictures and Attachments

This PSV Protects Vessels:

Vessel Number: 2531786 - FLARE KNOCKOUT - Side: Shell - Primary: Yes

FLD2097 Page 2 of 2

T		
	• 1	D a
1 🔻	•	
т л		

Material Transfer Orders:

Satellite Images Found:

[Click Here For Satellite Picture]

Record Entered: 2/16/2010 Record Last Updated: 2/16/2010

[Back To Start Page] [MtnWest.Ca]