



VESSEL (A): 0401859

DATE OF INSPECTION: 1999 Nov 19

Leland
ABSA

Certificate of Inspection

ULSTER PETROLEUMS LTD.

MISC. AREAS
ATTN: TOM PEYTON
BOX 700
WIMBORNE, AB
TOM 2G0

PREFERRED RE-INSP. INTERVAL: 4.00 Yr.

YEAR BUILT: 1999

CRN: L7755.2

SERIAL #: 6424-20

LOCATION: LELAND, LSD 1-34-58-26 W5M

DESCRIPTION: HORIZONTAL FLARE KNOCKOUT DRUM

COMPANY CODE: V-1050

MANUFACTURER: PRESSON MANUFACTURING LTD.

VOLUME: 18.179 M3

HEATING SURFACE:

SURFACE AREA:

Safety Valves

PART	MAX. AUTHORIZED WORKING PRESSURE	MAX. TEMP	MIN. TEMP	VALVE ID	SETTING	CAPACITY	LOCATION
VESSEL	345 KPA	93 C	-40 C	SV1			TO BE INSTALLED

OWNER INSTRUCTIONS/REMARKS:


VESSEL/BOILER TO BE INSTALLED IN ACCORDANCE WITH THE SAFETY CODES ACT AND REGULATIONS.

VERIFY THAT VESSEL/BOILER IS PROTECTED BY AN ACCEPTABLE ASME CODE PRESSURE RELIEF VALVE, OF ADEQUATE CAPACITY, SET AT NO MORE THAN MAXIMUM PRESSURE AUTHORIZED AND INSTALLED IN ACCORDANCE WITH THE SAFETY CODES ACT & REGULATIONS.

CONTACT THE ABSA SAFETY CODES OFFICER BEFORE PLACING THE VESSEL/BOILER IN SERVICE.

*1-34 (surf 8-34)
dry hole.
moved to Gundersen 5-3-63-H W6.*

Safety Codes Officer: JONES, AL

Signature: 

REQUIREMENTS OF THE SAFETY CODES ACT AND THE REGULATIONS ISSUED THEREUNDER:

The owner or person in charge shall report all accidents involving a boiler, pressure vessel or pressure piping system to the district Safety Codes Officer immediately and shall send a full report in writing to the Administrator as required by the Act. No repairs or alterations may be made unless authorized by a Safety Codes Officer.

A401859