



**MANUFACTURER'S DATA REPORT  
FOR INDIRECT FIRED  
HEATER COILS**

(A) No. 449231

Manufactured by PRIORITY PROJECTS LTD.

Manufactured for ANDERSON EXPLORATION LTD.

Ultimate Owner ANDERSON EXP. LTD. 1600, 324-8 AVE. S.W. CAL. ALTA. T2P-225

Location of Installation 4-10-79-5W6

Mfg. Serial No. 5215 Code: ASME B31.3, Edition 96 Addenda 1

Drawing Number 5215-301 Year Built 1998 Intended Service SWEET

a. Material Specifications A106B SMLS A105N FLG. 1500  
Coil Ends (Flanges/N.P.T.) Rating

b. Material Specifications A106B SMLS A105N FLG. 1500  
Coil Ends (Flanges/N.P.T.) Rating

a. Diameter 2.375" O.D. Nom. Thickness .343 O/A Length 146" C.A. 1/16"

b. Diameter 2.375" O.D. Nom. Thickness .343 O/A Length 146" C.A. 1/16"

a. Maximum Working Pressure 23,270 kPa at Maximum Temperature 93 °C

b. Maximum Working Pressure 23,270 kPa at Maximum Temperature 93 °C

a. Hydrostatic Test Pressure 34,906 kPa C.R.N. F-3086.231

b. Hydrostatic Test Pressure 34,906 kPa C.R.N. F-3086.231

Heating Surface 74.4 SQ. FT. Radiography 5% (Random, % or Full)

Volume 1.86 CU. FT. P.W.H.T. NONE

Remarks \_\_\_\_\_

**CERTIFICATE OF COMPLIANCE**

We certify that the statements in this report are correct and that all details of design, material, construction, and workmanship of this coil bundle are in accordance with Registered Design No. F-3086.231

Date 26-11-98 Signed [Signature] For PRIORITY PROJECTS LTD.  
(Representative) (Manufacturer)

**CERTIFICATE OF SHOP INSPECTION**

I, the undersigned, a duly authorized Safety Codes Officer employed by The Alberta Boilers Safety Association have inspected the above Heater Coils and state that, to the best of my knowledge and belief, the construction is in accordance with the Alberta Safety Codes Act and Regulations.

Date 28-11-20 Signed [Signature]