

Certificate of Inspection Permit

CANADIAN NATURAL RESOURCES LTD

855 2 STREET SW SUITE 2500

CALGARY, AB
T2P 4J8

Max. Inspection Interval: Yr.

Year Built: 2001

CRN: P3215.2

Serial #: 00-2167-6

Volume: 0.060 M3

Heating Surface: 5.76 M2

Surface Area:

COMPANY CODE: LADYFERN EAST

DESCRIPTION: INDIRECT FIRED HEATER COILS

LOCATION: LSD 10-19-94-12 W6M (LADYFERN)

MANUFACTURER: WELLS-HALL MANUFACTURING LTD

PART	MAX. ALLOWABLE PRESSURE	MAX. TEMP	MIN. TEMP	Pressure Relief Valves			
				VALVE ID	SETTING	CAPACITY	LOCATION
COIL 1	38783 KPA	94 C		SV1			BY OWNER
COIL 2	13962 KPA	94 C		SV2			BY OWNER

Terms and Conditions:


NOT SUBJECT TO ANNUAL FEES AS PER INFORMATION BULLETIN IB06-001 (h)
DIRECT OR INDIRECT FIRED OIL AND GAS PROCESS HEATERS OF THE COIL TYPE;

Owner must establish and maintain an integrity assessment program for this vessel/boiler. Refer to ABSA publication AB-506 for integrity assessment program requirements.

Owner must ensure this vessel/boiler has overpressure protection that is a relief valve that meets the requirements of the ASME Code, or other means accepted by the Administrator expressly for this item.

Owner must ensure this vessel/boiler is designed, constructed, installed, operated, maintained and decommissioned in accordance with the Safety Codes Act and Regulations.

Permit Issued by: SMITH, WAYNE

Signature: 

NOTE: REQUIREMENTS OF THE SAFETY CODES ACT AND THE REGULATIONS ISSUED THEREUNDER:

An owner or vendor must notify the Administrator in writing when the pressure equipment identified on this certificate is sold or otherwise disposed of.

The owner or person in charge shall report all accidents involving Pressure Equipment to the district Safety Codes Officer immediately and shall send a full report in writing to the Administrator as required by the Act. No repairs or alterations may be made unless authorized by a Safety Codes Officer.