

1060-04

Canadian Natural Resources Limited
Production - Facilities Engineering
A0475317 Indirect Fired Heater Coil Certificate of
Inspection

Content Date Range: 10/30/2001 to 10/30/2001

Vessel Integrity
Inspection Data

Open: 2/5/2007 Close: Vital: Yes
Original: Yes
Confidential: No

CC+2 0P P



00763525

A0475317 - HEATER COIL INSPECTION - OCT 2001

Certificate of Inspection

Terry R. McConnell
QA Coordinator

ANADARKO CANADA CORPORATION
PO BOX 2595 STN M
425-1 STREET SW
ATTN TERRY MCCONNELL
CALGARY, AB
T2P 4V4

PREFERRED RE-INSP. INTERVAL: Yr.

YEAR BUILT: 2001
CRN: K1977.12
SERIAL #: 126-96-01-C

LOCATION: CALGARY (STOCK)
DESCRIPTION: INDIRECT FIRED HEATER COILS
COMPANY CODE:
MANUFACTURER: MAR-QUINN INDUSTRIES LTD

VOLUME: 0.13 M3
HEATING SURFACE: 10.75 M2
SURFACE AREA:

Safety Valves

PART	MAX. AUTHORIZED WORKING PRESSURE	MAX. TEMP	MIN. TEMP	VALVE ID	SETTING	CAPACITY	LOCATION
COIL 1	20340 KPA	93 C		SV1			TO BE INSTALLED
COIL 2	13962 KPA	93 C		SV2			TO BE INSTALLED

OWNER INSTRUCTIONS/REMARKS:


NOT SUBJECT TO ANNUAL FEES AS PER REGULATIONS PART 4 SECTION 28 (h)
DIRECT OR INDIRECT FIRED OIL AND GAS PROCESS HEATERS OF THE COIL TYPE;

OWNER TO VERIFY INTEGRITY OF VESSEL BY PERIODIC INSPECTION PROGRAM.

VERIFY THAT VESSEL/BOILER IS PROTECTED BY AN ACCEPTABLE ASME CODE PRESSURE RELIEF VALVE, OF ADEQUATE CAPACITY, SET AT NO MORE THAN MAXIMUM PRESSURE AUTHORIZED AND INSTALLED IN ACCORDANCE WITH THE SAFETY CODES ACT & REGULATIONS.

VESSEL/BOILER TO BE INSTALLED IN ACCORDANCE WITH THE SAFETY CODES ACT AND REGULATIONS.

Safety Codes Officer: DENYS, METRO

Signature: 

REQUIREMENTS OF THE SAFETY CODES ACT AND THE REGULATIONS ISSUED THEREUNDER:

The owner or person in charge shall report all accidents involving a boiler, pressure vessel or pressure piping system to the district Safety Codes Officer immediately and shall send a full report in writing to the Administrator as required by the Act. No repairs or alterations may be made unless authorized by a Safety Codes Officer.