

## Mothballing and Rendering Safe Documentation Form TC-OVR-FM-INT-000046\_2

Equipment Description						
Jur#:		Date:	Jan 17	', 2024	• / / //	
Serial #:	VS-6713	Facility:	08-36-037-18W4 S2			
Equipment Type:	Vessel Piping Tank Other	Equipment Number:			•	
Equipment Description:	Vertical Separator	Equipment LSD/NTS:	08-36-	037-18W4 S2		
If mothballing or rendering safe multiple pieces of equipment insert "See Attached List"						
Mothballing for Temporary Suspension of Operation (<12 months)						
	1) The equipment will remain out-of-service for <u>less than 12 months</u>					
	2) Mothballing required actions will be carried out as per Section 4 of TC-OVR-PRO-INT-000021					
	3) Equipment Inspection and PRD servicing not required but maintained at given frequencies					
	4) Equipment status remains "in-service", form required in IDMS to document layup process					
Mothballing for Temporary Suspension of Operation (>12 months)						
	1) The equipment will remain out-of-service for more than 12 months					
	2) Mothballing required actions will be carried out as per Section 5 of TC-OVR-PRO-INT-000021					
	Equipment Inspection and PRD servicing is required when returned to active operation					
	4) Equipment status changed to "out of service", form is required in IDMS to track changes					
Mothballing for Surplus (To be reloacted)						
	1) The equipment will be allocated for surplus based on the Shut-In Facility Management Guideline TC-OVR-					
	XXX-XXX-XXXXX					
	Mothballing required actions w	) Mothballing required actions will be carried out as per Section 5 of TC-OVR-PRO-INT-000021				
	Equipment status changed to "mothballed", form is required in IDMS to track changes					
Rendering Safe for Decommisioning						
<b>✓</b>	1) The equipment has been selected for decommisioning as per the Shut-In Facility Management Guideline					
	TC-OVR-XXX-XXXXX					
	Rendering Safe required actions will be carried out as per Section 7 of TC-OVR-PRO-INT-000021 and the					
	Shut-In Facility Management Guideline – Site Clean-up Checklist					
	3) Equipment status changed to "out of service"					
	Comments					
Comments						
Final Sign off						
Print Name:	Jeff Sharpe	Sign	Name:	Jebra		