



Mountain West Services Ltd.

## Inspection Report - Barrick # 10152

[\[www.mtnwest.ca\]](http://www.mtnwest.ca) [\[Company Index Page\]](#) [\[Vessels\]](#) [\[Pipelines\]](#) [\[SMART\]](#) [\[Incidents\]](#) [\[Work Orders\]](#) [\[Management of Change\]](#)

### 549033- STABILIZER COOLER

#### VT External

<b>Province:</b>	Alberta	<b>Manway:</b>	NO
<b>District:</b>	PPLT	<b>Coating:</b>	No
<b>Location:</b>	PUSKWA PLANT	<b>Inspect Date:</b>	4/30/2012
<b>LSD:</b>	03-03-072-26W5	<b>Inspection Interval:</b>	60
<b>CRN:</b>	T4527.2	<b>Next Inspection:</b>	4/30/2017
<b>Skid/Equipment Number:</b>	PKG54488	<b>MAWP:</b>	350 PSI 2413.18 KPa
<b>Service:</b>		<b>Temperature:</b>	400 F 204.44 C
<b>Status:</b>	Spare	<b>Outstanding NCRs:</b>	0

#### General:

Vessel was inspected psv should be serviced prior to returning to service

#### Safety Valves:

PSV NON-CODE Protects the Tube Of the Vessel. Set Pressure of 5 PSI / 34.474 KPa. Capacity: SCFM / m3/min

<b>Status:</b> Spare	<b>Examination Methods:</b> VT	<b>Access:</b> External	<b>Cleaning:</b>
----------------------	--------------------------------	-------------------------	------------------

#### External:

All visible shell surfaces and nozzles appear in good condition. Name plate is intact and legible. Vessel supports, foundation, and external coating appear good. Confirm electrical bonding and equipment grounding. Associated piping supports and components appear in good condition and alignment with no signs of leaks or defects present at the time of inspection. Verify PSV protection and PSV's are properly installed with any block valves locked/sealed open. Verify vessel has Alberta CRN and A# stamping or Unique Identifier, PSV has correct set pressure and MWS tagging, and was last serviced within the required interval guidelines. Assign inspection interval.

#### Internal:

<b>Recommendations:</b>

<b>Inspector's Declaration:</b> I have witnessed the above inspections and certify that they have been done in accordance with our manual and that the information is accurate. I certify that the status of the pressure equipment detailed here is:	
<b>Suitable to be returned to service:</b> Yes	<b>Repairs complete:</b> N/A
<b>Repairs are still required:</b> No	<b>Suggested Inspection Interval:</b> 60
<b>Inspector:</b> Jay Bourne, MWS <b>Date:</b> 5/20/2012	
<b>Chief Inspector:</b> I certify that the information on this report is true and that all inspections required by the Owner/User Quality Assurance Program# AQP-9013 which expires in 12/11/2013 have been done.	
<b>Chief Inspector:</b> Jim Damiani Cert 00037 <b>Date:</b> 7/19/2012	

[\[Back To Start Page\]](#)   [\[MtnWest.Ca\]](#)