GARTON INSPECTIONS
Box 135
Lampman, SK
SOC 1N0
tel: (639)488-7746
office: (306)487-7746
email: gartoninspections@yahoo.com

M0057

May 7/2018

18-5-CPE-57

MOTOR INFORMATION

MAKE: Arrow
SIZE: C106
SERIAL #:
IGNITION: MAGNETO / (STARFIRE)
SPARKPLUG: Champion D89D
ELECTRIC START: (YES) / NO
COMMENTS: - cables missing for electric start
- needs starter switch

CARBURATOR INFORMATION

TYPE: Impco 210
DIAPHRAM: good
AIR VALVE: good
THROTTLE BODY: good
BUTTERFLY: good
AIR CLEANER: good
COMMENTS:

RADIATOR

CONDITION: good
FAN: good
FAN BELT: good
FAN BELT TENSION: good
ANTIFREEZE: good
ANTIFREEZE LEVEL: good
WATER MURPHY: good
RAD CAP: good
COMMENTS:

CLUTCH

CLUTCH PLATES: light wear
BEARINGS: good
ADJUSTMENT: good
SHAFT: good
GREASED: (YES) / NO
COMMENTS:

OIL

LEVEL: low
CONDITION: needs changing

OIL LINES

COPPER or (STEEL BRAIDED)
OIL PRESSURE GAUGE: good
CONDITION:

COMMENTS: - need to replace oil collector flange (one ear broke off)
- needs oil sight glass, 90° elbow for oil collector flange

CYLINDER HEAD

INLET VALVE: good
EXHAUST VALVE: good
VALVE CLEARANCE: good
VALVE COVER BREATHER: good
EXHAUST: muffler
COMMENTS:

TERMS AND CONDITIONS: YOU ARE ASSUMING ALL RISK OF INJURY,LOSS OR DAMAGE WITH RESPECT TO THE INSPECTION. Please be advised that Garton Inspections does not warranty inspections as all inspections are visual and a matter of opinion. Garton Inspections does not assume any liability for any damage to property or personal injury resulting from the inspection or use of the inspected equipment.