



Leak Technologies Solutions Ltd.

BOX 71119 - 8060 SILVER SPRINGS BLVD. NW
CALGARY, AB T3B 5K2

1-866-565-2611

Aboveground Storage Tank Leak Test Report

Test Date: June 27th 2016
Next Test Date: June 27th 2021

Canadian Natural Resources Ltd
17 7471 Edgar Industrial Bend
Red Deer, Alberta T4P 3Z5

Attention: Kevin Cartwright

As requested **Leak Technologies Solutions Ltd** performed a leak test to the aboveground controlled product liquid transfer system located at:


SEDALIA GAS PLANT
5-26-30-4W4

Vessel Description	Volume	Height	Ullage Test	Leak Test	Line Test
792223 PRODUCED WATER	100 BBL	8'	N/A	Pass	N/A

The product line for this tank was isolated at the tank with the valve installed at the tank. This tank had 36" of liquid level at the time of testing. This tank can be placed back into its current service.

Technician: Joe Pimm

This report was reviewed by _____


Pat White
Certification #: AL/TX 060

"Precision Testing and Inspection Specialists"



Leak Technologies Solutions Ltd.

BOX 71119 - 8060 SILVER SPRINGS BLVD. NW
CALGARY, AB T3B 5K2

1-866-565-2611

Aboveground Storage Tank
Visual Inspection Report

Test Date: June 27th 2016
Next Test Date: June 27th 2021

Canadian Natural Resources Ltd
17 7471 Edgar Industrial Bend
Red Deer, Alberta T4P 3Z5

Attention: Kevin Cartwright

SEDALIA GAS PLANT
5-26-30-4W4

Tank #1

ID..... 792223 PRODUCED WATER
Built by..... BIRD OIL EQUIPMENT LTD.
Year Built..... 1977
Serial #..... 7704-A
Capacity..... 100 BBL
Height..... 8'
Roof Thickness..... 1/4
Shell Thickness..... 1/4
Floor Thickness..... 1/4

This tank is sitting flat on the ground.

At the time of inspection there were no visible defects or leaks observed. Tank and insulation are in good condition. The berm around the lease site meets the D-55 guidelines for 110% containment.

This tank can be placed back into its current service.

Technician: Joe Pimm

This report was reviewed by _____

Pat White
Certification #: AL/TX 060