

Mountain West Services Ltd.

Box 7, Site 12, RR#1 DeWinton, AB T0L 0X0

Field Inspection Report - CNRL# 10756

Vessel Number	3121678	Vessel Name	INLET SEPARATOR	Province	Alberta
District	GPOU	LSD	10-08-083-09W6	Location	JOSEPHINE FIELD
Method	VT	Access	External	Cleaning	Good
Inspection Date	5/19/2010	Inspection Interval	60	Next Inspection	5/19/2015
CRN	M-9691.2	Skid Number	SKID0494	Service	Sweet
Manway	NO	Coating	False	Status	In Service
MAWP (PSI)	735	MAWP (Kpa)	5067.68		
MAWT (F)	37.78	MAWT (C)	100	Outstanding NCRS	0

General

Safety Valves

PSV MWS65365 Shell side. Set pressure 735 PSI / 1507 KPa. Capacity: 1507 SCFM / 42.67 m3/min.

External


All visible shell surfaces and nozzles appear in good condition. Name plate is intact and legible. Vessel supports, foundation, electrical bonding and external coating appear good. Associated piping, supports and components appear in good condition and alignment with no signs of leaks or defects present at the time of inspection. No evidence of short studding or nut rounding at time of inspection.

Verify PSV protection and PSV's are properly installed with any block valves locked/sealed open. Verify vessel has CRN and A# stamping, PSV has correct code stamp and MWS tagging, and was last serviced within the required interval guidelines.

Assign inspection interval.

Internal

Recommendations

INSPECTOR : I have witnessed/done the above inspections and certify that they have been done in accordance with our approved manual and that the information is accurate. I certify that the status of the Pressure equipment detailed here is:			
Suitable to be returned to Service	Yes	Repairs complete (AB-40 attached)	N/A
Repairs are still required	No	Suggested Inspection interval	60
Glenn Allen, CERT#000380 Inspector			5/19/2010 Date