

**Return to:**

**Canadian Natural Resources Ltd. – Integrity Group (Anthony Merle)**

Suite 2500, 855 – 2<sup>nd</sup> Street SW, Calgary, AB T2P 4J8

Phone: (403) 517-7301 Fax: (403) 517-7366

anthony.merle@cnrl.com

**Pressure Equipment Field Inspection Report**

<b>CNRL Business District</b> (e.g. NE Gas, St. Albert, Bonnyville, Edson)	GP North		<b>Date of Insp.</b>	Nov 30/11	
<b>Prov. Reg.#</b> (e.g. A#, RAE#, C#)	A 3121678		<b>Location</b> (Field Name)	Josephine #1712	
<b>Equipment Type</b> (e.g. treater, separator, scrubber)	inlet separator		<b>LSD</b>	10-8-83-9 W6	
<b>Tag/Equip. #</b> (e.g. V-101)	V-101		<b>Comp./Unit #</b> (e.g. 1408)		
<b>Vessel Status:</b>	In Operation	<u>Not In Operation</u>	<b>Job #</b>		
<b>Fabricator</b>	Opso '97	<b>Serial #</b>	V-2285	<b>MAWP/Temp</b>	735psi / 100 °F
<b>CRN#</b>	M9691.2	<b>Shell Mat'l</b>		<b>Shell Thick.</b>	
<b>Corr. All.</b>	0.0625"	<b>Head Mat'l</b>		<b>Head Thick.</b>	
<b>Diameter</b>		<b>Length</b>	<b>Height</b>	<b>RT</b>	<b>HT</b>
<b>Year Built</b>	1995	<b>Next Insp.</b>		<b>Insp. Type</b>	
<b>Service</b>	sweet	<b>Manway</b>	Yes	<b>Coating</b>	
<b>PSV #.</b>					
<b>Mfg.</b>		<b>Serial #</b>		<b>Set Pressure</b>	
<b>Type/Model</b>		<b>Capacity</b>		<b>Size</b>	
<b>Date of Service</b>		<b>Next Service</b>		<b>Service Co.</b>	

Report #

**Observations (attach additional pages if needed):**

for inventory.

**Recommendations:**

currently out of service.

**Inspector:**

Craig Liba

**Reviewed By:**

**Contact Number:**

(780) 831-7497

AB-40 to be attached