Ар	pendix 1: Mothballin		ntation Form
	Vessel D	escription	7
A#, NB# or C#:	A 496381	Date:	OCT 5/15 BERLAND
Serial #:	PE 7964	Facility:	CAS PLANT
Vessel Description	HORIZONTAL SEPARATOR	Vessel LSD:	16-15-59-24 W5
	one box that applies to this ves	sels situation:	
3) It is does i	not want to inspect the vessel after	r (ABSA) that this v r it is mothballed.	essel is out-of-service. Operations
2) Op	s vessel is currently not being use erations is unsure when it will be p s vessel will be inspected at on its ator of any changes.	out back into service	
NOTES/COMMEN	ITS.		
	Final	Sign-Off	
Print Name:	BYRON WEBB	Sign Name:	ByKIKI