8144 Page 1 of 2



## **Inspection Report - CNRL2 #8144**

[www.mtnwest.ca] [Company Index Page] [Vessels] [Pipelines] [SMART] [Incidents] [Work Orders] [Management of Change]

## **218748- GROUP SEPARATOR**

## VT External

<b>Province:</b>	Alberta	Manway:	Yes
District:	INVENTORY	Coating:	No
<b>Location:</b>	STURLS	<b>Inspect Date:</b>	1/24/2010
LSD:	14-24-068-22W5	Inspection Interval:	60
CRN:	F5445.2	Next Inspection:	1/24/2015
Skid/Equipment Number:	N/A	MAWP:	707 PSI 4874.6236 KPa
Service:	Sour	Temperature:	150 F 65.56 C
Status:	Spare	Outstanding NCRs:	0

General:			
Safety Valves:			
PSV <u>FLD2113</u> 5732SCFM / 154	Protects the Shell Of the Vessel. Sem3/hr	et Pressure of 700 PSI / 4	826 KPa. Capacity:
Status: Spare	Examination Methods: VT	Access: External	Cleaning: Good
	ll visible shell surfaces and nozzle		
Internal:			
Recommendatio	ons:		

The vessel is currently out of service and requires a thorough inspection prior to going back into

8144 Page 2 of 2

service.			1

**Inspector's Declaration:** I have witnessed the above inspections and certify that they have been done in accordance with our manual and that the information is accurate. I certify that the status of the pressure equipment detailed here is:

pressure equipment detailed here is:				
Suitable to be returned to service: Yes	Repairs complete: N/A			
Repairs are still required: No	Suggested Inspection Interval: 60			
<b>Inspector:</b> Leo Nedelec, MWS <b>Date:</b> 1/24/2010				
<b>Chief Inspector:</b> I certify that the information on this report is true and that all inspections required by the Owner/User Quality Assurance Program# AQP-9013 which expires in 12/11/2010 have been done.				
Chief Inspector: Jim Damiani Cert 00037 Date: 1/27/2010				

[Back To Start Page] [MtnWest.Ca]