



Mountain West Services Ltd.

## Inspection Report - CNRL2 # 8226

[\[www.mtnwest.ca\]](http://www.mtnwest.ca) [\[Company Index Page\]](#) [\[Vessels\]](#) [\[Pipelines\]](#) [\[SMART\]](#) [\[Incidents\]](#) [\[Work Orders\]](#) [\[Management of Change\]](#)

### 218747- JET PUMP SEPARATOR

#### VT External

<b>Province:</b>	Alberta	<b>Manway:</b>	Yes
<b>District:</b>	INVENTORY	<b>Coating:</b>	
<b>Location:</b>	STURLS	<b>Inspect Date:</b>	1/26/2010
<b>LSD:</b>	14-24-068-22W5	<b>Inspection Interval:</b>	60
<b>CRN:</b>	E5445.2	<b>Next Inspection:</b>	1/26/2015
<b>Skid/Equipment Number:</b>	N/A	<b>MAWP:</b>	707 PSI 4874.6236 KPa
<b>Service:</b>	Sour	<b>Temperature:</b>	150 F 65.56 C
<b>Status:</b>	Out Of Service	<b>Outstanding NCRs:</b>	0

#### General:

#### Safety Valves:

PSV NON-CODE Protects the Shell Of the Vessel. Set Pressure of PSI / KPa. Capacity: SCFM / m3/hr

<b>Status:</b> Out Of Service	<b>Examination Methods:</b> VT	<b>Access:</b> External	<b>Cleaning:</b> Good
-------------------------------	--------------------------------	-------------------------	-----------------------

#### External:

All visible shell surfaces and nozzles appear in good condition. Name plate is intact and legible. Vessel supports and external coating appear good. Assign inspection interval.

#### Internal:

#### Recommendations:

The vessel is currently out of service and requires a thorough inspection prior to going back into

service.

**Inspector's Declaration:** I have witnessed the above inspections and certify that they have been done in accordance with our manual and that the information is accurate. I certify that the status of the pressure equipment detailed here is:

**Suitable to be returned to service:** Yes

**Repairs complete:** N/A

**Repairs are still required:** No

**Suggested Inspection Interval:** 60

**Inspector:** Leo Nedelec, MWS **Date:** 2/6/2010

**Chief Inspector:** I certify that the information on this report is true and that all inspections required by the Owner/User Quality Assurance Program# AQP-9013 which expires in 12/11/2010 have been done.

**Chief Inspector:** Jim Damiani Cert 00037

**Date:** 2/27/2010

[\[Back To Start Page\]](#) [\[MtnWest.Ca\]](#)