



Mountain West Services Ltd.

Inspection Report - CNRL2 # 8143

[\[www.mtnwest.ca\]](http://www.mtnwest.ca) [\[Company Index Page\]](#) [\[Vessels\]](#) [\[Pipelines\]](#) [\[SMART\]](#) [\[Incidents\]](#) [\[Work Orders\]](#) [\[Management of Change\]](#)

2785626- TEST SEPARATOR

VT External

Province:	Alberta	Manway:	No
District:	INVENTORY	Coating:	
Location:	STURLS	Inspect Date:	1/24/2010
LSD:	14-24-068-22W5	Inspection Interval:	60
CRN:		Next Inspection:	1/24/2015
Skid/Equipment Number:	N/A	MAWP:	500 PSI 3447.4 KPa
Service:	Sour	Temperature:	F C
Status:	Spare	Outstanding NCRs:	0

General:

Safety Valves:

PSV [NON-CODE](#) Protects the Shell Of the Vessel. Set Pressure of PSI / KPa. Capacity: SCFM / m3/hr

Status: Spare	Examination Methods: VT	Access: External	Cleaning: Good
----------------------	--------------------------------	-------------------------	-----------------------

External:

Out of service. All visible shell surfaces and nozzles appear in ok condition. Name plate is intact and legible. Verify vessel has Alberta CRN and A# stamping. Assign inspection interval

Internal:

Recommendations:

The vessel is currently out of service and requires a thorough inspection prior to going back into

service.

Inspector's Declaration: I have witnessed the above inspections and certify that they have been done in accordance with our manual and that the information is accurate. I certify that the status of the pressure equipment detailed here is:

Suitable to be returned to service: Yes

Repairs complete: N/A

Repairs are still required: No

Suggested Inspection Interval: 60

Inspector: Leo Nedelec, MWS **Date:** 1/24/2010

Chief Inspector: I certify that the information on this report is true and that all inspections required by the Owner/User Quality Assurance Program# AQP-9013 which expires in 12/11/2010 have been done.

Chief Inspector: Jim Damiani Cert 00037

Date: 1/27/2010

[\[Back To Start Page\]](#) [\[MtnWest.Ca\]](#)