

Mountain West Services Ltd.

Box 7, Site 12, RR#1 DeWinton, AB T0L 0X0

Field Inspection Report - CNRL# 10767

Vessel Number	120295	Vessel Name	INLET SEPARATOR	Province	Alberta
District	GPOU	LSD	09-01-083-10W6	Location	JOSEPHINE PLANT
Method	VT	Access	External	Cleaning	Good
Inspection Date	5/19/2010	Inspection Interval	60	Next Inspection	5/19/2015
CRN	C9740.2	Skid Number	SKID0550	Service	Sweet
Manway	NO	Coating	False	Status	In Service
MAWP (PSI)	1420	MAWP (Kpa)	9790.62		
MAWT (F)	65.56	MAWT (C)	150	Outstanding NCRS	0

General

Safety Valves

PSV MWS65319 Shell side. Set pressure 1420 PSI / 22476 KPa. Capacity: 22476 SCFM / 636.45 m3/min.

External


All visible shell surfaces and nozzles appear in good condition. Name plate is intact and legible. Vessel supports, foundation, electrical bonding and external coating appear good. Associated piping, supports and components appear in good condition and alignment with no signs of leaks or defects present at the time of inspection. No evidence of short studding or nut rounding at time of inspection.

Verify PSV protection and PSV's are properly installed with any block valves locked/sealed open. Verify vessel has CRN and A# stamping, PSV has correct code stamp and MWS tagging, and was last serviced within the required interval guidelines.

Assign inspection interval.

Internal

Recommendations

<p>INSPECTOR : I have witnessed/done the above inspections and certify that they have been done in accordance with our approved manual and that the information is accurate. I certify that the status of the Pressure equipment detailed here is:</p>			
<p>Suitable to be returned to Service</p>	<p>Yes</p>	<p>Repairs complete (AB-40 attached)</p>	<p>N/A</p>
<p>Repairs are still required</p>	<p>No</p>	<p>Suggested Inspection interval</p>	<p>60</p>
<p>Glenn Allen, CERT#000380 Inspector</p>			<p>5/19/2010 Date</p>