

Equipment Photographs:

Figure 1_Nameplate_13May09

Figure 2_Inlet Separator_13May09

Figure 3_Paint Deteriorating_13May09

Figure 4_Mild Active Corrosion_13May09



Equipment Photographs:



Figure 5_Insulation Damage to Drain Piping_13May09

5311 – 86 Street, Edmonton, Alberta T6E 5T8 Phone: (780) 437-2022 Fax: (780) 438-1436

Calgary (403) 279-6121
 Lloydminster (780) 875-6455
 Barhead (780) 674-3018
 Nisku (780) 955-7616

Cold Lake (780) 594-1114
 Fort McMurray (780) 743-1536
 High Level (780) 956-4094
 Red Deer (403) 347-1742
 Medicine Hat (403) 527-6284

Corpus Christi, TX (361) 888-4700
 Deer Park, TX (281) 476-4444
 Matrix, Houston, TX (713) 722-7177
 Texas City, TX (490) 945-2262
 Tulsa, OK (918) 446-8773