



PRV INSPECTION AND TEST REPORT

BRANCH: Fort St John

UVL ID#: 19246F

Work Order: 307697

Customer PO#:

Customer: CANADIAN NATURAL RESOURCES LIMITED
Facility: MILLIGAN
A#: N/A
Cust. Ref.:
Cust. WO#:

LSD: d-031-G/94-H-02
Vessel SN:
Valve PO:
Cust AFE#:

Date: 10/11/2011
PSV Location:
Cust Id:
PO LINE#:
Cost Centre#: 35000295

VALVE DATA

Man.: FARRIS Model: 26JA13/SP Serial: 425527-1-A10 Seat: POP
Conn. Flanged Inlet: 2.5" 600 RF Orifice: J Outlet: 4" 150RF
Set Press. 1440 PSI Back Press.: 0 PSI Cold/Diff Set Press: Temp: Cap: 36000 SCFM
Lift Lever Cap Assembly: Closed Code Symbol: UV CRN#: 0G2369.5C

CUSTOMER INSTRUCTIONS

Instructions: Put in Customer Inventory Pretest Required? [checked] Reset Required? []
Replaces UVL ID#: Replaces Valve Serial#: Replaces Valve Cust ID#
RESET INFO: New Pressure: New Cold/Diff Set: New Capacity: New Model:

CONDITION AS RECEIVED

Visual Condition: Good Data Plate Condition: OK Date of last service: N/A
Seal Condition: Top: Intact Bottom: Intact Insignia: PPE Fittings Attached: Inlet: [] Outlet: []
Inlet: Clean Inlet Plugged: [] Outlet: Clean Outlet Plugged: [] Initial Insp. Signoff: Tara Stones

PRETEST 1

Simmer: 1478 PSI Set Press: 1479 PSI Reseat: 1373 PSI Leakage: 30+ BPM Test Gauge: FSJ 1+2
Tested By: Harley Anderson Pretest Comments:

PRETEST 2

Simmer: PSI Set Press: PSI Reseat: PSI Leakage: BPM Test Gauge:
Tested By: Pretest Comments:

COMPONENTS INSPECTION

Table with columns: ITEM, CLEAN, OILY, RUSTY, CARBON, OTHER, COMMENTS, OK / REPLACED, REPLACED?, REPAIRS PERFORMED. Rows include DISC, NOZZLE, CAP-LEVER ASSY, COMP SCREW and LOCKNUT, SPRING and BUTTONS, SPINDLE / STEM, STEM RETAINER, DISC HOLDER, GUIDE / UPPER RING, LOWER RING, RING PIN(S), BELLOWS, GASKET / SEALS, CONNECTION ENDS, OTHER.

DISC: : ACT - NOZZLE: MIN - ACT - NUMBER:

Comments:
Disassembly: Inspection: Reassembly:

FINAL TEST

Test Medium: Simmer: Set Pressure:
Reseat: Leakage: B.P. Test: Cold/Diff Set:
ADJ. RING SETTING (NOTCHES): Upper: Lower: Test Gauge: Set Press Def: POP
Tested by:

FINAL INSPECTION:

SEAL: Top: [] Bottom: [] End Protectors Installed: [] Painted: [] Palletized: [] Ship Container: [] Flex Gaskets Supplied: []
Final Inspection: Customer Inspection:
Comments: