

## **Inspection Report - CNRL2 # 6299**

[www.mtnwest.ca] [Company Index Page] [Vessels] [Pipelines] [SMART] [Incidents] [Work Orders] [Management of Change]

## **80683- #2 ELECTRIC DE-SALTER**

## **UT** External

Province:	Alberta	Manway:	Yes
District:	STURGEON LAKE	<b>Coating:</b>	No
Location:	STURLS GAS PLANT	Inspect Date:	5/1/2003
LSD:	02-02-069-22W5	Inspection Interval:	48
CRN:	B-8744.2	Next Inspection:	5/1/2007
Skid/Equipment Number:	V20-137	MAWP:	300 PSI 2068.44 KPa
Service:	Sour	Temperature:	250 F 121.11 C
Status:	In Service	Outstanding NCRs:	0

General:					
Safety Valves:					
PSV <u>POU2383</u> Protec 369GPM / 84m3/hr	cts the Shell Of the Vessel. Set P	ressure of 300 PSI / 2068	KPa. Capacity:		
Status: In Service	Examination Methods: UT	Access: External	Cleaning:		
External:		-			
Internal:					
	/ICES UT SURVEY AS NOTEI RE ABOVE CODE REQUIREM	<i>,</i>			
Recommendations:					

**Inspector's Declaration:** I have witnessed the above inspections and certify that they have been done in accordance with our manual and that the information is accurate. I certify that the status of the pressure equipment detailed here is:

Suitable to be returned to service: Yes	Repairs complete: N/A		
Repairs are still required: No	Suggested Inspection Interval: 48		
<b>Inspector:</b> John Bourne MWS <b>Date:</b> 11/23/2003			
<b>Chief Inspector:</b> I certify that the information on this report is true and that all inspections required by the Owner/User Quality Assurance Program# which expires in have been done.			
Chief Inspector: Jim Damiani Date: 11/30/2003			

[Back To Start Page] [MtnWest.Ca]