OWA Canadian Coyote Abandonments
Master Material Transfer Summary

Job Order #	Item #	Quantity	Transfer From	Transfer To	Date of Transfer	Description	Serial #	Condition	NOTES
601320	1	1	FA/14-15-011-05W4/00	Heavy Metal Demolition	July 26 2018	400 BBL Tank, Jensen Welding, Built 2005	100359	D	Skidded tank
601320	2	1	FA/14-15-011-05W4/00	Heavy Metal Demolition	July 26 2018	400 BBL Tank	No S/N	D	No ID Tag, Skidded tank
601320	3	1	FA/14-15-011-05W4/00	Heavy Metal Demolition	July 26 2018	400 BBL Tank, Bromley Mechanical, Built 2007	207-S400-10326	D	Skidded tank
601320	4	1	FA/14-15-011-05W4/00	Heavy Metal Demolition	July 26 2018	Bromley Vertical Sep Pkg, Built 2006	524557	D	Not in great shape, A#545658
601320	5	1	FA/14-15-011-05W4/00	Heavy Metal Demolition	July 26 2018	Petro Field Vertical Sep PKG, Built 1989	98036-13	JK	Not in great shape
601320	6	1	FA/14-15-011-05W4/00	Heavy Metal Demolition	July 26 2018	BS&B Vertical Sep PKG, Built 1978	78078-001	JK	Not in great shape, A#146127
601320	7	1	FA/14-15-011-05W4/00	Heavy Metal Demolition	July 26 2018	H2O Pump & Building, Gardner Denver Tri Plex		JK	Older pump
601320	8	1	FA/14-15-011-05W4/00	Heavy Metal Demolition	July 26 2018	H2O PC Pump & Building, Vortex V6 driver		D	V6 Engine may have value, pump junk
602385	9	1	00/08-07-011-12W4/00	Heavy Metal Demolition	July 26 2018	IPS Manufacturing Combo Sep PKG with H2O / Methanol Tanks,Built 2005	3837-00	C	A#3536189
602385	10	1	00/08-07-011-12W4/00	Heavy Metal Demolition	July 26 2018	Poly pipe spool and small QTY of 3" poly pipe		JK	Poly has been exposed to sun
603523	11	1	FA/06-04-013-14W4/00	Heavy Metal Demolition	July 31 2018	Platinum Separator PKG, Built 2000, MAWP 740#s, 30" x 10' Vertical Sep	V-189-001	C	A#461438
603523	12	1	FA/06-04-013-14W4/00	Heavy Metal Demolition	July 31 2018	50 BBL Flare Knock Out Drum, Manf - R. Pollitt, 72", Internal coated, MAWP 14.9 PSI	No S/N	C	Good shape, no fluid inside
603523	13	1	FA/06-04-013-14W4/00	Heavy Metal Demolition	July 31 2018	Tornado 40ft Flare Stack, arrestor & ignitor	No S/N	C	Good shape
603523	14	2	FA/06-04-013-14W4/00	Heavy Metal Demolition	July 31 2018	Stairs for tank farm berms	No S/N	C	Good shape
603523	15	2	FA/06-04-013-14W4/00	Heavy Metal Demolition	July 31 2018	Jts of yellow jacket line pipe	No S/N	JK	YJ is cracked/weathered