

VISUAL INSPECTION REPORT

District:	SOUTHERN/ALBERTA	Facility:	DRUMHELLER	Location/LSD:	04-01-028-18W4
Equipment Name	REBOILER			Prov Reg No. :	
Serial No.:		Equip No.:	4787	National Board No.:	

EXTERNAL INSPECTION

INSPECTION DATE:	Mar 17, 2011	INSPECTION INTERVAL	60	NEXT INSPECTION DATE:	Mar 17, 2016
ITEM	CONDITION	INSPECTION COMMENTS			
INSULATION	ACCEPT	IN GOOD CONDITION.			
EXTERNAL CONDITION	ACCEPT	IN GOOD CONDITION.			
LEAKAGE	ACCEPT	NO LEAKS FOUND.			
SKIRT/SADDLE	ACCEPT	IN GOOD CONDITION.			
ANCHOR BOLTS	ACCEPT	SECURE.			
CONCRETE FOUNDATION	N/A				
LADDER/PLATFORM	N/A				
NOZZLE	ACCEPT	IN GOOD CONDITION.			
GAUGES	ACCEPT	EASY TO READ. NO DAMAGE.			
EXTERNAL PIPING	ACCEPT	IN GOOD CONDITION.			
VALVING	ACCEPT	TIGHT/NO LEAKS.			
PSV	N/A				
NDE METHODS	ACCEPT	UT/VT.			
OTHER	N/A				

RECOMMENDATIONS:

FIT FOR SERVICE.

I have performed the above inspections and certify that they have been done in accordance with our approved manual and that the information is accurate.

Inspector:	Arron Hodgson	Signature:		Date:	Mar 17, 2011
------------	---------------	------------	--	-------	--------------

REPORT SIGN-OFF

Where required , the above reports has been reviewed and accepted as noted below:

WQS Supervisor Name:					
WQS Supervisor Title/Cert No.:				Cert No.:	
WQS Supervisor Signature/Date:				Date:	

Where required , the above reports has been reviewed and accepted as noted below:

Client Supervisor Name:					
Client Supervisor Title/Cert No.:					
Client/Supervisor Signature/Date:				Date:	