

## **PRV INSPECTION AND TEST REPORT**

BRANCH: Fort St John Work Order: 308562 UVL ID#: 1231F Customer PO#:

Customer: CANADIAN NATURAL RES	SOURCES LIMITED	Date	e: 8/8/2012			
Facility: CARIBOU	LSD: d-062-C/94-A	-16 PSV Location	n: 1ST STAGE DISCHARGE			
<b>A#:</b> 3098592	Vessel SN: 98	5-7977.9	Cust Id:			
Cust. Ref.: BLUE TAG-1231F	Valve PO:		PO Line#:			
Cust WO#:	Cust AFE#:		Cost Centre #: 30595000			
VALVE DATA						
Man.: MERCER	Model: 95-28F1107NS	Serial: 74970	Seat: Soft			
Conn: Flanged	Inlet: 1 " 300RF		2 " 150RF			
Ū	ck Press: 0 PSI	Cold/Diff Set: PSI	<b>Temp:</b> 70F <b>Cap:</b> 4352 SCFM			
	ssembly: Closed		<b>Symbol:</b> UV <b>CRN#:</b> 0G2606.5C			
· · · · ·	-	OMER INSTRUCTIONS	•			
Instructions: Pretest, Service, and			Pretest Required? 🗹 Reset Required?			
Replaces UVL ID#:		es Serial #:	Replaces Cust ID#:			
RESET INFO: New Pressure:	New Cold/Diff:	New Capacity:	New Model:			
	COND	TION AS RECEIVED				
Visual Condition: Fair	Data Plate Conditi		Date of last service: 12/08			
Seal Condition: Top: Intact	Bottom: Intact	Insignia: UVL	Fittings Attached: Inlet: Outet:			
Inlet: Carbon Inlet Plugge	ed: Outlet: Carbon	Outlet Plugged:	nitial Insp. Signoff: Tara Stones			
		PRETEST 1				
Simmer: 649 PSI Set Press:	655 PSI Reseat:	607 PSI Leakage:	AUDIABLE Test gauge: FSJ 1&2			
Tested by: Brian Gunson	Pretest comments:	_				
		PRETEST 2				
Simmer: PSI Set Press:	PSI Reseat:	PSI Leakage:	Test gauge:			
Tested by:	Pretest comments:					
			ок /			
ITEM	CLEAN OILY RUSTY CARBO	N OTHER COMMENTS	REPLACE REPLACED? REPAIRS PERFORMED			
MAIN VALVE COMPONENTS INSPECT						
BODY						
BONNET			ОК			
PISTON			ок 🗌			
PISTON SLEEVE			ок 🗌			
SOFT GOODS KIT MAIN		Vorn	REPLACE 🗹 95-2f71A			
TUBING			ок 🗌			
DISC			ок 🗌			
NOZZLE			ок 🗌			
SPRING and BUTTONS		$\square$	ok 🗌			
CONNECTION ENDS			OK 🗌			
PILOT VALVE COMPONENTS INSPEC						
BODY			ок Ц			
CAP			ОК			
ADJUSTING SCREW			ок 🗌			
PILOT SPRING			ок 🗌			
DISC		Dented	REPLACE 🗹 95-SCON			
NOZZLE		Dented	REPLACE 🗹 95-SCON			
VENT			ОК			
BLOWDOWN ASSY		Dented	REPLACE 🗹 95-SCON			
PISTON		Dented	REPLACE <b>V</b> 95-SCON			
GUIDE			OK			
SOFT GOODS KIT PILOT		Vorn	REPLACE 🗹 95-SCON			
OTHER						
OTHER						
OTHER						
Disc: MIN= ACT=	Nozzle:	ACT=	Spring Number:			
Comments:						
Disassembly: Brian Gunson	Inspection:	Brian Gunson	Reassembly: Brian Gunson			



## **PRV INSPECTION AND TEST REPORT**

BRANCH: Fort St John

UVL ID#: 1231F

	VALVL	Work Order: 308562	Customer PO#:			
FINAL TEST:						
Test Medium:	Air Simm	er: 799 PSI Set Pressure:	800 PSI			
Reseat:	744 PSI	Leakage Acceptable: J B.P. Test:	60 PSI			
ADJ. RING SETT	NG (NOTCHES): Upper: N/A	Lower: N/A Test Gauge FSJ 1&2	Set Press Def: POP			
Tested by:	Harley Anderson					
FINAL INSPECTION:						
SEAL:	Top: 🖌 Bottom: 🖌 End Pro	tectors Installed: 🖌 Painted: 🖌 Palletized:	Ship Container: Flex Gaskets Supplied: 🗸			
Final Inspection:	Tara Stones	Customer Inspection				

Comments:

REVISION 3 5-24-08 QF-056